The City of Waxahachie Waxahachie Historic Resources Survey Update Final Report August 2004

Prepared by:



HHM Inc. Austin, Texas

The City of Waxahachie Waxahachie Historic Resources Survey Update Final Report August 2004

Prepared by:

HHM Inc.

Austin, Texas

TABLE OF CONTENTS

TABLE OF CONTENTS

Table of Contents
Introduction1
Research Methods
Historical Research
Legal Research
Preliminary Investigations5
Field Investigations5
Fieldwork Results7
Data Analysis7
Criteria for Evaluation7
Surveyed Post-World War II Neighborhoods11
Almond Street (the University Annex Addition)
Barger Drive (the Barger Addition)
Boze Street (Various Additions)14
Bryson Street (the Hillcrest and Williams Addition)15
Ferris Avenue (the Ferris 2 nd Addition)
Floyd Street (the University Annex Addition)17
Getzendaner Street Housing Project
Kirksey Street (the Ferris 2 nd Addition)
Lewis Street (the Park Hill Addition)
Overhill Drive (Various Additions)
Olive Street (Various Additions)
Patrick Street Housing Project
Perry Street (the Highland Park Addition)
Richmond Drive, Pensacola Ave., Monticello Drive, Charlotte Ave., and
Wilmington Ave. (The Belleview Addition)
Village Drive (the Village Addition)
National Register of Historic Places
Introduction
NRHP Criteria
NRHP Criteria Considerations
NRHP Recommendations
Individual Properties
New Historic Districts
Other Noteworthy Groupings
Other Recommendations
List of Preparers
Appendix A – Inventory of Properties Appendix B – Inventory of Post-World War II Neighborhoods

- Appendix C Supplemental Inventory of HIGH Priority Properties (Built Prior to 1946)
- Appendix D Maps of Waxahachie Historic Resource Survey Update

HISTORIC RESOURCES SURVEY UPDATE – REPORT

INTRODUCTION

In 1985, Hardy-Heck-Moore Inc. conducted a comprehensive survey of all resources within the city's boundaries that were erected in 1935 or earlier. In January 2003, the City of Waxahachie, Texas contracted HHM Inc. of Austin, Texas, to update the 1985 survey.

The scope of work consists of:

- Surveying all resources erected before 1935 that were not examined in the 1985 survey;
- Surveying all individual resources built between 1935 and 1945;
- Determining the preservation priority status of each surveyed resource;
- Identifying and taking a sampling from post-World War II neighborhoods that were established between 1945 and 1955 that were two or more blocks in size;
- Noting any previously unidentified noteworthy groupings or individual resources that have the potential to be listed in the NRHP;
- Examining areas directly adjacent to the current NRHP-listed historic districts for possible boundary expansion; and
- Compiling the survey and research results into a final report.

Survey work products include three types of documentation: survey report, GIS data, and digital photographs. The survey report describes the project goals, survey methodology, and the manner in which the properties were evaluated. This report includes:

- A discussion of the project goals and objectives;
- A definition of the survey methodology;
- A discussion of preservation priority assessments;
- Recommendations for the delineation of any separate potential historic districts;
- An inventory of all pre-1946 properties identified in the survey; and
- An inventory of the representative examples surveyed within the post-World War II neighborhoods.

David W. Moore Jr. served as Project Director and oversaw the project's completion. Architectural Historians Jennifer Ross, Olivia Fagerberg, Sophie Roark, and Karen Hughes comprised the survey team that identified, documented, photographed, and evaluated the historic resources. Ms. Ross was principal author and Mr. Moore edited the survey report. Paul Stevens, the Assistant City Manager with the City of Waxahachie, represented the City of Waxahachie and provided technical assistance.

RESEARCH METHODS

HISTORICAL RESEARCH

Prior to fieldwork, the HHM survey team downloaded electronic copies of Sanborn Fire Insurance Maps from a website maintained by the Dallas City Library. Sanborn Fire Insurance Maps depicted building footprints and note construction materials, the number of stories, and any ancillary buildings. In addition to the Sanborn Maps, the survey team copied Waxahachie City Directories from 1942 and 1955 at the Nicholas P. Sims Library and the Ellis County Museum. The Waxahachie City Directories provided a listing of all addresses within the city limits and a separate listing of all residents with their home address, phone number, and occupation. Both the City Directories and the Sanborn Maps enabled the survey team to more accurately assess the age of surveyed resources and to justify preservation priority ratings.

LEGAL RESEARCH

HHM contacted the Ellis County Tax Appraisal District to obtain a list of all non-tax exempt properties estimated to have been built between 1935 and 1945. HHM also examined plat maps held at the Ellis County Courthouse to identify the boundaries of a number of neighborhoods that were established between 1945 and 1955.

PRELIMINARY INVESTIGATIONS

In order to identify the small number of buildings erected in Waxahachie between 1935 and 1945, the HHM survey team accessed the comprehensive inventory of resources from the 1985 Historic Resources Survey, which listed all properties within the city's boundaries erected in 1935 and earlier and compared it to the street addresses listed in the 1942 City Directories. From this comparison, HHM compiled a listing of properties that were built between 1935 and 1942. One limitation associated with this methodology was that the city's boundaries have been expanded at least twice since 1942. This meant that a number of properties that were within the current city limits were outside the city limits in 1942 and therefore were not listed in the 1942 Waxahachie City Directories. Also, a number of addresses and street names have changed since 1942. To identify any properties that were erected within the targeted period in areas outside the 1942 city limits, HHM compared maps that depicted the 1942 and 2003 city boundaries. HHM then surveyed those areas that were located within the current city boundaries but were outside the city limits in 1942. In addition to utilizing the City Directories to identify buildings erected between 1935 and 1942, HHM obtained a list of buildings from the Ellis County Tax Appraisal District that inventoried all buildings within the city limits that were erected between 1935 and 1945. When compared to the comprehensive inventory of surveyed resources from the1985 Historic Resources Survey, the survey team found that the majority had been identified in the 1985 survey and were thus actually erected in 1935 or earlier.

To aid in its identification of post-World War II neighborhoods established between 1945 and 1955, HHM obtained Waxahachie City Directories published in 1955 and compared them to the 1942 City Directories. From this comparison, the survey team created an inventory of addresses of the houses that were erected between 1942 and 1955. HHM identified those neighborhoods with two or more blocks of houses erected within the targeted time period, inventorying and assessing all buildings within these groupings and photo-documenting representative examples.

FIELD INVESTIGATIONS

While in the field, the HHM survey team:

- Documented all previously unidentified properties erected before 1945, regardless of their condition;
- Noted each property's physical features and alterations;
- Plotted the location of each surveyed property on a map;
- Photographed each identified resource;
- Assessed each property's relative architectural and/or historical significance;

- Inventoried and assessed all buildings within targeted post-World War II neighborhoods established between 1945 and 1955 and photo-documented representative examples;
- Noted any previously unidentified groupings of noteworthy resources or significant individual resources that may be eligible for listing in the NRHP; and
- Assessed areas directly adjacent to the existing NRHP historic districts' boundaries for possible expansion.

Field investigations took place through a series of pedestrian surveys conducted in July and August 2003. Construction dates recorded in the field were based upon both resources collected during preliminary investigations (i.e. Waxahachie City Directories, maps, and Ellis County Tax Appraisal District Records) and the survey team's knowledge of time periods that particular architectural styles, plans, and construction techniques were popular.

FIELDWORK RESULTS

DATA ANALYSIS

Following completion of fieldwork, the HHM survey team initiated a review of all physical data and priority assessments recorded in the field. This process began with a comparison of each survey form to its associated photo or photos. Any discrepancies between information collected in the field and the true appearance of the property were noted and corrected on the survey forms. After reviewing all physical data collected in the field for accuracy, the survey team assessed all preservation priorities assigned in the field. All surveyed properties were compared to one another, re-evaluated as to their relative integrity within the project area, and assigned final recommendations of *HIGH*, *MEDIUM*, and *LOW* architectural value.

CRITERIA FOR EVALUATION

Each surveyed resource was evaluated and assigned a rating based upon its current architectural integrity and, if known, historical and cultural value. The evaluations reflect an assessment of each property's relative significance within a local context at the time they were surveyed and should not be considered static but can, and should, be changed to reflect the evolving status of properties. A property's rating may also change if future rehabilitation efforts or alterations affect its historic architectural integrity. Because the scope of work did not include any site-specific historical research, the priority assessments may be upgraded if future research reveals significant historical or cultural associations.

The current survey effort included an assessment of properties based upon a three-tier rating system (*HIGH*, *MEDIUM*, *LOW*). Properties with a *HIGH* rating were the most noteworthy resources within the project area. Properties classified as *MEDIUM* priority were still significant but may have been moderately altered. Properties in the *LOW* priority category, identified as the least important of the resources because they had been altered, were typical examples of a common architectural style or form.

HIGH PRIORITY

Properties ranked in this category were the city's most significant historic resources and were considered to be outstanding, unique, or good examples of architecture, engineering, or crafted design. *HIGH* priority resources were either individually listed or were good candidates for listing in the NRHP. If situated within a historic district, they were classified as Contributing elements. Properties identified with a *HIGH* rating have typically retained their physical/ architectural integrity to a high degree. If previously moved, these resources must have retained their architectural integrity to an exceptional degree.

HIGH priority resources that remained in situ may have undergone minimal alterations since their construction but retained their original exterior materials, fenestration pattern, form, and massing to a high degree. If altered, changes are typically of historic age (50 years or more) and were in keeping with original design, scale, and workmanship. Some of these properties had small additions, particularly to the side or rear, that represented historic-age porch enclosures or additions to provide expanded interior space. Non-historic alterations undertaken as part of regular building maintenance, such as the replacement of original exterior roofing materials, porch flooring and roofing, etc., did not necessarily affect the historic integrity if materials were replaced in kind and did not detract from the historic appearance of the resource.

MEDIUM PRIORITY

Resources in the *MEDIUM* priority category include properties that were not individually eligible for listing in the NRHP because they were older properties that had been modified. Despite alterations, these resources generally retained much of their historic integrity. If exterior materials, doors, and/or fenestration had been altered, *MEDIUM* priority properties retained their overall form, massing, and historic appearance to a good degree. For example, many of the *MEDIUM* priority resources have had their original exterior wall cladding covered or replaced with non-historic materials such as vinyl, aluminum, or fiber-based hardboard. These materials resembled horizontal wood siding, a common original exterior siding and therefore did not significantly impact a building's historic appearance. Also, the addition of non-historic doors and/or windows did not represent major modifications provided that the window and door openings themselves had not been altered. If *MEDIUM* priority resources had non-historic additions they were typically constructed of similar materials and/or confined from view from the public right-of-way.

A *MEDIUM* priority rating was also given to typical examples of common building forms within significant post-World War II neighborhoods. Although the houses may not be architecturally noteworthy on an individual basis, when viewed collectively, they may present a distinct, highly cohesive neighborhood. If the neighborhood is identified as potentially eligible for listing in the NRHP as an historic district, these resources are classified as Contributing properties.

LOW PRIORITY

The *LOW* priority category includes properties that represent typical examples of architectural styles and building forms that were erected in large numbers across the U.S. soon after the conclusion of World War II and therefore lack individual distinction. In some cases, these dwellings were erected as infill housing in earlier established neighborhoods. In other cases, these resources were situated within post-World War II neighborhoods established between 1945-1955 that were not eligible for listing in the NRHP due to a lack of historic integrity and/or significance.

A *LOW* priority rating was also given to examples of distinctive building forms, architectural styles, or plan types that have been severely altered. Among the types of alterations that collectively may warrant classification in the *LOW* priority category include the replacement of original exterior cladding with materials that adversely affect a building's historic appearance, the truncation or enclosure of original window or door openings, and major additions, particularly to publicly visible views, that alter the property's form, roofline, and/or massing.

SURVEYED POST-WORLD WAR II NEIGHBORHOODS

As part of the current study, HHM conducted a reconnaissance survey of all post-World War II neighborhoods established in Waxahachie between 1945 and 1955 that were composed of two or more blocks of resources. All resources within the neighborhoods were inventoried and assessed for potential NRHP eligibility and a sampling of representative examples was taken within each targeted neighborhood. Of all the neighborhoods assessed, HHM identified the Overhill Drive neighborhood, the Patrick Street Housing Projects, and the Getzendaner Street Housing Projects as potentially eligible for listing in the NRHP. A more in-depth discussion of these neighborhoods has been provided in the section entitled *New Historic Districts*. In addition, a complete listing of all inventoried properties within these neighborhoods is located in *Appendix B* of this report. The following are short descriptions and photographs of representative examples from each targeted post-World War II neighborhood including:

- Almond Street (The University Annex Addition);
- Barger Drive (The Barger Addition);
- Boze Street (Various Additions);
- Bryson Street (The Hillcrest and Williams Additions);
- Ferris Avenue (The Ferris 2nd Addition);
- Floyd Street (The University Annex Addition);
- Getzendaner Street Housing Project;
- Kirksey Street (The Ferris 2nd Addition);
- Lewis Street (The Park Hill Addition);
- Overhill Drive (Various Additions);
- Olive Street (Various Additions);
- Patrick Street Housing Project;
- Perry Street (The Highland Park Addition);
- Richmond Drive, Pensacola Avenue, Monticello Drive, Charlotte Avenue, and Wilmington Avenue (The Belleview Addition); and
- Village Drive (The Village Addition).

ALMOND STREET (THE UNIVERSITY ANNEX ADDITION)

PHYSICAL DESCRIPTION

Located within the 100-200 blocks of Almond Street is a grouping of wood-frame, single-family houses that were erected c.1946-1950. These resources are typically rectangular in plan and have either side-gabled or hipped roofs. All but two of the houses in this neighborhood are one-story in height. Original exterior wall materials include wood, brick, and stucco. All of the houses are utilitarian in appearance, displaying no distinctive stylistic elements. There are many alterations within the neighborhood, the most common include the re-cladding of original exterior materials with vinyl siding, asbestos shingles, or plywood paneling and the replacement of original windows.



100 Almond Street, erected c. 1950

Address	Date	Priority
100 Almond	1950	Low
101 Almond	1946	Low
102 Almond	1946	Low
103 Almond	1955	Low
104 Almond	1960	Low
105 Almond	1955	Low
106 Almond	1946	Low
108 Almond	1960	Low
111 Almond	1946	Medium
200 Almond	1946	Low
201 Almond	1950	Low



209 Almond Street, erected c. 1946

Address	Date	Priority
202 Almond	1946	Low
203 Almond	1946	
204 Almond	1950	Low
205 Almond	1950	Low
206 Almond	1950	Low
207 Almond	1946	Low
208 Almond	1946	Low
209 Almond	1946	Low
210 Almond	1950	Low
211 Almond	1960	Low

BARGER DRIVE (THE BARGER ADDITION)

PHYSICAL DESCRIPTION

Barger Drive, located in central Waxahachie, is a short, U-shaped street off Brown Avenue. According to records held at the Ellis County Courthouse, the neighborhood was platted in 1946. The resources in this neighborhood are wood-frame, one-story, single-or multiple-family houses that date from 1946-1955. Roofs are hipped or sidegabled. Original exterior materials include brick veneer and wood siding. All of the houses are utilitarian in appearance, displaying no distinctive stylistic elements. Almost all of the neighborhood's resources have had alterations to their original exterior wall material and/or original windows.



122 Barger Drive, erected c.1946

Address	Date	Priority
99 Barger	1955	Low
99 A/B Barger	1956	Low
100 Barger	1946	Low
101 Barger	1950	Low
102 Barger	1950	Low
103 Barger	1946	Low
105 Barger	1946	Low
106 Barger	1946	Low
107 Barger	1946	Low
107 Barger	1950	Low
108 Barger	1950	Low
108-08 1/2 Barger	1950	Low
109 Barger	1950	Low
110 Barger	1950	Low
111 Barger	1950	Low
112 Barger	1950	Low
113 Barger	1956	Low



99 Barger Drive, erected c. 1955

Address	Date	Priority
		J.
114 Barger	1946	Low
115 Barger	1950	Low
116 Barger	1946	Low
117 Barger	1950	Low
118 Barger	1950	Low
119 Barger	1950	Low
120 Barger	1946	Medium
121 Barger	1950	Low
122 Barger	1946	Low
122 Barger	1946	Low
123 Barger	1946	Low
124 Barger	1950	Low
125 Barger	1946	Low
126 Barger	1946	Low
128 Barger	1946	Low
130 Barger	1956	Low
132- A/B Barger	1956	Low

BOZE STREET (VARIOUS ADDITIONS)

PHYSICAL DESCRIPTION

Situated in central Waxahachie directly south of Barger Street is Boze Street, which contains a collection of single-family, wood-frame dwellings. Most of the neighborhood's resources were erected early in the post-World War II era, c.1946-1950. The street is narrow and lots are small allowing for small front and rear yards. Roofs are cross-gabled or side-gabled with a projecting front-gabled wing. Some roofs also have exposed rafter ends. The majority of the neighborhood's homes have been altered with the addition of vinyl siding, asbestos shingles, or masonite to exterior walls and the replacement of original windows.



207 Boze Street, erected c. 1946

Address	Date	Priority
104 Boze	1946	Low
104 Boze	1946	Low
106 Boze	1985	Low
113 Boze	1946	Low
113 Boze	1946	Low
114 Boze	1915	Medium
115 Boze	1950	Low
117 Boze	1946	Low
119 Boze	1946	Low
201 Boze	1920	High
202 Boze	1946	Low



113 Boze Street, erected c. 1946

Address	Date	Priority
203 Boze	1946	Low
204 Boze	1946	Low
205 Boze	1946	Low
206 Boze	1950	Low
207 Boze	1946	Low
207 Boze	1946	Low
208 Boze	1946	Low
209 Boze	1946	Low
210 Boze	1940	Low

BRYSON STREET (THE HILLCREST AND WILLIAMS ADDITIONS)

PHYSICAL DESCRIPTION

The 400-900 blocks of Bryson Street, centrally located within Waxahachie, contain a grouping of c.1940-1955, single-family homes with generous, well-landscaped front and rear yards. Also located within this neighborhood are two houses that were erected before 1935 and one c.1960 house. These resources are primarily one-story and have side-gabled, hipped, or front-gabled roofs. Exterior materials include asbestos shingles, wood siding, and brick veneer. A small number have had alterations to original exterior materials, but for the most part the neighborhood retains its historic integrity to a good degree.



700 Bryson Street, erected c. 1946

Address	Date	Priority
402 Bryson	1960	Low
404 Bryson	1946	Low
404 Bryson	1946	Medium
500 Bryson	1950	Low
502 Bryson	1950	Low
600 Bryson	1946	Medium
600 Bryson	1945	Low
606 Bryson	1946	Low
606 Bryson	1950	Medium
700 Bryson	1950	Low
700 Bryson	1946	Low
701 Bryson	1960	Low
703 Bryson	1955	Low
800 Bryson	1946	Low
803 Bryson	1955	Low
804 Bryson	1954	Low
805 Bryson	1950	Low



901 Bryson Street, erected c. 1955

Address	Date	Priority
806 Bryson	1925	Low
807 Bryson	1955	Low
900 Bryson	1885	High
901 Bryson	1955	Low
901 Bryson	1955	Medium

FERRIS AVENUE (THE FERRIS 2ND ADDITION)

PHYSICAL DESCRIPTION

The 1400-1500 blocks of North Ferris Avenue contain primarily single-family irregularor rectangular-plan dwellings. The majority of the neighborhood's houses were erected in the late 1940s while a smaller number were erected in the early 1950s. Resources are one-story in height and all utilize wood-frame construction. Side-gabled roofs are prevalent although the neighborhood has some hipped-roof and front-gabled dwellings. Front and rear yards are generous and well landscaped. A majority of the neighborhood's resources have exterior material alterations. In addition, some of the neighborhood's dwellings have had their original windows replaced with aluminum sash, single-hung units. Within the 1400 block there is one c.1980 commercial building, one c.1960 church, and one c.1985 dwelling.



1500 N. Ferris Ave., erected c. 1946

Address	Date	Priority
1504 N. Ferris Ave.	1946	Low
1408 N. Ferris Ave.	1955	Low
1409 N. Ferris Ave.	1950	Low
1410 N. Ferris Ave.	1950	Low
1412 N. Ferris Ave.	1955	Low
1413 N. Ferris Ave.	1950	Low
1414 N. Ferris Ave.	1946	Medium
1415 N. Ferris Ave.	1946	Medium
1417 N. Ferris Ave.	1955	Low
1419 N. Ferris Ave.	1946	Low
1500 N. Ferris Ave.	1946	Medium
1501 N. Ferris Ave.	1946	Medium
1502 N. Ferris Ave.	1955	Low
1505 N. Ferris Ave.	0	Low
1507 N. Ferris Ave.	1950	Low



1415 N. Ferris Ave., erected c. 1946

Address	Date	Priority
1508 N. Ferris Ave.	1950	Low
1400 W. Ferris Ave.	1985	Low
1401 W. Ferris Ave.	1969	Low
1404 W. Ferris Ave.	1985	Low
1411 W. Ferris Ave.	1950	Low
1414 W. Ferris Ave.	1950	Low
1415 W. Ferris Ave.	1946	Low
1500 W. Ferris Ave.	1946	Medium

FLOYD STREET (THE UNIVERSITY ANNEX ADDITION)

PHYSICAL DESCRIPTION

The 500-600 blocks of Floyd Street are dominated by a small grouping of c.1955, almost identical Ranch houses. These resources are one-story in height and are built of wood-frame construction. Each house was originally built with an attached garage, although two of the houses have had their garages infilled. Additional alterations include the addition of vinyl siding or asbestos shingles to the exterior and the replacement of original windows with aluminum-sash, single-hung units. The rectangular-plan dwellings have shallow side-gabled roofs with deep overhanging eaves.



602 Floyd Street, erected c. 1955

Address	Date	Priority
104 Floyd	1946	Low
106 Floyd	1945	Low
200 Floyd	1944	Medium
204 Floyd	1935	Low
208 Floyd	1942	Low
408 Floyd	1935	Low
500 Floyd	1955	Low
506 Floyd	1955	Low
506 Floyd	1955	Low
507 Floyd	1960	Low
600 Floyd	1955	Low
601 Floyd	1955	Low
602 Floyd	1955	Low
604 Floyd	1955	Low

GETZENDANER STREET HOUSING PROJECT

PHYSICAL DESCRIPTION

The Getzendaner housing projects is a planned neighborhood that the Housing Authority of the City of Waxahachie erected between 1951 and 1952. The neighborhood contains a grouping of Ranch-style, one-story wood-frame duplexes with brick veneer exterior walls and hipped roofs. Each house rests atop a concrete-slab-on-grade. Plans are irregular, and alterations are limited to the replacement of original windows with aluminum sash units.



800 Getzendaner Street, erected 1951

	_1	11	
	10		-
-	E		

Units 95-96	1951	Medium
Units 97-98	1951	Medium
Units 99-100	1951	Medium
Units 101-102	1951	Medium
Units 103-104	1951	Medium

Address	Date	Priority
800 Getzendaner Units 61-62	1951	Medium
Units 63-64	1951	Medium
Units 65-66	1951	Medium
Units 67-68	1951	Medium
Units 69-70	1951	Medium
Units 71-72	1951	Medium
Units 73-74	1951	Medium
Units 75-76	1951	Medium
Units 77-78	1951	Medium
Units 79-80	1951	Medium
Units 81-82	1951	Medium
Address	Date	Priority
Units 83-84	1951	Medium
Units 85-86	1951	Medium
Units 87-88	1951	Medium
Units 89-90	1951	Medium
Units 91-92	1951	Medium
Units 93-94	1951	Medium

KIRKSEY STREET (THE FERRIS 2ND ADDITION)

PHYSICAL DESCRIPTION

The 100-300 blocks of Kirksey Street are composed of primarily 1946-1955, singlefamily dwellings. The resources, which are one-story in height, were built of woodframe construction. Roof types include hipped, side-gabled and front-gabled. The majority of the neighborhood's resources have had their exterior wall re-clad with vinyl siding, asbestos shingles, or plywood panels. In addition, a number of the neighborhood's homes have had their original windows replaced with aluminum-frame, single hung units. The neighborhood has a number of non-historic intrusions, the majority of which are confined to the 300 block.



215 Kirksey Street, erected c. 1946

Address	Date	Priority
201 Kirksey	1930	Low
201 Kirksey	1930	Low
205 Kirksey	1950	Low
207 Kirksey	1946	Low
209 Kirksey	1946	Medium
209 Kirksey	1950	Low
211 Kirksey	211	Low
213 Kirksey	1946	Low
215 Kirksey	1946	Medium
301 Kirksey	1946	Low
302 Kirksey	1985	Low
303 Kirksey	1955	Low



209 Kirkset Street, erected c. 1946

Address	Date	Priority
305 Kirksey	1955	Low
307 Kirksey	1950	Low
309 Kirksey	1955	Low
311 Kirksey	1955	Low
313 Kirksey	1955	Low
315 Kirksey	1955	Low
317 Kirksey	1955	Low
319 Kirksey	1990	Low
321 Kirksey	1990	Low
325 Kirksey	1975	Low

LEWIS STREET (THE PARK HILL ADDITION)

PHYSICAL DESCRIPTION

Single-story, wood-frame dwellings dominate the 100-200 blocks of Lewis Street. The resources in this neighborhood, which date from between 1946 and 1950, are dedicated to both single-family and multiple-family residential uses. They are typically rectangular in plan and have side-gable roofs. The majority of the neighborhood's houses have either attached or detached single-car garages. Original exterior materials include wood siding and brick veneer. Typical alterations within the neighborhood include the replacement of original windows and exterior materials.



104 Lewis Street, erected c. 1950



207 Lewis Street, erected c. 1946

Address	Date	Priority
99 Lewis	1960	Low
100 Lewis	1955	Low
101 Lewis	1925	High
102 Lewis	1946	Low
103 Lewis	1955	Low
103 – 103 1/2 Lewis	1955	Low
104 Lewis	1956	Low
104 Lewis	1950	Low
106 Lewis	1950	Low
107 Lewis	1950	Low
108 Lewis	1950	Low
108 Lewis	1946	Low
109 Lewis	1950	Low
110 Lewis	1950	Low
111 Lewis	1946	Low
111 Lewis	1950	Low
207 Lewis	1946	Low

OVERHILL DRIVE (VARIOUS ADDITIONS)

PHYSICAL DESCRIPTION

Overhill Drive is a wide, two-block street in the northern portion of Waxahachie. The neighborhood contains a collection of primarily one-story, single-family Ranch dwellings with one early c.1925 Classical Revival dwelling, one c.1955 Contemporary style home, and one c.1946 Neoclassical Revival home. The 100 block is dominated by c.1956 Ranch homes while within the 200 block are c.1950 Ranch homes. Exteriors are typically brick veneer and roofs are hipped and gabled. Each house has a generous front and rear lawn. The neighborhood has undergone few alterations and contains only one post-1960 intrusion.



208 Overhill Drive, erected c. 1955 1955

Address	Date	Priority
111 Overhilll	1955	Medium
112 Overhill Drive	1960	Low
113 Overhill Drive	1960	Low
114 Overhill Drive	1960	Medium
115 Overhill Drive	1955	Medium
116 Overhill Drive	1955	Medium
118 Overhill Drive	1955	Low
119 Overhill Drive	1965	Low
120 Overhill Drive	1960	High
200 Overhill Drive	1955	Medium
201 Overhill Drive	1925	Medium
202 Overhill Drive	1955	Medium



218 Overhill Drive, erected c.

Address	Date	Priority
203 Overhill Drive	1955	Medium
204 Overhill Drive	1955	Medium
205 Overhill Drive	1946	Medium
205 Overhill Drive	1940	Medium
208 Overhill Drive	1955	Medium
209 Overhill Drive	1970	Low
210 Overhill Drive	1955	Medium
211 Overhill Drive	1955	Medium
215 Overhill Drive	1955	Medium
218 Overhill	1955	High

OLIVE STREET (VARIOUS ADDITIONS)

PHYSICAL DESCRIPTION

The targeted post-World War II grouping includes the 100-300 blocks of Olive Street. This neighborhood contains an assemblage of single- and multiple-family houses that were erected between 1946 and 1955. The 100 block is dominated by c.1946-1950 homes while the 200 block is composed primarily of c.1955 Ranch houses. All resources within this neighborhood are small wood-frame houses with small front and back yards. Roofs are side-gabled or cross-hipped. Original exterior materials include wood and brick veneer. The bulk of this neighborhood's resources have had their exterior walls reclad with vinyl siding.



105 Olive Street, erected c. 1955

Address	Date	Priority
101 Olive Street	1946	Low
103 Olive Street	1950	Low
105 Olive Street	1950	Low
105 Olive	1950	Low
107 A/B Olive Street	1950	Low
109 Olive Street	1955	Low
111 A/B Olive Street	1955	Low
201 Olive Street	1950	Low
203 Olive	1950	Low
203 Olive Street	1946	Low
205 Olive Street	1955	Low
206 Olive	1955	Low
206 A/B Olive Street	1955	Low
207 Olive Street	1950	Low
208 Olive Street	1955	Low



206 Olive Street, erected c. 1955

PATRICK STREET HOUSING PROJECT

PHYSICAL DESCRIPTION

Similar to the Getzendaner Street Housing Project, the Patrick Street Housing Project is composed of a grouping of Ranch-style, one-story, wood-frame duplexes with brick veneer exterior walls and hipped roofs that were erected 1951-1952. Foundations are concrete slab-on-grade, and plans are irregular. Alterations are limited to the replacement of original windows with aluminum sash units and the addition rear storage units.



208 Patrick Street, erected in 1951.

Address	Date	Priority
208 Patrick	1951	Medium
Units 1-2		
Units 3-4	1951	Medium
Units 5-6	1951	Medium
Units 7-8	1951	Medium
Units 9-10	1951	Medium
Units 11-12	1951	Medium
Units 13-14	1951	Medium
Units 15-16	1951	Medium
Units 17-18	1951	Medium
Units 19-20	1951	Medium
Units 21-22	1951	Medium
Units 23-24	1951	Medium
Units 25-26	1951	Medium
Units 27-28	1951	Medium
Units 29-30	1951	Medium



208 Patrick Street, rear facade, erected in 1951.

Address	Date	Priority
Units 31-32	1951	Medium
Units 33-34	1951	Medium
Units 35-36	1951	Medium
Units 37-38	1951	Medium
Units 39-40	1951	Medium
Units 41-42	1951	Medium
Units 43-44	1951	Medium
Units 45-46	1951	Medium
Units 47-48	1951	Medium
Units 40-50	1951	Medium
Units 51-52	1951	Medium
Units 53-54	1951	Medium
Units 55-56	1951	Medium
Units 57-58	1951	Medium
Units 59-60	1951	Medium

PERRY STREET (THE HIGHLAND PARK ADDITION)

PHYSICAL DESCRIPTION

The Perry Street neighborhood is a historically African-American neighborhood in the southeast portion of Waxahachie, off Getzendaner Street. The majority of Perry Street's homes date from 1945 to 1955, although there are a number of post-1960 and pre-1935 buildings within the neighborhood. The street is narrow and the lots are small, allowing for only small front lawns without sidewalks. The houses in the neighborhood are wood-frame, single-family dwellings and roofs are side-gabled, front-gabled, or hipped. Exterior wall cladding includes wood siding, asbestos shingles, vinyl siding, and plywood paneling. Common alterations include the replacement of original exteriors and windows. Also, a number of the neighborhood's homes have had wings added to front and/or rear facades.



301 Perry Street, erected c. 1946

Address	Date	Priority
102 Perry Street	1960	Low
106 Perry Street	1980	Low
202 Perry Street	1955	Low
203 Perry Street	1956	Low
204 Perry Street	1956	Low
205 Perry Street	1955	Low
206 Perry Street	1956	Low
208 Perry Street	1955	Low
301 Perry Street	1946	Low
301 Perry Street	1955	Low
302 Perry Street	1900	Medium



303 Perry Street, erected c. 1946

Address	Date	Priority
303 Perry Street	1955	Low
303 Perry Street	1946	Medium
304 Perry Street	1941	Low
304 Perry Street	1940	Low
305 Perry Street	1960	Low
306 Perry Street	1940	Low
306 Perry Street	1940	Low
307 Perry Street	1960	Low
308 Perry Street	1925	Medium

RICHMOND DRIVE, PENSACOLA AVENUE, MONTICELLO DRIVE, CHARLOTTE AVENUE, AND WILMINGTON AVENUE (THE BELLEVIEW ADDITION)

PHYSICAL DESCRIPTION

The 100 block of Monticello Drive, Pensacola Avenue, Charlotte Avenue, and Wilmington Avenue, in addition to the 100-200 blocks of Richmond Drive form one distinct neighborhood in the central portion of Waxahachie. Also associated with this neighborhood is a small, well-landscaped pocket park, situated along Richmond Drive. These streets are composed primarily of a mix of single- and multiple-family, late 1940s utilitarian homes and 1950s Ranches with some later, post-1960 development on Wilmington Street. The resources in this neighborhood are wood-frame and are one-story in height. Roofs are hipped, gable-on-hip, cross-gabled, and side-gabled. Alterations to exterior materials and original windows appear throughout the neighborhood.



110 Richmond Drive, erected c. 1946



103 Charlotte Avenue, erected c. 1950 1950

Address	Date	Priority
100 Charlotte	1950	Low
100 Charlotte	1946	Low



15 Mondeeno Drive, erected c. 1955



101 Wilmington Ave., erected c.

101 Charlotte	1950	Low
Address	Date	Priority
101 Charlotte	1950	Low

		-
102 Charlotte	1950	Low
103 Charlotte	1950	Low
Address	Date	Priority
103 Charlotte	1950	Low
105 Charlotte	1950	Low
106 Charlotte	1950	Low
107 Charlotte	1950	Low
108 Charlotte	1950	Low
109 Charlotte	1950	Low
110 Charlotte	1950	Low
111 Charlotte	1950	Low
112 Charlotte	1950	Low
113 Charlotte	1955	Low
114 Charlotte	1955	Low
101 Monticello	1950	Low
102 Monticello	1955	Low
103 Monticello	1950	Low
105 Monticello	1950	Low
106 Monticello	1950	Low
107 Monticello	1955	Low
108 Monticello	1960	Low
109 Monticello	1955	Low
110 Monticello	1955	Low
111 Monticello	1955	Low
112 Monticello	1955	Low
113 Monticello	1955	Low
113 Monticello	1955	Medium
114 Monticello	1955	Medium
114 Monticello	1955	Low
100 Pensacola Ave.	1955	Low
101 Pensacola Ave.	1955	Medium
101 Pensacola Ave.	1950	Low
102 Pensacola Ave.	1950	Low
102 Pensacola Ave.	1950	Low
103 Pensacola Ave.	1950	Low
104 Pensacola Ave.	1950	Low
104 Pensacola Ave.	1955	Low
L		

105 Pensacola Ave.	1950	Low
Address	Date	Priority
106 Pensacola Ave.	1950	Low
107 Pensacola Ave.	1955	Low
108 Pensacola Ave.	1950	Low
109 Pensacola Ave.	1955	Low
110 Pensacola Ave.	1955	Low
111 Pensacola Ave.	1955	Low
113 Pensacola Ave.	1955	Low
102 Richmond Drive	1955	Medium
104 Richmond Drive	1955	Medium
104 Richmond Drive	1955	Medium
106 Richmond Drive	1955	Medium
110 Richmond Drive	1946	Medium
110 Richmond Drive	1955	Low
114 Richmond Drive	1955	Low
116 Richmond Drive	1955	Low
118 Richmond Drive	1946	Medium
101 Richmond Lane	1955	Medium
201 Richmond Lane	1946	Medium
100 Wilmington	1950	Low
101 Wilmington	1950	Medium
101 Wilmington	1950	Low
103 Wilmington	1950	Low
104 Wilmington	1950	Low
105 Wilmington	1950	Low
106 Wilmington	1950	Low
106 Wilmington	1955	Medium
107 Wilmington	1950	Low
108 Wilmington	1950	Low
109 Wilmington	1955	Low
110 Wilmington	1955	Low
111 Wilmington	1946	Low
112 Wilmington	1955	Low
113 Wilmington	1955	Low
114 Wilmington	1960	Low
U		

VILLAGE DRIVE (THE VILLAGE ADDITION)

PHYSICAL DESCRIPTION

The Village Drive neighborhood is composed of a collection of nearly identical singlefamily, concrete-block dwellings that were erected c.1946. These rectangular-plan, frontgabled resources are situated within a cul-de-sac in the northern portion of Waxahachie. Exterior wall materials include concrete block, asbestos shingles, and plywood panels. Each dwelling has a small fenced front and rear yard. The majority of these dwellings have had their exterior walls re-clad and their original windows replaced. The neighborhood has only one modern intrusion located at 210 Village Drive. Due to the homogeneous nature of the neighborhood, it is likely the homes are former rental units.



211 Village Drive, erected c. 1946

Address	Date	Priority
200 Village Drive	1946	Low
202 Village Drive	1945	Low
202 Village Drive	1946	Low
203 Village Drive	1946	Low
204 Village Drive	1946	Low
205 Village Drive	1946	Low
206 Village Drive	1946	Low
207 Village Drive	1946	Low
208 Village Drive	1946	Low
209 Village Drive	1946	Low
210 Village Drive	1980	Low
211 Village Drive	1946	Low
211 Village Drive	1946	Low



202 Village Drive, erected c. 1946

NATIONAL REGISTER OF HISTORIC PLACES

INTRODUCTION

The National Historic Preservation Act (NHPA) of 1966 established the National Register of Historic Places (NRHP) as the official Federal list of historic and cultural properties that are worthy of preservation. Congress authorized the Secretary of the Interior to maintain the NRHP. The National Park Service (NPS) within the Department of the Interior, oversees the implementation of the program at the Federal level and works with each of the State Historic Preservation Officers (SHPO) who administer the program in each state.

To be eligible for the NRHP, a property must be significant in the history, architecture, archaeology, engineering, and culture of our nation and retain sufficient integrity to convey that significance. A property does not necessarily have to be a nationally recognized landmark to be eligible for the NRHP, and a property that is significant within a state or local context may also be eligible for the NRHP. Thus, the NRHP includes such well-known landmarks as Mount Vernon, Monticello, and the U.S. Capitol, but also county courthouses, schools, and residences of locally prominent citizens.

The NRHP includes a diverse collection of properties that represent virtually all aspects of the built environment. The NHPA defines four kinds of properties that can be eligible for the NRHP, and each has a very specific denotation:

Building—an edifice created to shelter any form of human activity, such as a house, barn, church, hotel, factory, or similar structure. The designation "building" may refer to a historically related complex such as a courthouse and jail or a house and barn. A building can include grand, architect-designed residences, churches, schools, or stores, as well as modest, vernacular buildings.

Site—location of a significant event, a prehistoric or historic occupation or activity, or a building or structure, whether standing, ruined or vanished, where the location itself maintains historical or archaeological value regardless of the value of any existing structure. A site can mark the location of a battlefield, a rock midden Native American village, or an early milling operation.

Structure—a work made of interdependent and interrelated parts in a definite pattern of organization. Constructed by man, it is often an engineering project that is large in scale, such as a bridge or trestle.

Object—a material thing of functional, aesthetic, cultural, historical, or scientific value that may be, by nature or design, movable yet related to a specific setting

or environment. An object can be public art, a mode of transportation, or infrastructural features.

Properties can be eligible for inclusion in the NRHP on an individual basis or as a cohesive grouping, known as a historic district. The NPS defines a historic district as a significant concentration linkage or continuity of buildings, sites, structures, and/or objects united historically or aesthetically by plan or physical development. The resources in a historic district share a common history and/or physical traits that collectively convey a sense of time and place. A historic district encompasses a well-defined area that is distinct from its surroundings and whose boundaries are logically established. Typically, the majority (at least 50 percent) of the extant resources within a historic district must retain sufficient integrity to enhance the district's historic character. These resources are classified as Contributing properties. Severely altered historic resources or properties constructed after the district's period of significance are classified as Noncontributing elements and generally detract from the district's overall historic character.

NRHP CRITERIA

To be eligible for listing in the NRHP, a property typically must be at least 50 years old, must retain integrity, and meet at least one of the following four NRHP Criteria:

A. be associated with events that have made a significant contribution to the broad patterns of our history;

B. be associated with the lives of persons significant in our past;

C. embody the distinctive characteristics of a type, period, or method of construction or represent the work of a master, or possess high artistic values, or represent a significant and distinguishable entity whose components may lack individual distinction; or

D. has yielded, or may be likely to yield, information important in prehistory or history.

NRHP CRITERIA CONSIDERATIONS

The NHPA allows for a wide variety of properties to be evaluated for possible inclusion in the NRHP, but certain kinds of resources ordinarily are excluded from consideration for NRHP eligibility. The kinds of properties normally exempted from such designation include cemeteries, birthplaces, or graves of historical figures; properties owned by religious institutions or used for religious purposes; buildings or structures that have been moved from their original locations; reconstructed historic buildings; properties that are primarily commemorative in nature; and properties that have achieved significance within the past 50 years. However, the NHPA recognizes that in certain cases, these properties can be noteworthy and thus may deserve NRHP recognition, under the established NRHP Criteria Considerations. Such properties will qualify if they are integral parts of districts or if they conform to the following criteria:

A. a religious property deriving primary significance from architectural or artistic importance;

B. a building or structure removed from its original location but which is significant primarily for architectural value, or which is the surviving structure most importantly associated with a historic person or event;

C. a birthplace or grave of a historical figure of outstanding importance if there is no other appropriate site or building directly associated with his or her productive life;

D. a cemetery which derives its primary significance from graves of persons of transcendent importance, from distinctive design features, or from association with historic events;

E. a reconstructed building when accurately executed in a suitable environment and presented in a dignified manner as part of a restoration master plan, and when no other building or structure with the same association has survived;

F. a property primarily commemorative in intent if design, age, tradition, or symbolic value has invested it with its own historical significance; or

G. a property achieving significance within the past 50 years if it is of exceptional importance.

NRHP RECOMMENDATIONS

INDIVIDUAL PROPERTIES

One of the goals of this project was to locate and document all buildings, structures, sites, and objects within the city's boundaries that may be individually eligible for listing in the NRHP. Based on the current study, HHM assigned each of the following properties a HIGH-priority rating. These properties have therefore been identified as the strongest candidates for individual listing in the NRHP. A number of these properties are significant because they represent outstanding examples of a unique or common architectural style or form, or exhibit particularly noteworthy craftsmanship or design qualities. Some also contribute significantly to local or broader historical patterns. These resources must retain a high level of integrity and thus, the removal, replacement, or

covering of structural or decorative features will diminish a notable property's opportunity for historic designation.

Evaluations were based on the present condition of each building and known historical data. Before a definitive list of High-priority/individually-eligible properties can be compiled, more research is necessary to determine which properties have associative significance. The following table represents a cross-section of property types recorded by the HHM survey team.

Resource	Location	Year
Hawkins Spring	Hawkins Street	c. 1900
House (Queen Anne-style)	3209 Highway 77	c. 1905
House (Queen Anne-style)	Howard Road	c. 1900
Cemetery (Freedman's Cemetery)	E. Jefferson	c. 1920
Church	501 W. Marvin	c. 1951
House (Colonial Revival/Ranch Style)	606 W. Marvin	c. 1944
House (Mission Revival)	202 Old Howard	c. 1915
	Road	
House (Queen Anne style)	140 E. Sterrett	c. 1890
	Road	
House (Vernacular)-Contributing to the West End	209 S. Hawkins	c. 1890
Historic District		
House (Tudor Revival)	602 Sycamore	c. 1930

NEW HISTORIC DISTRICTS

Based on a reconnaissance survey of the project area, HHM identified four individual groupings of resources that have a strong potential for listing in the NRHP. These potential historic districts included: the Patrick Street Housing Project; the Getzendaner Street Housing Project; the Overhill Drive Neighborhood; and the University Street area. Because the current survey effort did not include in-depth historic research, these recommendations are merely preliminary. HHM therefore recommends that these areas be more closely researched before final determinations are made.

• <u>Getzendaner Street Housing Project</u>: In 1951-1952, the Housing Authority of the City of Waxahachie erected the Getzendaner Street Housing Project using Federal funds secured from the Housing and Home Finance Authority. HHM determined that the neighborhood was significant because is was a distinct example of post-World War II housing in Waxahachie and was representative of the Federal Government's efforts to improve living conditions for economically disadvantaged families in the years immediately following World War II. The neighborhood, located on Getzendaner Street on the city's east side, contains one-story, wood-frame, Ranch-style duplexes. On an individual basis, the houses are not architecturally distinctive nor do they display noteworthy detailing or workmanship. However, when viewed collectively, the neighborhood presents a

highly cohesive grouping that has retained its integrity to a high degree. The neighborhood has had no new construction since its original construction. Alterations to the buildings themselves are limited to the replacement of original windows.

- <u>Overhill Drive</u>: The 100 and 200 blocks of the Overhill Drive neighborhood, situated in the northern portion of Waxahachie, is composed primarily of a collection of single-family post-World War II era Ranch-style homes. Also located within the neighborhood, at 201 Overhill, is a c.1920 Colonial Revival dwelling that was listed in the NRHP in 1986. The neighborhood's generous, well-landscaped lawns and serpentine, curving street presents an overall aesthetically pleasing atmosphere. A number of the houses in the neighborhood are individually noteworthy, displaying strong associations with the Ranch style. The neighborhood has only one post-1960 resource and alterations are minimal. Similarities in style, setback, scale and use of materials create a strong sense of cohesiveness in the neighborhood. HHM therefore found Overhill Drive to be an excellent example of a post-World War II Era Ranch-dominated neighborhood.
- Patrick Street Housing Project: Similar to its companion neighborhood on Getzendaner Street, the Patrick Street Housing Projects include a grouping of one-story, wood-frame duplexes with brick veneer exterior cladding. The resources, erected in 1951-1952 by the Housing Authority of the City of Waxahachie using Federal funds secured from the Housing and Home Finance Authority, were determined to be eligible because the neighborhood remains a representative example of the Federal Government's efforts to improve living conditions for economically disadvantaged families in the years immediately following World War II. Similarities in style, form, and materials in addition to landscaping, created a highly cohesive grouping. Alterations were limited and include the replacement of original window units and the addition of rear storage units. The additions were constructed of materials similar to the buildings' original exterior and cladding were confined to the rear of the houses and thus are not visible from the street.
- <u>University Street Neighborhood</u>: Located directly south of the Southwestern Assemblies of God College campus in the north central portion of Waxahachie, the University Street Neighborhood potential historic district includes the 100-300 blocks of W. University, University, E. University, Cynisca, and Virginia Streets. The neighborhood is dominated by single-family c.1920-1935 bungalows of varying styles including Craftsman and Tudor Revival. Although a small number of these houses were subdivided and some underwent alterations to exterior materials, windows, etc., as a grouping the neighborhood retains its historic integrity to a good degree and remains the best, most architecturally intact bungalow-dominated neighborhood in Waxahachie.

OTHER NOTEWORTHY GROUPINGS

In addition to its identification of the aforementioned potential NRHP historic districts, the current survey effort determined that two concentrations of resources –the Harbin/Kirven Street neighborhood and the 400-1400 block of Sycamore Street– were architecturally noteworthy. However, when compared to the Patrick Street Housing Project, the Getzendaner Street Housing Project, the Overhill Drive Neighborhood, and the University Street area, neither grouping stood as a strong candidate for listing in the NRHP. Although both the Harbin/Kirven Street neighborhood and the 400-1400 block of Sycamore Street contain individually significant dwellings, the survey team found that they generally lacked the cohesiveness and/or integrity that existed in the newly identified potential historic districts.

The Harbin/Kirven Street neighborhood contains a collection of one- and two-story residential properties that date from the early 1920s to the late 1940s. The neighborhood's earliest homes are bungalow-plan dwellings, some with Craftsman or Tudor Revival ornamentation, while its post-World War II historic-age resources are typically irregular-plan, Ranch- or Minimal Traditional-style dwellings. The neighborhood's houses sit on generous lots and share uniform setbacks and landscaping. In addition, there is little non-historic age infill or vacant lots in the neighborhood, and nearly all of the houses well maintained. Although similarities in style, setback, and scale create a good sense of cohesiveness within the neighborhood, many of its resources have undergone exterior modification after the historic period of significance. Common non-historic alterations include the application of synthetic exterior cladding, the replacement of original windows, and porch alterations. These modifications have led to an overall loss of historic character and architectural integrity within the neighborhood, rendering it ineligible for listing in the NRHP.



Streetscape. Harbin Street, showing porch (right) and window (left) alterations.



Dwelling, Harbin Street. Showing porch alteration.

Sycamore Street is an east/west thoroughfare in the north-central portion of Waxahachie. The street, which is dominated by single-family, one- and two-story dwellings, contains a range of resources that date from the early 20th century to the late 20th century. Due primarily to its location off of Ferris Street/US 77, a main north/south commercial thoroughfare, the formerly solely residential street has undergone a small amount of commercial development. In addition, a number of vacant lots dot the eastern portion of the street. The most significant concentration of resources along Sycamore Street is situated within the 500-600 block, off Harbin and Kirven Streets. Within these blocks is a small number of Tudor Revival, Ranch, and Dutch Colonial Revival, early 1930s though late 1940s massed-plan, dwellings. As a whole, these dwellings are well maintained and have undergone little modification. Common changes to a number of dwellings along other parts of Sycamore Street include the replacement of original exterior materials and windows and additions affect the neighborhood's historic character. Furthermore, the presence of non-historic infill development and vacant lots has diminished the street's historic setting and its overall sense of cohesiveness. The survey update, therefore, recommends that Sycamore Street is not eligible for inclusion in the NRHP.



Sycamore Street. Dutch Colonial Revival dwelling.

OTHER RECOMMENDATIONS

This update supplements the 1985 survey by completing the list of all pre-1945 historic resources within the current (2003) city limits of Waxahachie. Some of the properties

were simply overlooked during the 1985 survey, or they did not meet the NRHP 50-year age threshold at that time. Still other properties were outside the city limits in 1985 but have since been incorporated into the city. The survey update has also identified individual properties and historic districts that may be eligible for the NRHP. However, the City should consider additional work to complete the survey update and establish other preservation planning efforts. The following are recommended actions to be considered by the City:

- Re-examine and re-evaluate properties identified in the 1985 survey:
 - Re-assess properties based upon current conditions by:
 - Upgrading properties that have been subject to restoration efforts that are sensitive and appropriate to historic character; and
 - Downgrading properties that have been altered so that historic integrity has been degraded; and
 - Photograph the more significant properties:
 - individual properties that are listed in or may eligible for inclusion in the NRHP; and
 - properties that are classified as Contributing elements in historic districts listed in the NRHP; and
- Conduct additional research for the post-1935 era to supplement the historic context developed for the multiple-resource NRHP nomination. The research should examine the history and developmental patterns of Waxahachie and areas immediately surrounding the city since 1935. This information will enable properties from this period to be assessed for their relative significance within the established context;
- Conduct site-specific research on newly designated HIGH priority properties to determine if they meet NRHP Criteria and thus are eligible for inclusion in the NRHP;
- Conduct research on areas identified in the survey update as having potential for inclusion in the NRHP;
- Nominate additional properties to the NRHP including:
 - Individual properties;
 - New historic districts; and
 - Expand existing NRHP-listed historic district, if applicable; and
- Consider the adoption of a preservation plan to guide local preservation efforts; and
- Consider developing a design manual that identifies the major architectural styles, types, and forms in Waxahachie and provides fundamental preservation techniques and strategies.

Although identified as not eligible for listing in the NRHP, the current survey effort identified the two groupings of properties –the Harbin/Kirven Street neighborhood and the 400-1400 block of Sycamore Street– as architecturally significant due to the number of individually noteworthy properties each possessed. Upon initiation of the next historic resources survey effort, the City should re-assess the Harbin/Kirven Street neighborhood and, in particular, the associated 500-600 block of Sycamore Streets by:

- Upgrading properties that have been subject to restoration efforts that are sensitive and appropriate to historic character;
- Downgrading properties that have been altered so that historic integrity has been degraded; and
- Conducting research on both areas if they are considered eligible for listing in the NRHP.

LIST OF PREPARERS

David W. Moore, Jr.	
Project Director	HHM Historian with 26 years experience. Responsible for overall project direction; contributed to portions of the report.
Jennifer Ross	
Architectural Historian	HHM Architectural Historian with 5 years experience. Principal author of the report. Conducted extensive field and archival research.

OTHER CONTRIBUTORS

Karen Hughes	HHM Architectural Historian with 5 years experience.
Architectural Historian	Conducted extensive field and archival research.
Olivia Fagerberg	HHM Architectural Historian with 2 years experience.
Architectural Historian	Conducted extensive field and archival research.
Sophie Roark	HHM Architectural Historian with 3 years experience.
Architectural Historian	Conducted extensive field and archival research.
Lori Smith Production Manager	HHM Production Manager with 2 years experience. Report editor; managed and facilitated report layout and production.

Appendix A

Inventory of Historic Properties

Appendix A

The following inventory includes a listing of all pre-1946 historic resources within the current city limits that have not be previously identified and documented and supplements the 1985 historic resources survey. The properties are listed in address order and include the most essential information for each identified resource: address, estimated date of construction, property type classification, plan, stylistic influence, structural system, roof type, and exterior materials. The inventory also identifies major changes to exterior finishes, windows, doors, porches, roofs, as well as major additions.

Waxahachie Survey Update of 2003 - Supplemental Inventory of Historic Properties (Built Prior to 1946)

	Address	108 N. Aiken		
	Date	1935		Alterations/Modifications
	Current Use	Residence; Vacant		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
<i>Priority</i>	Exterior Materials	Wood	Addition(s)	
		L		
A LAND AND A LAND	Address	112 S. Aiken		
	Date	1940		Alterations/Modifications
	Current Use	Residence	First Materials	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped		
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	
	Address	201 S. Aiken		
	Address Date	201 S. Aiken 1940		Alterations/Modifications
			Evt Materials	Alterations/Modifications
	Date	1940	Ext. Materials Windows	Alterations/Modifications
	Date Current Use	1940 Residence	Windows	Alterations/Modifications
	Date Current Use Property Type	1940 Residence Domestic: single-family	Windows Doors	Alterations/Modifications
	Date Current Use Property Type Plan	1940 Residence Domestic: single-family Rectangular: linear	Windows Doors Porch	Alterations/Modifications
	Date Current Use Property Type Plan Style	1940 Residence Domestic: single-family Rectangular: linear No Style	Windows Doors Porch Roof	Alterations/Modifications
	Date Current Use Property Type Plan Style No. of Stories	1940 Residence Domestic: single-family Rectangular: linear No Style 1	Windows Doors Porch Roof Alterations	
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame	Windows Doors Porch Roof Alterations	Alterations/Modifications
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable	Windows Doors Porch Roof Alterations	
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable	Windows Doors Porch Roof Alterations	
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood	Windows Doors Porch Roof Alterations	
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940 Residence	Windows Doors Porch Roof Alterations Addition(s)	Has a small side façade addition
Prority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940	Windows Doors Porch Roof Alterations Addition(s) Ext. Materials	Has a small side façade addition
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940 Residence Domestic: single-family Rectangular: linear	Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows	Has a small side façade addition
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940 Residence Domestic: single-family Rectangular: linear No Style	Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows Doors	Has a small side façade addition
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940 Residence Domestic: single-family Rectangular: linear No Style 1	Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows Doors Porch	Has a small side façade addition Has a small side façade addition Alterations/Modifications
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940 Residence Domestic: single-family Rectangular: linear No Style	Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows Doors Porch Roof	Has a small side façade addition Has a small side façade addition Alterations/Modifications
Priority High Priority High	Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories	1940 Residence Domestic: single-family Rectangular: linear No Style 1 Wood frame Front gable Wood 203 S. Aiken 1940 Residence Domestic: single-family Rectangular: linear No Style 1	Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows Doors Porch	Has a small side façade addition Has a small side façade addition Alterations/Modifications

Appendix A: Page 1

	Address	205 S. Aiken		
States of the second se	Date	1944		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		Original windows replaced
	Style	No Style	— Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
the second of the second	Roof	Front gable	Alterations	
<i>Priority</i> ☐ High Medium ✓ Low	Exterior Materials	Wood	Addition(s)	
			L	
	Address	207 S. Aiken		
	Date	1935		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Bungalow		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
The second s	Roof	Front gable	— Alterations	
Priority ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
· · · · · · · · · · · · · · · · · · ·				
	Address	201 Aldridge		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	— Alterations	
Priority High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
			L	
	Address	215 Aldridge		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
		Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed		Original windows replaced
	Style	No Style	— Doors	
P -	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
And the second se	-	Side gable	— Alterations	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address	110 Bauder		
	Date	1941		Alterations/Modifications
	Current Use	Residence	—	
ALCONS ALCON	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow		
	Style	Craftsman	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame		
			1	
	-		— Alterations	
Priority ☐ High ☐ Medium ✔ Low	-	Cross gable Asbestos	Alterations Alterations Addition(s)	

	Address	117 Bauder		
	Date	1935		Alterations/Modifications
	Current Use	Residence	- Fort Materials	
	Property Type	Domestic: single-family	 Ext. Materials 	Windows replaced w/aluminum-frame units
	Plan	Rectangular: massed	— Doors	
	Style	No Style	- Porch	
	No. of Stories	1	- Roof	
	Structural System	Wood frame	- Alterations	
	Roof	Front gable	— Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Wood		
· ALLES VILLES	Address	200 Bauder		
	Date	1935	_	Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exteriors re-clad w/vinyl siding
	Property Type	Domestic: single-family	- Windows	
	Plan	Bungalow	— Doors	
	Style	No Style	- Porch	
the second secon	No. of Stories	1	— Roof	
	Structural System	Wood frame	— Alterations	
Drievity Ulish Madium I Law	Roof		- Addition(s)	
Priority High Medium V Low	Exterior Materials	Vinyl		
	Address	204 Bauder		
	Date	1915		
- San	Current Use	Residence	-	Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Property Type Plan	Rectangular: massed	— Windows	Windows replaced w/aluminum-frame units
	Style	No Style	— Doors	
	No. of Stories	1	- Porch	
A State of the sta	Structural System	Wood frame	— Roof	
	Roof	Hipped	— Alterations	
Priority 🗌 High 🔄 Medium 🖌 Low	Exterior Materials	Wood	— Addition(s)	Has a c. 1950 shed-roof side addition
			L	
	Address	208 Bauder		
	Date	1930		Alterations/Modifications
	Current Use	Residence		Atterations/modifications
	Property Type	Domestic: single-family	— Ext. Materials	Mindaus and and under since frame units
	Plan	Shotgun		Windows replaced w/aluminum-frame units
	Style	No Style	— Doors	
	No. of Stories	1	— Porch — Roof	
and the second se	Structural System	Wood frame	— Roor — Alterations	
	Roof	Front gable	— Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(6)	
	Address	209 Bauder		
-90	Date	1945	_	Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad
	Property Type	Domestic: single-family		Most original windows changed
	Plan	Rectangular: massed	- Doors	
	Style	No Style	- Porch	
AND AND ALL AN	No. of Stories	1 Weed from a	— Roof	
Handler I. Carlo and	Structural System	Wood frame	- Alterations	
	Roof	Front gable; Shed	Addition(s)	Side façade shed-roof addition
Priority High Medium V Low	Exterior Materials	Wood; Masonite; Asphalt shingle		

	Address	215 Bauder		
	Date	1920		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad w/vinyl siding
	Plan	Rectangular: massed		Windows replaced w/aluminum-frame units
	Style	No Style	— Doors	Original porch replaced
Charles and the second se	No. of Stories	1	— Porch	
	Structural System	Wood frame	- Alterations	
	Roof	Hipped		Has front, rear, and side additions
<i>Priority</i>	Exterior Materials	Vinyl		
and the second se	Address	642 Black Champ Road		
and the second	Date	1925		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/masonite
	Property Type	Domestic: single-family		
	Plan Style	Bungalow Craftsman	— Doors	
	No. of Stories	Cransman 1	Porch	
	Structural System	Wood frame		
	-	Front gable	— Alterations	
<i>Priority</i>	Exterior Materials	Masonite	— Addition(s)	
	Address	2380 Black Champ Road		
	Date	1910		
and the second	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: multiple-family		Exterior walls re-clad
	Plan	Irregular		Original windows replaced
	Style	No Style	— Doors	
	No. of Stories	2	- Porch	
	Structural System	Wood frame	- Roof	
	Roof	Cross gable	— Alterations	
<i>Priority</i>	Exterior Materials	Hardboard	— Addition(s)	
	Address	210 Boze		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan	Rectangular: massed	— Doors	
	Style	No Style		
	No. of Stories	1	Roof	
	Structural System	Wood frame		
	Roof	Complex	— Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Vinyl; Stucco		
	Address	611 Brookside		
	Date	1940		··· · · · · · ·
Net.	Current Use	Residence	—	Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Property Type Plan	Bungalow	Windows	Some replaced w/ aluminum frame
	Style	No Style	— Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	— Alterations	
<i>Priority</i> High Medium ☑ Low	Exterior Materials	Wood	Addition(s)	Garage Addition

	Address	209 1/2 Brown		
	Date	1945		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
STREET, GARLES TON	Style	No Style	Porch	
	No. of Stories	1		
a contract of the second se	Structural System	Wood frame	Alterations	
and the second	Roof	Side gable	Addition(s)	
Priority 🗌 High 📄 Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address	209-B Brown		
	Date	1935		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
<i>Priority</i> ☐ High	Exterior Materials	Wood	, iduliion(o)	
section of the section of	Address	300 Brown		
	Date	1935		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Irregular	Doors	
	Style	No Style	Porch	
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Complex	Addition(s)	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Vinyl		
	Adduses	444 D		
	Address	411 Brown		
	Date	1942		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family	Windows	
		Rectangular: massed	Doors	
	Style	No Style	Porch	
and the second second	No. of Stories Structural System	1 Wood frame	Roof	
and the second	-		Alterations	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Cross gable Wood	Addition(s)	
	Address	1202 Buena Vista Road		
	Date	1945		
	Current Use	Residence		Alterations/Modifications
the second second	Property Type	Domestic: single-family		Exterior walls re-clad w/vinyl siding
	Plan	Irregular	Windows	
	Style	No Style	Doors	
	No. of Stories	1		Porch supports replaced
	Structural System	Wood frame	Roof	
	-	Cross gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Vinyl	Addition(s)	
			L	

	Address	? Business 287		
	Date	1925		Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exteriors re-clad in asbestos shingle
A Real	Property Type	Domestic: single-family	— Windows	
No Ladore var	Plan	Bungalow	- Doors	
	Style	Craftsman		Porch supports replaced
	No. of Stories	2	- Roof	
	Structural System	Wood frame	Alterations	
	Roof	Front gable	- Addition(s)	Large rear two story addition
Priority High Medium 🖌 Low	Exterior Materials	Wood; Asbestos		
and the state of	Address	2319 Business 287		
	Date	1944		
and the second	Current Use	Residence	—	Alterations/Modifications
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Rectangular: massed	- Windows	
	Style	No Style	— Doors	
	No. of Stories	1	- Porch	
	Structural System	Load-bearing masonry	- Roof	
	Roof	Front gable	 Alterations 	
<i>Priority</i>	Exterior Materials	Concrete Block	— Addition(s)	
A-	Address	1702 Business 287 (Main)		
	Date	1930		Alterations/Modifications
ALLA STREET	Current Use	Commercial	Ext. Materials	
	Property Type	Commercial	- Windows	
	Plan	Irregular	Doors	
	Style	No Style	- Porch	
	No. of Stories	1.5	— Roof	
	Structural System Roof	Wood frame Front gable; Comp Shingle	- Alterations	
Priority ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood; Plywood panel	— Addition(s)	
	Address	807 Cantrell		
	Date	1940		Alterations/Modifications
	Current Use	Residence	—	
	Property Type	Domestic: single-family	— Ext. Materials	
- the set of the set	Plan	Rectangular: massed	- Windows	
	Style	No Style	— Doors — Porch	
	No. of Stories	1	— Roof	
	Structural System	Wood frame	- Alterations	
		Side gable	- Addition(s)	
Priority High 🖌 Medium 🗌 Low	Exterior Materials	Wood		
	Addroop	833 Cantrell		
	Address Date	1945		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family		Exterior walls re-clad w/vinyl
	Plan	Rectangular: massed		Original windows replaced
	Style	No Style	- Doors	
	No. of Stories	1	- Porch	
	Structural System	Wood frame	- Roof	
	-	Side gable	Alterations	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Vinyl	Addition(s)	

	Address	206 Center		
And a set of the set	Date	1935		Alterations/Modifications
A CARLEY	Current Use	Residence	Fut Matariala	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		
	Style	No Style		
A REAL PROPERTY AND	No. of Stories	1	— Porch — Roof	
and the second sec	Structural System	Wood frame	Alterations	
THE NEW .	Roof	Side gable		
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	118 Church		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Aluminum sash units added
	Plan	Bungalow	- Doors	
	Style	Craftsman		
	No. of Stories	1	- Roof	
	Structural System	Wood frame	— Alterations	
	Roof	Front gable		
<i>Priority</i> High Medium	Exterior Materials	Wood	Addition(3)	
	Address	112 Coats		
	Date	1910		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl
	Property Type	Domestic: single-family		
	Plan	L-Plan		
	Style	No Style		
A second se	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Vinyl		
	Address	115 Coats		
Contraction of the second second	Date	1942		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Plan	Rectangular: massed		
	Style	No Style	— Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	— Roof	
ACRES CONTRACTOR		Front gable	Alterations	
Priority High Medium V Low	Exterior Materials	Vinyl	Addition(s)	
	Address	119 Coats		
	Date	1940		Alterations/Modifications
A A A A A A A A A A A A A A A A A A A	Current Use	Residence		
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Irregular		
	Style	No Style	— Doors	
	-	1		Porch enclosed w/plywood
	No. of Stories	I		
		Wood frame	Roof	
	No. of Stories Structural System Roof	Wood frame	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Structural System			

	Address	124 Coats		
ALL AND THE REAL	Date	1935		Alterations/Modifications
Why Allow	Current Use	Residence		
	Property Type	Domestic: single-family		Plywood panel added to exterior walls
	Plan	Rectangular: massed		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Hipped	Alterations	
Priority 🗌 High 🗌 Medium ✔ Lo	w Exterior Materials	Plywood panel; Wood	Addition(s)	
	Address	303 N. College		
And all and a second	Date	1945		Alterations/Modifications
Contraction of the second second	Current Use	Commercial		
Beccherger	Property Type	Commercial	Ext. Materials	
	Plan	Rectangular: massed		
	Style	No Style		Original doors replaced
Last Constant	No. of Stories	1	Porch	
and the second	Structural System	Load-bearing masonry	Roof	
	Roof	Front gable	Alterations	
Priority 🗌 High 🗌 Medium ✔ Lo	w Exterior Materials	Brick	Addition(s)	
· - •			L	
	Address	823 S. College		
	Date	1930		Alterations/Modifications
	Current Use	Residence		
A second and the second second	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos & vinyl
	Plan	Bungalow		
	Style	No Style	Doors	
	No. of Stories	1		Original porch posts and flooring replaced
	Structural System	Wood frame	Roof	
and the second state of the second states	Roof	Front gable	Alterations	
Priority 🗌 High 🗌 Medium ✔ Lo	w Exterior Materials	Asbestos; Vinyl	Addition(s)	
the states of th	Address	110 Cook		
	Date	1942		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan	Gable-Front-and Wing		
	Style	No Style	Doors	
	No. of Stories	1	Porch Roof	Porch support replaced
	Structural System	Wood frame		
	Roof	Cross gable	Alterations Addition(s)	
Priority High Medium 🖌 Lo	w Exterior Materials	Wood	Addition(s)	
	Address	201 E. Criddle		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	:
	Property Type	Domestic: single-family		
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority High Medium 🖌 Lo	w Exterior Materials	Vinyl	Addition(3)	

	Address	208 Cynisca		
	Date	1936	-	Alterations/Modifications
The second se	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad
	Plan	Bungalow	– Windows – Doors	Original windows replaced
	Style	No Style		Original porch supports replaced
	No. of Stories	1	- Roof	
	Structural System	Wood frame	- Alterations	
	Roof	Front gable	- Addition(s)	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Vinyl; Particle Board	Addition(3)	
7780474448788247465882474658244472667467				
	Address	407 Cynisca		
	Date	1940	_	Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls clad w/incompatible materials
	Property Type	Domestic: single-family		Porch partially enclosed
	Plan	Bungalow	– Doors	
	Style	No Style	- Porch	
	No. of Stories	1	- Roof	
and a second second	Structural System	Wood frame	– Roor – Alterations	
and the second	Roof	Front gable	– Addition(s)	
Priority 🗌 High 🗌 Medium 🖌 Low	Exterior Materials	Brick; Plywood; Stucco	- Addition(s)	
	Address	415 Cynisca		
	Date	1925	_	Alterations/Modifications
And the second sec	Current Use	Residence	Ext Matorials	Exterior walls partially re-clad
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Bungalow	– Windows – Doors	
	Style	No Style		Shingles added to front gable end
	No. of Stories	1	– Porch – Roof	
	Structural System	Wood frame	– Roor – Alterations	
	Roof	Front gable	– Anterations – Addition(s)	
Priority 🗌 High 🗌 Medium 🖌 Low	Exterior Materials	Wood;Vinyl		
	Address	302 Dewberry		
	Date	1920	_	Alterations/Modifications
	Current Use	Residence	– Ext. Materials	
	Property Type	Domestic: single-family	- Windows	
	Plan	Bungalow	– Doors	
	Style	Craftsman	– Porch	
	No. of Stories	1	- Roof	
	Structural System	Wood frame	– Alterations	
	Roof	Front gable	 Addition(s) 	
<i>Priority</i>	Exterior Materials	Wood	Addition(5)	
	Address	606 Dunaway		
	Date	1920	_	Alterations/Modifications
	Current Use	Residence	- Ext Materials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family	- Windows	
	Plan	Rectangular: massed	– Doors	
	Style	National Folk	– Porch	
	No. of Stories	1	– Porch – Roof	
	Structural System	Wood frame	– Roor – Alterations	
2 3 148	Roof	Hipped		
<i>Priority</i> ☐ High	Exterior Materials	Vinyl	 Addition(s) 	
		•		

	Address	204 Dunlap		
	Date	1945		Alterations/Modifications
	Current Use	Residence	Evt Matorials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Gable-Front-and Wing	— Doors	
	Style	No Style		One porch support replaced
	No. of Stories	1		
and the second se	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority 🗌 High 🗌 Medium 🔽 Low	Exterior Materials	Vinyl		
	Address	300 Dunn		
	Date	1940		
the second s	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	
	Plan	Gable-Front-and Wing		
	Style	No Style	— Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	— Alterations	
<i>Priority</i>	Exterior Materials	Vinyl	— Addition(s)	
	Address	308 Dunn		
	Date	0		Alterations/Modifications
A THE WAY AND		Residence	Ext. Materials	
	Property Type	Domestic: multiple-family		
	Plan	L-Plan	- Doors	
	Style	No Style	- Porch	
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Front gable	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Asbestos		
	Address	312 Dunn		
the second second	Date	1945		
		Residence		Alterations/Modifications
		Domestic: multiple-family	Ext. Materials	
		Rectangular: massed		
	Style	No Style	— Doors	
	No. of Stories	1	Porch	
and the second sec	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority 🗌 High 📄 Medium 🖌 Low	Exterior Materials	Wood	Addition(s)	
PACE PACE	Address	410 Dunn		
LANCE AND AND AND A	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	· · · · · · · · · · · · · · · · · · ·
		Domestic: single-family		
		Rectangular: massed	— Doors	
	Style	No Style	Porch	
	No. of Stories	1 Weed from a		
	Structural System	Wood frame	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Root Exterior Materials	Side gable Vinyl	Addition(s)	
<i>Priority</i> High Medium ✔ Low		<u>viiiyi</u>		

	Address	412 Dunn		
aller / ste	Date	1940		Alterations/Modifications
Carlos	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed		
	Style	No Style		
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	·
Priority 🗌 High 🔄 Medium 🗹 Low	Exterior Materials	Wood		
A.4.				
4	Address	301 -303 S. Elm		
	Date Current Use	1935		Alterations/Modifications
THEN BE	Current Use	Commercial	Ext. Materials	Exterior walls re-clad w/plywood paneling
	Property Type	Commercial	Windows	
	Plan Style	Rectangular: massed No Style	Doors	
	No. of Stories	1	Porch	
and the second	Structural System	Load-bearing masonry	Roof	
	Roof	Flat	— Alterations	
Priority 🗌 High 🔄 Medium ✔ Low	Exterior Materials	Brick: Plywood Panel	Addition(s)	
	Address	117 Emanuel		
	Date	1940		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Bungalow		Window openings added,all original window
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame		
	Roof	Front gable; Shed	Alterations Addition(s)	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address	228 Emanuel		
A CONTRACTOR OF A CONTRACTOR	Date	1945		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family		
	Plan	Gable-Front-and Wing	Doors	
	Style	No Style	Porch	
		1 Wood from a		
and the second se	Structural System	Wood frame	Alterations	
Priority High Medium 🗸 Low	Roof Exterior Materials	Cross gable Wood	Addition(s)	
Priority High Medium V Low				
	Address	230 Emanuel		
	Date	1945		··· ·· ·· ·· ·· ··
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Gable-Front-and Wing		Original windows replaced
	Style	No Style	Doors	
	-	1	Porch	
	Structural System	Wood frame	Roof	
and the second	Roof	Cross gable	Alterations	
Priority 🗌 High 🔄 Medium ✔ Low	Exterior Materials	Asbestos Shingles	Addition(s)	
· - ·			L	

	Address	208 Farley		
	Date	1920		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
and the second second second second second	Roof	Hipped	Alterations	
Priority ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
······································				
	Address	200 Floyd		
	Date	1944		Alterations/Modifications
	Current Use	Residence; Shed		
	Property Type	Domestic: single-family	Ext. Materials	Exterior walls re-clad
	Plan	Irregular	Windows	
	Style	Tudor Revival	Doors	
	No. of Stories	1	Porch	
A COMPANY & Lot COM Description	Structural System	Wood frame	Roof	
and a second	Roof	Cross gable	Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Asbestos Shingles; Plywood Panel	Addition(s)	
	Address	204 Floyd		
	Date	1935		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Property Type Plan	Bungalow	Windows	
			Doors	
	Style	No Style	Porch	
and the second se	No. of Stories	1	Roof	
the second se	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority High Medium ⊻ Low	Exterior Materials	Wood		
the state of the state of the state	Address	208 Floyd		
	Date	1942		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Plan	Irregular	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
208	•	Side gable	Alterations	
Prinsite Ulish Medium Cham			Addition(s)	Side wings added
Priority High Medium 🖌 Low	Exterior Materials	Vinyl		
	Address	100 Floyd		
	Address Date	408 Floyd 1935		
				Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior wall re-clad w/asbestos shingles
	Property Type	Domestic: single-family	Windows	most original windows replaced
	Plan	Bungalow	Doors	
	Style	Craftsman	Porch	Porch posts replaced
and the second sec	No. of Stories	1	Roof	
and the second second second second	Structural System	Wood frame	Alterations	
		Front gable	Addition(s)	Rear carport addition
Priority High Medium 🖌 Low	Exterior Materials	Asbestos Shingles		· · · · · · · · · · · · · · · · · · ·

	Address	401 FM 664		
	Date	1920		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Ext. Wateriars Windows	
	Plan	Rectangular: massed	Doors	
and the second se	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
		Hipped	Addition(s)	
<i>Priority</i> High ✔ Medium Low	Exterior Materials	Wood		
South Sec				
and the second sec	Address	513 FM 664		
A CONTRACTOR OF	Date	1925		Alterations/Modifications
	Current Use	Vacant	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan Style	Bungalow	Doors	
	No. of Stories	No Style	Porch	Porch enclosed
	Structural System	Wood frame	Roof	
The second with the first	Roof	Front gable; Shed	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood; Corrugated metal panel	Addition(s)	Side shed-roof metal-clad addition
	Address	601 FM 664		
A Contraction	Date	1900		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Modified L-Plan		Original windows replaced
	Style	Folk Victorian	Doors	
	No. of Stories	1	Porch	
and the second se	Structural System	Wood frame	Roof	
	Roof	Complex (Cross Gable; Hipped; She	Alterations Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	2901 FM 813		
	Date	1945		Alterations/Modifications
A CARLEY AND A CAR	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Bungalow	Doors	• ·
	Style	No Style	Porch	
	No. of Stories	1 Wood frame	Roof	
	Structural System	Wood frame	Alterations	
Priority High Medium V Low	Roof Exterior Materials	Complex (Cross gable; Hipped) Wood	Addition(s)	Rear addition
	Address	? FM 875		
	Date	1920		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
Past in the	Plan	Rectangular: massed		6/6 windows added
	Style	No Style	Doors	
	No. of Stories	1		Original porch supports replaced, new entry
	Structural System	Wood frame	Roof	
	-	Hipped	Alterations	
Priority High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	Carport
			·	

	Address	? FM 875		
	Date	1920		Alterations/Modifications
	Current Use	Vacant	Ext Motoriala	
	Property Type	Agricultural	Ext. Materials	
	Plan	Rectangular: massed		
ALL RANGE AND A REAL PROPERTY OF	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
South Contraction of the little	Roof	Gable-on-hip	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	
	Address	180 FM 875		
	Date	1935		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
Contraction of the second s	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Exterior Materials	Brick	Addition(s)	
			L	
	Address	514 ? FM 875		
	Date	1910		••••••••••••••••••••••••••••••••••••••
the second secon	Current Use	Religious		Alterations/Modifications
	Property Type	Religious	Ext. Materials	Exterior walls re-clad with vinyl siding
	Plan	Irregular	Windows	Aluminum-frame units added
	Style	No Style	Doors	Original primary entry doors replaced
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	•
	Roof		Alterations	
Priority High Medium ✔ Low	Exterior Materials	Hipped Vinyl	Addition(s)	1
		<u></u>		
	Address	1752 FM 875		
	Date	1752 FM 875 1915		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	1
and the second sec		Modified L-Plan	Windows	
			Doors	
	Style	Tudor Revival	Porch	Porch added c. 1925
	No. of Stories	1 Wood framo	Roof	-
and the second of the second sec	Structural System Roof	Wood frame Cross gable, Hipped	Alterations	
Drievity Uligh I Madium Ulaw			Addition(s)	
Priority High 🖌 Medium Low	Exterior Materials	Wood		
	A alalwa	5100 EM 975		
	Address	5120 FM 875		
	Date	1945		Alterations/Modifications
The second se	Current Use	Commercial	Ext. Materials	1
	Property Type	Domestic: single-family	Windows	Window openings partially infilled w/plywood
	Plan	Rectangular: massed		Door opening infilled w/plywood panel
	Style	Vernacular	Porch	
	No. of Stories	1		-
Contraction of the second seco	Structural System	Wood frame	Alterations	
	Roof	•	Addition(s)	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Stone; Wood		

Order 14/3 Atteraions/Modifications Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Ext. Materials Findry Light of the logic order Ext. Materials Materials Findry Light of the logic order Ext. Materials Materials Findry Light of the logic order Ext. Materials Materials Findry Light of the logic order Ext. Materials Materials Findry Light of the logic order Ext. Materials Materials Find		Address	5125 ? FM 875		
Property Type Connexts: single-family Ext. Materials Priority High Madium Low Doors Priority High Madium Low Address		Date	1945		Alterations/Modifications
Proget 7 ype Domatic: single-family Windows Priority 1 High 2 Medium 1 Low Strice 1 (ad-backing massed) Doors Priorit Priority 1 High 2 Medium 1 Low Exterior Materials Store Address 510/6 Californian Priority 1 High 2 Medium 1 Low Exterior Materials Store Address 510/6 Californian Priority 1 High 2 Medium 1 Low Exterior Materials Store Exterior Materials Store Priority 1 High 2 Medium 1 Low Exterior Materials Store Exterior Materials Store Priority 1 High 2 Medium 1 Low Exterior Materials Store Exterior Materials Store Priority 1 High 2 Medium 1 Low Exterior Materials Store Internet Store Address Store Internet Store Priority 1 High 2 Medium 1 Low Exterior Materials Store Internet Store Exterior Materials Store Priority 1 High 2 Medium 2 Low Exterior Materials Store Internet Store Exterior Materials Store Priority 1 High 1 Medium 2 Low Exterior Materials Store Store Exterior Materials Store Priority 1 High 1 Medium 2 Low Exterior Materis Store Store </th <th></th> <th>Current Use</th> <th>Residence</th> <th>Ext Matorials</th> <th></th>		Current Use	Residence	Ext Matorials	
Pian Reclangular massad Doors Pior Nr No. of Stories 1 Structural System No. of Stories Address Priority High Madum Low Address 540 Ends Store Priority High Madum Low Priority High Madum Low Priority High Madum Low Priority High Madum Correct Los		Property Type			
Skyle Calabraian Parch Rod of Stories 1 Priority' High Medium Low Low-basing masony Priority' High Medium Low Store Priority' High Medium Low Address Store Priority' High Medium Low Store Address Store Priority' High Medium Low Store Address Store Priority' High Medium Low Store Address Store Priority' High Medium Low Residence Priority High Address Store Priority' High Medium Low Residence Priority High Address Store High Address Store High Address Store High Address Store<		Plan			
No. of Stories 1 Structure System Address 140 FM 275 Address 540 FM 275 Address 540 FM 275 Address 540 FM 275 Address 520 FM 275 Priority High Medium Low Recircingular: linear Boots Structural System Kodfress 520 FM 275 Address 520 FM 275 Address 520 FM 275 Doors Address 520 FM 275 Current Use Recidingular: mascad Boors Address 520 FM 275 Current Use Recidingular: mascad Boors Address 520 FM 275 Date Date 15 Structural System Moddres Address 537 FM 275 Date Date 150 Structural System Modd 700 Address 537 FM 275 Date 1940 Current Use		Style	Craftsman		
Priority High Medium Ladd-beating massiny Alterations Priority High Medium Low Address Status Priority High Medium Low Address Status Address Priority High Medium Low Address Status Extend Materials Priority High Medium Low Address Status Extend Materials Priority High Medium Low Address Status Extend Materials Priority High Medium Low Address Status Extend Materials Medium Extend Materials Medium Extend Materials Medium Address Status Extend Materials Medium Medium Extend Materials Medium Medium Extend Materials Medium Medium <t< th=""><th></th><th></th><th></th><th></th><th></th></t<>					
Priority High Medium Low Exterior Materials Sone Priority High Medium Low Address Sine Address Sine Address Sine Sine Address Sine Address Sine Address Sine Sine Sine Address Sine Address Sine Address Sine Microson Congonal windows replaced wit/S units Doors Ext. Materials Doors Proch Priority High Medium Low Exterior Materials Mood frame Address Side pable Priority High Medium Low Address Side pable Address Side pable Priority High Medium Low Address Side pable Address Side pable Priority High Medium Low Address Side pable Address Side pable Priority High Medium Low Address Side pable Address Side pable Priority High Medium Low <th></th> <th>-</th> <th></th> <th></th> <th></th>		-			
Priority High Medium Low Exterior Materials Stone Image: State				Addition(s)	
Date 1900 Alterations/Modifications Current Use Residence For Marrials Priority Hgh Medua Dors Priority Hgh Medua Cors Priority Hgh Medua Low Address 5265 FM 875 Estairce Property Cornent Use Residence Property Property Cornent Use Structural System Nood fame Roof Cornet Estairce Haladia: Windows Cornet Estairce Proper ty Type Dere	Priority High ✔ Medium Low	Exterior Materials	Stone		
Date 1900 Alterations/Modifications Current Use Residence For Marrials Priority Hgh Medua Dors Priority Hgh Medua Cors Priority Hgh Medua Low Address 5265 FM 875 Estairce Property Cornent Use Residence Property Property Cornent Use Structural System Nood fame Roof Cornet Estairce Haladia: Windows Cornet Estairce Proper ty Type Dere		A dalama a	5440 EN 075		
Current Use Residence Property Type Domestic: single-family Priority High Priority High </th <th>State of the second second second</th> <th></th> <th></th> <th></th> <th></th>	State of the second second second				
Property Type Domestic: single-family Mindows Doors Priority High Redraguiar linear Mindows Original windows replaced wi6i6 units Priority High Mindows Style No. of Stories Mindows Priority Priority High Mindows Style No. of Stories Mindows Priority Priority High Mindows Current Us Residence Priority Address S266 FM 875 Date 1915 Current Us Residence Priority Priority Priority Mindows Address S266 FM 875 Date Priority Priority Priority Mindows Address S266 FM 875 Date Priority					Alterations/Modifications
Pinn Rectangular: linear Dors Style No. Style Porch No. of Stories Stuctural System Wood frame Root Stuctural System Wood frame Root Stide gable Address Structural System Wood frame Address Structural System Structural System Mood Priority High Medium Low Address S266 FM 875 Exterior Materials Doors Fromerty System Breatangular: Imased Doors Fromerty System No Syle No. of Stories Structural System Wood frame Rood Current Use Fromerty System Mood frame Rood Structural System Wood frame Address Structural System Structural System Wood frame Address Structural System Structural System Wood Mood Protrity				Ext. Materials	
Style No. 5/Style Parch No. of Stories 1 Broot Priority High Medum Low Attentions Stde gable Attentions Attentions Stde gable Attentions Attentions Attentions Attentions Attentions Stde gable Attentions Attentions Attentions Attentions Attentions Stde final 375 Attentions Attentions Attentions Attentions Attentions Attentions Attentions Priority High Medum Low Attentions Priority High Medum Low Structural System Priority High Medum Low Structural System Proch Root Stories Structural System Proch Root Attentions Structural System Wood frame Attentions Priority High Medum Low Structural System Proch Root Stories Structural System Proch Root <				Windows	Original windows replaced w/6/6 units
No. of Stories 1 Prich Structural System Wood frame Roof Roof Alterations Address Structural System Wood Address S266 FM 875 Date 1915 Alterations/Modifications Priority High Medium Low Address Structural System S266 FM 875 Date 1915 Current Use Residence Dorssit: single-family Windows replaced Priority High No. of Stories 15 Alterations/Modifications Priority High Modum Low Kord Complex Priority High Medum Low Structural System Wood frame Roof Complex Address Structural System No. of Stories Priority High Medum Low Address Structural System No. of Stories 1.5 Structural System Wood Address Priority High Medium Low Address Structural System No. Structural System No. of Stories				Doors	
Structural System Wood frame Rod Priority High Medium Low Side gable Atterations Addition(s) Addition(s) Atterations Addition(s) Addition(s) Atterations Addition(s) Atterations Address S266 FM 875 Atterations/Modifications Atterations/Modifications Address S266 FM 875 Date Donestic: single-family Windows replaced Priority High Medium Low Address S270 FM 875 Priority High Medium Low Address S379 FM 875 Date Barg Complex Address S379 FM 875 Date Date Donestic: single-family Mindows Address S379 FM 875 Date Date Date Date Donestic: single-family Mindows Donestic: single-family Priority High Medium Low Address S379 FM 875 Atterations/Modifications Property Type Donestic: single-family Mindows Donestic: single-family Mindows Donestic: single-family <		•		Porch	
Roof Side gable Address Priority High Medium Low Exterior Materials Wood Address 5266 FM 875 Date 1915 Atterations/Modifications Current Use Residence Proirity Proirit				Roof	
Priority High Medium Low Exterior Materials Wood Addition(s) Addition(s) Addition(s) Addition(s) Addition(s) Date	The second s	-			
Address 5266 FM 875 Date 1915 Current Use Residence Property Type Domestic: single-family Pin Retangular: massed Style Style No. 61 Stories Structural System Wood frame Roof Complex Address 5379 FM 875 Date 1940 Address 5379 FM 875 Date 1940 Current Use Vood Address 5379 FM 875 Date 1940 Current Use Vood Address 5379 FM 875 Date 1940 Current Use Vacant Property Type Domestic: single-family Plan Bungalow Style No. 61 Stories 1 Structural System Wood frame Roof Front gable Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Plan Bungalow Style	Priority High 🖌 Medium 🗌 Low		•	Addition(s)	
Date 1915 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Priority High No. of Stories 15 Structural System Priority High Medium Low Address 5379 FM 875 Date 1940 Alterations/Modifications Address Address 5379 FM 875 Address Structural System Date 1940 Alterations/Modifications Current Use Vacant Property Type Domestic: single-family Plan Bungalow Style No. of Style No. of Style Porch No. of Style No. of Style Porch No. of Style Property Type Domestic: single-family Windows Ext. Materials Windows Property Type Domestic: single-family Property Type Domestic: single-family Bord Priority High Medium Low Style No. of Stories 1 Property Type Domestic: single-family Style No. of Stories 1 Style No. of Stories	, _ ,			L	
Current Use Residence Interactions/Modifications Property Type Domestic: single-family Plan Priority High Medium Low Priority High Medium Low Address 53/9 FM 875 Rectangular: massed Porch Address 53/9 FM 875 Darestic: single-family Priority High Medium Low Address 53/9 FM 875 Darestic: single-family Priority High Medium Address Style No. of Stories 1 Structural System Mood Priority High Medium Dow Address S3/9 FM 875 Date 1940 Atterations/Modifications Ext. Materials Windows Domestic: single-family Pha Burgalow Dorrit No. of Stories 1 Structural System Wood Priority High Medium Low Exterior Materials Wood Priority High Medium Low Exterior family Pha Priority High Medium<		Address	5266 FM 875		
Current Use Residence Priority File Domstic: single-family Priority High No. of Stories 1.5 Structural System Wood frame Roof Roof Complex Address Address 5379 FM 875 Address Darett: single-family High Medium Low Address 5379 FM 875 Address Darett: single-family High Has an historic rear addition Priority High Medium Current Use Vacant Vacant Proch Priority High Medium No. of Stories No. of Stories 1 Structural System No. of Stories 1 Structural System Priority High Medium No. of Stories Priority High Medium No. of Stories Roof Fond gable Exterior Materials Windows Current Use Residence Priority High Medium No. of Stories Priority High Medium Ext. Materia		Date	1915		Alterations/Modifications
Property Type Domestic: single-family Windows Original windows replaced Bit Rectangular: massed Doors Porch Structural System Wood frame Address System Priority High Medium Low Exterior Materials Mod Address 5379 FM 875 Address Address Address Bungalow Doors Exterior Materials Mod Address Property Type Domestic: single-family Mindows Mindows Ext. Windows Materials Wood Address Structural System Address Bungalow Doors Porch Porch enclosed Roof Priority High Medium Low Style No Style Porch Priority High Medium Low Exterior Materials Wood frame Atterations Priority High Medium Low Exterior Materials Wood Boors Bungalow Structural System Wood frame Roof Atterations Priority High Med		Current Use	Residence	Fort Motorials	
Plan Rectangular: massed No. Style No. Style No. of Stories 1.5 Structural System Wood frame Roof Complex Address 5379 FM 875 Date Structural System Viacant Vacant Current Use Vacant Property Type Doors Domestic: single-family Windows Doors Atterations/Modifications Exterior Materials Wood No. of Stories 1 Roof Atterations/Modifications Priority High Medium No. of Stories 1 Structural System Wood Viacont Exterior Materials Viacont Exterior Materials Viacont Exterior Materials Viacont Yood frame Pronch Porch enclosed No. of Stories 1 Roof Structural System Wood Property Type Danestic: single-family Mindows Daors Style Dors		Property Type	Domestic: single-family		
Style No. style No. of Stories 1.5 Structural System Wood frame Roof Complex Address 5379 FM 875 Date 1940 Address 5379 FM 875 Date 1940 Current Use Vacant Property Type Domestic: single-family Bungalow Doors No. of Stories 1 Style No Style Priority High Medium Low Address 5329 FM 875 Date 1940 Current Use Vacant Bungalow Doorsetic: single-family No. of Stories 1 Style No Style No. of Stories 1 Structural System Wood frame Roof Atterations Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Priority High Medium Low Address 4520 FM 877 Date<		Plan	Rectangular: massed		
No. of Stories 1.5 Roof Priority High Medium Low Kood frame Address 5379 FM 875 Address Address Date 1940 Atterations/Modifications Current Use Vacant Dorestic: single-family Piority High Medium Low Property Type Domestic: single-family Windows Dores Structural System Wood frame Roof Address 5379 FM 875 Date 1940 Atterations/Modifications Property Type Domestic: single-family Windows Dores 1 Structural System No. of Stories Structural System Wood frame Rectangular: linear Property Type Domestic: single-family Address Address 4520 FM 877 Address Property Type Domestic: single-family Kindows Property Type Domestic: single-family Address Mood frame Rectangular: linear Doors Property Type Domestic: single-family Kindows <t< th=""><th></th><th>Style</th><th>No Style</th><th></th><th></th></t<>		Style	No Style		
Structural System Wood frame Roof Complex Alterations Addition(s) High Medium Low Address 5379 FM 875 Date 1940 Current Use Vacant Property Type Domestic: single-family Windows Doors Property Type Nos of Stories Structural System Wood frame Roof Frong gable Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Address Structural System Wood No. of Stories 1 Structural System Wood Roof Front gable Atterations Address Structural System Wood No. of Stories 1 Browney Low Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family	the second se		1.5		
Priority High Medium Low Exterior Materials Wood Addition(s) Has an historic rear addition Priority High Medium Low Address 5379 FM 875 Address 5379 FM 875 Date 1940 Adterations/Modifications Alterations/Modifications Current Use Vacant Vacant Ext. Materials Windows Property Type Domestic: single-family Bungalow Doors Porch Porch enclosed No. of Stories 1 Structural System Wood Roof Alterations. Addition(s) Priority High Medium Low Exterior Materials Wood Nood Address 4ddress 4520 FM 877 Date 1900 Alterations/Modifications Ext. Materials Exterior walls re-clad w/vinyl siding Vindows Property Type Domestic: single-family Porch Roof Address Doors Property Type Domestic: single-family Plan Recitangular: linear Stories Structural System No. of Stories Structural System Nood fame No.	A REAL PROPERTY AND A REAL	Structural System			
Priority High Medium Low Exterior Materials Wood Address 5379 FM 875 Date 1940 Alterations/Modifications Current Use Vacant Domestic: single-family Mindows Doors Property Type Domestic: single-family No. of Stories 1 Structural System Doors No. of Stories 1 Structural System Wood frame Alterations Alterations Address 4520 FM 877 Exterior Materials Vood Alterations/Modifications Address 4520 FM 877 Date 1900 Alterations/Modifications Current Use Residence Property Type Doors Ext. Materials Ext. Materials Vood No. of Stories 1.5 Structural System No. of Stories 5.5 Proch No. of Stories 1.5 Structural System Nood frame Alterations Doors Proch No. of Stories 1.5 Structural System Nood frame Alterations Addition(s) Side gable Side gable Side gable Alterations			Complex		
Date 1940 Current Use Vacant Property Type Domestic: single-family Bungalow Style No. of Stories 1 Structural System Wood frame Roof Atterations Address 4520 FM 877 Date 1900 Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Doors Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Ext. Materials Ext. Materials Exterior walls re-clad w/vinyl siding Windows Doors Property Type Domestic: single-family Windows Style Polk Victorian Porch No. of Stories 1.5 Structural System Wood frame Roof Side gable	<i>Priority</i> High ✔ Medium Low	Exterior Materials	Wood		
Date 1940 Current Use Vacant Property Type Domestic: single-family Bungalow Style No. of Stories 1 Structural System Wood frame Roof Atterations Address 4520 FM 877 Date 1900 Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Doors Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Ext. Materials Ext. Materials Exterior walls re-clad w/vinyl siding Windows Doors Property Type Domestic: single-family Windows Style Polk Victorian Porch No. of Stories 1.5 Structural System Wood frame Roof Side gable			5070 EN 075		
Current Use Vacant Anter allohis/modifications Property Type Domestic: single-family Bungalow No Style No Style Doors Priority High Medium Low Address 4520 FM 877 Date 1900 Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Exterior Materials Wood faine Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Exterior walls re-clad w/vinyl siding Windows Doors Style 1.5 No. of Stories 1.5 Structural System Wood frame Roof Alterations Address 1.5 Style Folk Victorian Roof Side gable					
Property Type Domestic: single-family Ext. Materials Bungalow No Style Doors No. of Stories 1 Porch Porch enclosed Structural System Wood frame Roof Priority High Medium Low Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Exterior walls re-clad w/vinyl siding Windows Style Folk Victorian No. of Stories Style Folk Victorian No. of Stories 1.5 Structural System Wood frame No. of Stories 1.5 Structural System Wood frame No. of Stories 1.5 Structural System Wood frame Roof Stide gable					Alterations/Modifications
Plan Bungalow Doors Style No Style Doors Priority High Medium ✓ Low Address 4520 FM 877 Date 1900 Current Use Residence Property Type Doors Property Type Domestic: single-family Windows Windows Style Folk Victorian No. of Stories 1.5 Style Folk Victorian No. of Stories 1.5 Structural System Wood frame Alterations/Modifications Exterior walls re-clad w/vinyl siding Windows Doors Porch Porch Property Type Domestic: single-family Windows Doors Doors I.5 Structural System Wood frame Roof Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alteration				Ext. Materials	
Style No Style Doors No. of Stories 1 Porch Porch enclosed Structural System Wood frame Alterations Alterations Priority High Medium Low Exterior Materials Wood Address 4520 FM 877 Date 1900 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Exterior walls re-clad w/vinyl siding Plan Rectangular: linear Doors Doors Doors Style Folk Victorian Porch Porch No. of Stories 1.5 Wood frame Doors Style Folk Victorian Porch Roof Alterations Style Interational (Interations) Doors Alterations Style Folk Victorian Doors Doors No. of Stories 1.5 Wood frame No of Stories Alterations Stide gable Side gable Alterations Alterations				Windows	
No. of Stories 1 Porch Porch enclosed Structural System Wood frame Alterations Priority High Medium Low Exterior Materials Wood Wood Wood Addition(s) Address 4520 FM 877 Addition(s) Addition(s) Date 1900 Exterior Materials Exterior Materials Vood Date 1900 Exterior walls re-clad w/vinyl siding Current Use Residence Ext. Materials Exterior walls re-clad w/vinyl siding Plan Rectangular: linear Doors Doors Style Folk Victorian No. of Stories 1.5 Structural System Wood frame Alterations Side gable Addrition(s) Addition(s)				Doors	
Structural System Wood frame Alterations Priority High Medium Low Exterior Materials Wood Address 4520 FM 877 Address 4520 FM 877 Date 1900 Alterations/Modifications Current Use Residence Exterior walls re-clad w/vinyl siding Property Type Domestic: single-family Windows Plan Rectangular: linear Doors Style Folk Victorian Porch No. of Stories 1.5 Roof Structural System Wood frame Alterations Roof Side gable Alterations		-			
Roof Front gable Alterations Priority High Medium Low Exterior Materials Wood Addition(s) Address 4520 FM 877 Date 1900 Alterations/Modifications Date 1900 Exterior Materials Exterior walls re-clad w/vinyl siding Property Type Domestic: single-family Windows Exterior walls re-clad w/vinyl siding Plan Rectangular: linear Folk Victorian Porch No. of Stories 1.5 Porch Roof Structural System Wood frame Alterations Alterations Roof Side gable Alterations Addition(s)					
Priority High Medium Low Exterior Materials Wood Addition(s) Address 4520 FM 877 1900 1900 Alterations/Modifications Date 1900 Residence Ext. Materials Exterior walls re-clad w/vinyl siding Property Type Domestic: single-family Windows Doors Doors Plan Rectangular: linear Doors Doors Porch No. of Stories 1.5 Wood frame Noof Alterations Structural System Wood frame Side gable Alterations Alterations		•			
Address 4520 FM 877 Date 1900 Current Use Residence Property Type Domestic: single-family Windows Ext. Materials Exterior walls re-clad w/vinyl siding Vindows Doors Plan Rectangular: linear Doors No. of Stories 1.5 Porch Style Folk Victorian Porch No. of Stories 1.5 Roof Structural System Wood frame Alterations Roof Alterations Address Address	Priority High Medium V Low			Addition(s)	
Date 1900 Alterations/Modifications Current Use Residence Ext. Materials Exterior walls re-clad w/vinyl siding Property Type Domestic: single-family Windows Plan Folk Victorian Doors Style Folk Victorian Porch No. of Stories 1.5 Wood frame Structural System Side gable Alterations/Modifications	, _ ,			L	
Current Use Residence Property Type Domestic: single-family Plan Rectangular: linear Style Folk Victorian No. of Stories 1.5 Structural System Wood frame Roof Alterations Addition(s)		Address	4520 FM 877		
Current Use Residence Property Type Domestic: single-family Plan Rectangular: linear Style Folk Victorian No. of Stories 1.5 Structural System Wood frame Roof Alterations Addition(s) Addition(s)		Date	1900		Alterations/Modifications
Property Type Domestic: single-tamily Windows Plan Rectangular: linear Doors Style Folk Victorian Doors No. of Stories 1.5 Porch Structural System Wood frame Alterations Roof Side gable Addition(s)		Current Use	Residence	Ext Motoriala	
Plan Rectangular: linear Style Folk Victorian No. of Stories 1.5 Structural System Wood frame Roof Alterations Addition(s)		Property Type	Domestic: single-family		
Style Folk Victorian No. of Stories 1.5 Structural System Wood frame Roof Alterations Alterations Addition(s)		Plan	Rectangular: linear		
No. of Stories 1.5 Structural System Wood frame Roof Alterations Side gable Addition(s)		Style	Folk Victorian		
Structural System Wood frame Alterations Roof Side gable Addition(s)			1.5		
Roof Side gable Addition(s)					
Priority High 🖌 Medium 🗌 Low Exterior Materials Vinyl					
· · · · · · · · · · · · · · · · · · ·	Priority 🔄 High 🖌 Medium 📋 Low	Exterior Materials	Vinyl		

	Address	? FM 878 (Palmer Road)		
	Date	1930		Alterations/Modifications
	Current Use	Vacant	Ext. Materials	
	Property Type	Unknown		Windows removed
	Plan	Rectangular: massed		Doors removed
	Style	No Style	– Porch	
	No. of Stories	1		Missing
	Structural System	Load-bearing masonry	- Alterations	
	Roof	Flat	- Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Stucco; Brick		
and the second	Address	1931 FM 878 (Palmer Road)		
	Date	<u>1910</u>	_	Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	— Windows	
	Plan	Rectangular: massed	— Doors	
and the second provide the second	Style	No Style	— Porch	Porch partially infilled, porch posts changed
and the second second	No. of Stories	1 Wood frame	— Roof	
The second second second	Structural System Roof	Front/Side Gable	- Alterations	
Priority Ulinh Madium Ulaw	Roor Exterior Materials	Wood	— Addition(s)	
Priority High 🖌 Medium Low		woou		
	Address	FM 879 (Boyce Road)		
and the second second	Date	1910		
A CONTRACTOR OF THE REAL OF TH	Current Use	Residence	_	Alterations/Modifications
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Rectangular: massed	— Windows	
	Style	No Style	— Doors	
	No. of Stories	1	– Porch	
and the second	Structural System	Wood frame	- Roof	
	Roof	Hipped; Shed - rear	 Alterations 	
<i>Priority</i>	Exterior Materials	Wood	— Addition(s)	
	Address	835 FM 879 (Boyce Road)		
States and states of the	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Bungalow	— Doors	<u> </u>
	Style	Craftsman	- Porch	
	No. of Stories	1	- Roof	
	Structural System	Wood frame	- Alterations	
	Roof	0	- Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Wood		
	Address	640 NL Cibeen		
· A set of the set of the set	Address Date	612 N. Gibson 1942		
	Date Current Use	Residence	— <u> </u>	Alterations/Modifications
and the second	Property Type	Domestic: single-family	Ext. Materials	
	Property Type Plan	Rectangular: massed	— Windows	
	Style	No Style	— Doors	
	No. of Stories	1	— Porch	
	Structural System	Wood frame	— Roof	
and the second se	Roof		— Alterations	
Priority ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	— Addition(s)	

A PART AND A PART	Address	728 N. Gibson		
	Date	1944		Alterations/Modifications
	Current Use	Residence	Fort Materials	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular	Windows	
	Style	No Style	Doors	
	No. of Stories	2	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
	Address	731 N. Gibson		
	Date	1942		Alterations/Modifications
IEI	Current Use	Residence	Ext Matariala	
	Property Type	Domestic: multiple-family - Duplex		Exterior walls re-clad w/vinyl siding
	Plan	Bungalow	Windows	
	Style	No Style	Doors	
	No. of Stories	1		Porch posts replaced
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> High Medium	Exterior Materials	Vinyl	Addition(s)	Has a large rear addition
	Address	712 Givens		
	Date	1920		Alterations/Modifications
	Current Use	Residence	Fort Materials	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular		Some windows boarded-up w/plywood
	Style	No Style	Doors	
	No. of Stories	1		Front façade porch has been enclosed
and a state of the second	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority 🗌 High 🗌 Medium 🖌 Low	Exterior Materials	Wood; Plywood Panel	Addition(s)	Has shed-roof side façade addition
	Address	800 Givens		
	Date	1915		Alterations/Modifications
	Current Use	Residence	Ext. Materials	· · · · · · · · · · · · · · · · · · ·
	Property Type	Domestic: single-family	Windows	
	Plan	L-Plan	Doors	
	Style	Folk Victorian		Porch has been enclosed
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority High 🖌 Medium Low	Exterior Materials	Wood		
	Address	917 Givens		
	Date	1945		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	Ranch	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
		Side gable	Addition(s)	
Priority High Medium 🗹 Low	Exterior Materials	Wood		

	Address	108 Graham		
	Date	1935		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad w/vinyl siding
	Plan	Rectangular: massed		Replaced w/ Aluminum windows
	Style	No Style		Porch posts replaced
	No. of Stories	1	Porch	
and the second second	Structural System	Wood frame	Roof	
and the second	Roof	Gable-on-hip	Alterations	
<i>Priority</i>	Exterior Materials	Vinyl	Addition(s)	
			L	
The second s	Address	200 Graham		
	Date	1944		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
the second se	Roof	Side gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	
	Address	132 Grainery Road		
	Date	1925		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow	Windows	
	Style	Craftsman	Doors	
- and a second second second	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
			L	
	Address	435 N. Grand		
	Date	1942		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family		Exterior walls partially re-clad
	Plan	Irregular		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
and the second sec	-	Cross gable;Shed	Alterations	
Priority High Medium 🗸 Low	Exterior Materials	Asbestos	Addition(s)	
	Address	505 N. Grand		
	Date	1940		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	
	Property Type Plan	Bungalow	Windows	
	Style	No Style	Doors	
		1	Porch	
	Structural System	Wood frame	Roof	
	-	Side gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	

Address 602 N	N. Grand
Date 1945	Alterations/Modifications
Current Use Resid	
Property Type Dome	estic: single-family Windows Some window openings infilled
Plan Recta	angular: masseg
Style Ranch	b Doors
No. of Stories 1	Porch
Structural System Wood	d frame Roof
Roof Side g	gable Alterations
Priority ☐ High ☐ Medium ✔ Low Exterior Materials Brick	Addition(5)
Address 103 H	Harbin
Date 1938	Alterations/Modifications
Current Use Reside	dence
Property Type Dome	estic: single-family Ext. Materials
Plan Irregu	ular Windows
Style Tudor	r Revival Doors
No. of Stories	Porch supports replaced
Structural System Wood	d frame Roof
Roof Cross	Alterations
Priority High V Medium Low Exterior Materials Wood	Addition(s)
Address 207 H	Harbin
Date 1940	Alterations/Modifications
Current Use Resid	dence
Property Type Dome	estic: single-family Ext. Materials
	ular Windows
Style No Str	tyle
No. of Stories 1	Porch
Structural System Wood	d frame Roof
Roof Cross	Alterations
Priority High Vedium Low Exterior Materials Wood	Addition(s)
Address 208 H	Harbin
Date 1938	Alterations/Modifications
Current Use Resid	dence
Property Type Dome	estic: single-family Ext. Materials
Plan Irregu	Windows Litidinal Windows replaced
Style No Str	tyle
No. of Stories 1	Porch
Structural System Wood	d frame Roof
Roof Cross	Alterations
Priority High Vedium Low Exterior Materials Wood	Addition(s)
Address 210 H	Harbin
Date 1936	
Current Use Resid	
Property Type Dome	estic single family
Plan Irregu	ular Some replaced
Style No Str	tyle
No. of Stories	Porch
Structural System Wood	d frame Roof
Roof Cross	Alterations
Priority High Medium Low Exterior Materials Wood	- Addition(S)
	<u> </u>

	Address	215 Harbin		
is the second second	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	- Windows	
	Plan	Irregular	- Doors	
	Style	No Style	- Porch	
	No. of Stories	1	- Roof	
	Structural System	Wood frame	- Alterations	
	Roof	Cross gable	- Addition(s)	
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Wood		
		000.11.11		
	Address	308 Harbin		
	Date	1936		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan Style	Irregular No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
the second the	Roof	Cross gable	— Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
	Address	331 Harbin		
	Date	1942		Alterations/Modifications
	Current Use	Residence		Alterations/modifications
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Irregular	- Windows	
	Style	Minimal Traditional	— Doors	
	No. of Stories	1	- Porch	
	Structural System	Wood frame	- Roof	
Constant 12 Reconstant	Roof	Cross gable	Alterations Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	209 S. Hawkins		
	Date	1890		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	- Windows	
	Plan	Rectangular: linear (horizon	Doors	
	Style	Folk Victorian		
	No. of Stories	1 Weed from a		
	Structural System	Wood frame	Alterations	
		Side gable Wood	Addition(s)	
Priority 🖌 High 🔄 Medium 🔄 Low	Exterior Materials			
	Address	? Hawkins Street		
	Date	1900		
	Current Use	Landscape (Hawkins Spring)		Alterations/Modifications
	Property Type	Landscape (Hawkins Spring)	Ext. Materials	
A CONTRACTOR OF		N/A	Windows	
	Style	N/A	Doors	
	No. of Stories		Porch	
	Structural System	N/A		
	Roof			
Priority 🗸 High 🗌 Medium 🗌 Low	Exterior Materials	Concrete	Addition(s)	

and the	Address	? Hawkins Street		
	Date	1950		Alterations/Modifications
	Current Use	Recreational/Civic (Richards Park)	Ext Materiala	
	Property Type	Recreational/Civic:City Baseball P	Ext. Materials Windows	
	Plan	Irregular		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Load-bearing masonry	Roof	
	Roof	Front gable; flat	Alterations	
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Concrete Block	Addition(s)	
	Address	? Henrietta		
	Date	1935		Alterations/Modifications
	Current Use	Vacant	Ext Matorials	Exterior walls re-clad w/asbestos shingles
	Property Type	Domestic: single-family		Original windows replaced w/aluminum sash
	Plan	Irregular	Doors	
	Style	No Style		Porch infilled
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable; Shed		
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Asbestos; Wood	Addition(s)	Has a side shed-roof addition
	Address	108 Henry		
A CALL AND A	Date	1936		Alterations/Modifications
IN THE REAL PROPERTY OF	Current Use	Residence		
	Property Type	Domestic: single-family		Asphalt shingles added to gable end
	Plan	Bungalow		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Front gable	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood; Asphalt Shingle	Addition(s)	
	Address	205 Henry		
	Date	1920		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Complex	Alterations	
Priority High Medium 🗸 Low	Exterior Materials	Asbestos Siding; Asphalt Shingles	Addition(s)	
	Address	209 Henry		
	Date	1905		Alterations (Madifications
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	L-Plan	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	Original porch supports replaced
	Structural System	Wood frame	Roof	·
-	Roof		Alterations	
		Cross gable	Addition(s)	
Priority High 🖌 Medium Low	Exterior Materials	Wood		

	Address	304 Henry		
	Date	1905		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	L-Plan	Doors	
	Style	No Style	Porch	
	No. of Stories	1		
S	tructural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority High I Medium Low E	xterior Materials	Wood		
	Address	200 Цорт		
	Address Date	309 Henry 1945		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	Exteriors re-clad w/current wood siding
	Plan	Irregular	Windows	Openings altered; original windows changed
Construction of the second second	Style	No Style	Doors	
A CONTRACT OF TAXABLE PARTY AND A CONTRACT OF TAXABLE PARTY.	No. of Stories	1		porch supports replaced
s	tructural System	Wood frame	Roof	
	Roof	Cross/hipped	Alterations	
Priority High Medium 🖌 Low	xterior Materials	Wood	Addition(s)	C. 1945 addition
	Address	301 Highland		
	Date	1936		Alterations/Modifications
	Current Use	Residence	Ext Matariala	Exterior wall re-clad w/asbestos shingles
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1		
S	tructural System	Wood frame	Alterations	
	Roof	Front gable	Addition(s)	
Priority High Medium V Low E	xterior Materials	Asbestos		
	Address	200 History		
	Address Date	308 Highland 1940		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	Craftsman	Doors	
And a state of the	-	1	Porch	
S	tructural System	Wood frame	Roof	
	•	Side gable	Alterations	
<i>Priority</i> High ✔ Medium Low <i>E</i>	xterior Materials	Wood	Addition(s)	
	Address	514 Highland		
STATES AND AND SHALL	Date	1936		Alterations/Modifications
	Current Use	Residence	Ext Matariala	Exterior walls re-clad w/asbestos shingles
	Property Type	Domestic: single-family	Windows	
	Plan	Bungalow	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
S	tructural System	Wood frame	Alterations	
		Cross gable	Addition(s)	
<i>Priority</i> High Medium ✔ Low <i>E</i>	xterior Materials	Asbestos		

	Address	? Highway 77		
	Date	1905		Alterations/Modifications
	Current Use	Residence	Ext Motoriala	
	Property Type	Domestic: single-family	Windows	Exterior walls re-clad w/asbestos shingles
	Plan	L-Plan		Original doors replaced
	Style	No Style		Porch enclosed c. 1925
The second second second	No. of Stories	1		Roof altered by additions
	Structural System	Wood frame	- Alterations	
		Cross gable w/ shed		C. 1925 & 1950 side and rear additions
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood; Asbestos		
	Address	? Highway 77		
	Date	1920		Alterations/Modifications
	Current Use	Commercial	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan Style	Irregular	Doors	
	•	No Style 2	Porch	Porch filled in
	Structural System	2 Wood frame		
and the second second		Front gable; Cross/hipped	— Alterations	
Priority ☐ High Medium ✔ Low	Exterior Materials	Wood	Addition(s)	Wing added to front façade
	Address	3209 Highway 77		
	Date	1905		Alterations/Modifications
	Current Use	Residence		
		Domestic: single-family	Ext. Materials	
	Plan	Modified L-Plan		
	Style	Queen Anne; Folk Victorian	— Doors	
	No. of Stories	2	Porch	
	Structural System	Wood frame	- Roof	
	Roof	Cross gable	— Alterations	
Priority 🖌 High 🗌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	2800 N. Highway 77		
	Date	1930		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Orig. windows replaced w/ aluminum sash
STOCILL COLUMN TO AND	Plan	Irregular		
a set the gas	Style	No Style		Porch posts replaced
and the second se	No. of Stories	1		
A CONTRACTOR OF THE OWNER	Structural System	Wood frame		
		Cross gable		Garage added to the rear
Priority 🔄 High 🔄 Medium 🖌 Low	Exterior Materials	Wood		
	A	2067 N. History 77		
and the second	Address	2857 N. Highway 77		
	Date Current Llee	1925		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan Style	Bungalow Craftsman	— Doors	
	No. of Stories	1	Porch	
and the second	Structural System	Wood frame	— Roof	
		Front gable	— Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
			L	

	Address	0 ? Howard Road		
	Date	1900		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: linear	Doors	
	Style	Folk Victorian		
	No. of Stories	1		
and the second	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority 🗹 High 🗌 Medium 🗌 Low	Exterior Materials	Wood		
	Address	202 Howard Road		
	Date	1936		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Plan	Bungalow	Windows	
	Style	No Style	Doors	
	No. of Stories	1		Original porch posts and flooring replaced
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
<i>Priority</i> High Medium	Exterior Materials	Vinyl	Addition(s)	Has a side façade addition
	Address	306 Howard Road		
11	Date	1940		Alterations/Modifications
A statement of the stat	Current Use	Vacant	Ext. Materials	1
	Property Type	Domestic: single-family		Window openings added
	Plan	Rectangular: massed		Second entrance added to front façade
	Style	No Style	Porch	
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
Drievity Uliah Madium I Law	Roof Exterior Materials	Side gable	Addition(s)	
Priority High Medium V Low		Wood		
	Address	821 Howard Road		
	Date	1915		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family		Exterior walls re-clad w/plywood panels
	Plan	Rectangular: massed		Windows replaced w/aluminum-frame units
	Style	No Style	Doors	
	No. of Stories	1	— Porch — Roof	Original porch posts and flooring replaced
and the second s	Structural System	Wood frame	Alterations	
	Roof	Hipped; Front gable		Has rear and side additions
<i>Priority</i> ☐ High	Exterior Materials	Plywood panel	Addition(3)	
		·····		
94 M	Address	1809 Howard Road		
	Date	1925		Alterations/Modifications
	Current Use	Residence	Ext. Materials	1
	Property Type Plan	Domestic: single-family Rectangular: massed	Windows	Original windows replaced, some openings
	Plan Style	No Style	Doors	·
	No. of Stories	1	Porch	Original porch posts and flooring replaced
	Structural System	Wood frame		
Restance - we		Hipped	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	Has rear additions
, _ ,			L	

		Address	1909 Howard Road		
A		Date	1935	_	Alterations/Modifications
A CANANA AND AND AND AND AND AND AND AND AN		Current Use	Commercial		
A TRANSFER		Property Type	Domestic: single-family		Exterior walls re-clad w/vinyl siding
		Plan	Bungalow		Windows replaced w/aluminum-frame units
A REAL PROPERTY	TTOM TO SALE	Style	Craftsman	– Doors	Original south south real-ord
		No. of Stories	1		Original porch posts replaced
	Carlo Carlos	Structural System	Wood frame	– Roof	
and a second second	and Mag	Roof	Cross gable	 Alterations 	
<i>Priority</i> 🗌 High	🗌 Medium 🗹 Low	Exterior Materials	Vinyl	– Addition(s)	Has several rear additions
Contraction of the Contraction		Address	2405 Howard Road		
		Date	1940	_	Alterations/Modifications
Peter 1990		Current Use	Residence	Ext Matorials	Exterior walls re-clad w/asbestos shingles
		Property Type	Domestic: single-family	– Windows	
		Plan	Bungalow		Front façade entrance enclosed w/ plywood
		Style	No Style		Original porch posts and flooring replaced
		No. of Stories	1	- Roof	
		Structural System	Wood frame	– Alterations	
		Roof	Side gable	– Addition(s)	
Priority 🗌 High	Medium 🗸 Low	Exterior Materials	Asbestos	Addition(s)	_
	Service and	Address	2503 Howard Road		
anticity and		Date	1930	_	Alterations/Modifications
		Current Use	Residence	- Ext Materials	Exterior walls re-clad w/asbestos shingles
		Property Type	Domestic: single-family	– Windows	
		Plan	Bungalow	– Doors	
		Style	No Style		Original porch posts and flooring replaced
		No. of Stories	1	– Roof	
T have a		Structural System	Wood frame	– Alterations	
		Roof	Front gable	- Addition(s)	
<i>Priority</i> 🗌 High	🔄 Medium 🖌 Low	Exterior Materials	Asbestos		
	Statistics of the local division of the loca	Address	2005 Haward David		
10 mar	-	Date	2605 Howard Road 1940	_	
		Current Use	Residence	-	Alterations/Modifications
Bulley Broker	and the second second	Property Type	Domestic: single-family	– Ext. Materials	
Aires				- Windows	
		Plan Style	Bungalow No Style	– Doors	
		No. of Stories	1	– Porch	
And Aller		Structural System	Wood frame	– Roof	
		Roof	Side gable; Shed	 Alterations 	
Priority 🗌 High	Medium 🖌 Low	Exterior Materials	Wood	 Addition(s) 	Shed-roof garage added
	the state of the second	Address	2607 Howard Road		
AR BAR S	ALL STREET	Date	1930	_	Alterations/Modifications
	A Street and	Current Use	Residence	_	
N in white	Kala and a second	Property Type	Domestic: single-family		Exterior walls re-clad w/present wood siding
		Plan	Bungalow		Windows replaced w/aluminum-frame units
		Style	No Style	– Doors	
		No. of Stories	1		Original porch posts and flooring replaced
And the second second		Structural System	Wood frame	– Roof	
		-	Front gable	 Alterations 	
Priority 🗌 High	🗌 Medium 🗹 Low	Exterior Materials	Wood	 Addition(s) 	
· — •					

The second s	Address	? E. Jefferson		
	Date	1920	-	Alterations/Modifications
	Current Use	Funerary (Freedman's Cemetery)	- Eut Matariala	
	Property Type	Funerary	Ext. Materials Windows	
	Plan	Not applicable		
III · · · · · · · · · · · · · · · · · ·	Style	Not applicable	- Doors - Porch	
	No. of Stories	0	- Porch - Roof	
and a second second	Structural System	Not applicable	- Alterations	
	Roof	Not applicable	- Addition(s)	
Priority 🖌 High 🗌 Medium 🗌 Low	Exterior Materials	Not applicable	Addition(s)	
	Address	202 -212 E. Jefferson		
2	Date	1940	_	Alterations/Modifications
	Current Use	Commercial	Ext. Materials	
202	Property Type	Commercial	- Windows	
	Plan	Irregular	- Doors	
	Style	No Style	- Porch	
and the second s	No. of Stories	1	- Roof	
	Structural System	Wood frame	- Alterations	
	Roof	Hipped; Shed	- Addition(s)	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Corrugated metal	Addition(6)	
	Address	117 W. Jefferson		
	Date	1945	_	Alterations/Modifications
	Current Use	Governmental	Ext. Materials	· · · · · · · · · · · · · · · · · · ·
	Property Type	Governmental	- Windows	
	Plan	Irregular	- Doors	
	Style	No Style	- Porch	
	No. of Stories	2	- Roof	
	Structural System	Load-bearing masonry	Alterations	
	Roof	Flat	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Brick; Stone; Concrete		
ATL WALL THE				
and the second sec	Address	404 W. Jefferson	-	
	Date	1942	-	Alterations/Modifications
	Current Use	Commercial	Ext. Materials	
Sime Players \$37.5m	Property Type		Windows	
	Plan	Rectangular: massed	- Doors	
	Style No. of Stories	No Style	- Porch	
		-	- Roof	
	Structural System Roof	Load-bearing masonry	- Alterations	
<i>Priority</i> High Medium ✔ Low	Roor Exterior Materials	Concrete block	- Addition(s)	
<i>Priority</i> High Medium ∨ _ Low				
1000	Address	405 W. Jefferson		
	Date	1945	_	Alternation of Mandification
	Current Use	Commercial	-	Alterations/Modifications
ALAMACON HURDOFT		Commercial		Permastone exterior cladding added
		Rectangular: massed	Windows	
	Style	No Style		Overhead door and doorway added
	No. of Stories	1	- Porch	
	Structural System	Load-bearing masonry	- Roof	
and the set of the set	Roof		- Alterations	
Priority High Medium 🗸 Low	Exterior Materials	Permastone; Concrete block	- Addition(s)	
, _ ,				

	Address	407 W. Jefferson		
	Date	1945		Alterations/Modifications
where is all an all and the	Current Use	Commercial	_	
	Property Type	Commercial	— Ext. Materials	
	Plan	Rectangular: massed	- Windows	
	Style	No Style		Overhead door and doorway added
	No. of Stories	1	- Porch	
	Structural System	Load-bearing masonry		
		Front gable	— Alterations	
<i>Priority</i> ☐ High		Brick; Concrete block	— Addition(s)	
	Address	1116 W. Jefferson		
	Date	1915		Alterations/Modifications
	Current Use	Residence		Anerations/modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow	- Windows	
	Style	National Folk	— Doors	
	No. of Stories	1	Porch	
and the second	Structural System	Wood frame	— Roof	
and the second	Roof	Hipped - front gable porch	— Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
	Address	108 Jim		
	Date	1930		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Irregular	— Windows	Windows replaced w/aluminum-frame units
	Style	No Style	— Doors	
	•			
And a supervised of the second	No of Ciavian	1		
	No. of Stories	1 Wood frame	— Roof	
ALC: NOT	Structural System	Wood frame	— Roof — Alterations	
	Structural System Roof	Wood frame Complex	Alterations	Hipped roof wing is a c. 1940 addition
Priority High Medium ✔ Low	Structural System	Wood frame	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Structural System Roof Exterior Materials	Wood frame Complex Wood	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Structural System Roof Exterior Materials Address	Wood frame Complex Wood 109 Jim	Alterations	Hipped roof wing is a c. 1940 addition
Priority ☐ High ☐ Medium ✔ Low	Structural System Roof Exterior Materials Address Date	Wood frame Complex Wood 109 Jim 1935	Alterations	
Priority ☐ High ☐ Medium ☑ Low	Structural System Roof Exterior Materials Address Date Current Use	Wood frame Complex Wood 109 Jim 1935 Residence	Alterations	Hipped roof wing is a c. 1940 addition
Priority ☐ High ☐ Medium ☑ Low	Structural System Roof Exterior Materials Address Date Current Use Property Type	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family	Alterations Addition(s)	Hipped roof wing is a c. 1940 addition
Priority ☐ High ☐ Medium ☑ Low	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow	Alterations Addition(s)	Hipped roof wing is a c. 1940 addition Alterations/Modifications
Priority High Medium ✓ Low	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style	Alterations Addition(s)	Hipped roof wing is a c. 1940 addition Alterations/Modifications
Priority ☐ High ☐ Medium ☑ Low	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1	Alterations Addition(s) Ext. Materials Windows Doors	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
Priority High Medium Low	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame	Alterations Addition(s) Ext. Materials Windows Doors Porch	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable	Alterations Addition(s) Ext. Materials Windows Porch Roof	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
Priority High Medium ✓ Low Image: State of the state	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame	Alterations Addition(s) Ext. Materials Undows Doors Porch Roof Alterations	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood	Alterations Addition(s) Ext. Materials Undows Doors Porch Roof Alterations	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim	Alterations Addition(s) Ext. Materials Undows Doors Porch Roof Alterations	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim 1940	Alterations Addition(s) Ext. Materials Undows Doors Porch Roof Alterations	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim 1940 Residence	Alterations Addition(s) Ext. Materials Undows Doors Porch Roof Alterations	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family	Alterations Addition(s) Ext. Materials Windows Doors Porch Roof Alterations Addition(s) Ext. Materials	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family Bungalow	Alterations Addition(s) Ext. Materials Windows Doors Porch Roof Alterations Addition(s) Ext. Materials	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units Alterations/Modifications
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family Bungalow No Style	Alterations Addition(s) Ext. Materials Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units Alterations/Modifications
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family Bungalow No Style 1	Alterations Addition(s) Ext. Materials Undows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows Doors Do	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units Alterations/Modifications
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family Bungalow No Style 1 Wood frame Uomestic: single-family Bungalow No Style 1 Wood frame	Alterations Addition(s) Ext. Materials Windows Doors Porch Roof Alterations Addition(s) Ext. Materials Windows Doors Porch Porch	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units Alterations/Modifications
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Style	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family Bungalow No Style 1 Wood frame Front gable	Alterations Addition(s)	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units Alterations/Modifications
	Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System	Wood frame Complex Wood 109 Jim 1935 Residence Domestic: single-family Bungalow No Style 1 Wood 1 Wood frame Cross gable Wood 113 Jim 1940 Residence Domestic: single-family Bungalow No Style 1 Wood frame Uomestic: single-family Bungalow No Style 1 Wood frame	Alterations Addition(s)	Hipped roof wing is a c. 1940 addition Alterations/Modifications Windows replaced w/aluminum-frame units Alterations/Modifications

	Address	117 Jim		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Fort Materials	
	Property Type	Domestic: single-family	Ext. Materials Windows	
	Plan	Irregular	Doors	
	Style	No Style	Porch	
the second se	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable		Has a rear addition
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood		
	Address	604 John Arden		
	Date	<u>1935</u>		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad
	Property Type Plan	Domestic: single-family	Windows	Original windows replaced
	Style	Rectangular: massed	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
and the second sec	Roof	Gable-on-hip	Alterations	
Priority High Medium 🖌 Low	Exterior Materials	Masonite	Addition(s)	
	Address	605 John Arden		
	Date	1935		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow	Windows	
	Style	No Style	Doors	
A CONTRACTOR OF THE OWNER	No. of Stories	1	Porch	Original porch posts replaced
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Alterations Addition(s)	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Asbestos	Addition(3)	
	Address	99 Joseph		
	Date	1945		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
		Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories Structural System	1 Wood frame	Roof	
	•	Side gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Vinyl	Addition(s)	
		····/·		
	Address	100 Joseph		
and the second second	Date	1936		Alterations/Modifications
	Current Use	Residence		AILEI AUUIIS/INIUUIIICAUUIIS
	Property Type	Domestic: single-family	Ext. Materials	
		Rectangular: massed		Replacements
	Style	Colonial Revival; Minimal Traditional		New front door
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
Western Carlos And		Side gable	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood	Addition(s)	

	Address	104 Joseph		
	Date	1942		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
and the second sec	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority High Medium V Low	Exterior Materials	Wood		
	Address	107.2 Jacoph		
And the second	Date	107 ? Joseph 1935		
A CONTRACTOR OF A CONTRACTOR O	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: outbuilding (garage apt	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	2		New exterior staircase added
	Structural System	Wood frame	Roof	
	Roof	Front gable	Alterations	
<i>Priority</i>	Exterior Materials	Wood	Addition(s)	
	Address	121 Kaufman		
and a state	Date	1935		Alterations/Modifications
	Current Use	Religious	Ext. Materials	
A BREAK AND AND A BREAK AND AND A BREAK AND AND AND A BREAK AND	Property Type	Religious	Windows	
	Plan	Rectangular: massed		Original doors replaced
	Style	No Style	Porch	
	No. of Stories	1	Roof	
Cat of	Structural System	Wood frame	Alterations	
Priority ☐ High	Roof Exterior Materials	Front gable	Addition(s)	
Priority High Medium V Low		Wood		
	Address	404 Kaufman		
	Date	1920		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family		Exterior walls re-clad w/vinyl
	Plan	Bungalow		Some window opening enclosed
	Style	No Style	Doors	
	No. of Stories	1	Porch Roof	
1-1	Structural System	Wood frame	Alterations	
1	Roof	Front gable	Addition(s)	
<i>Priority</i>	Exterior Materials	Vinyl	Addition(3)	
	Address	406 Kaufman		
A State of the sta	Date	1936		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/asbestos shingles
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Bungalow		Front door replacement
	Style No. of Stories	No Style	Porch	
	Structural System	Wood frame	Roof	
	-	Side gable	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Asbestos	Addition(s)	

	Address	502 Kaufman		
	Date	1935		Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exterior walls re-clad w/ masonite & plywoo
	Property Type	Domestic: single-family		Windows replaced w/aluminum frame units
	Plan	Bungalow		Original doors replaced
	Style	No Style		Original porch posts & flooring replaced
A CONTRACT OF A	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	-
	Roof	Front gable	Addition(s)	
Priority High Medium V Low	Exterior Materials	Plywood panel; Masonite		
	Address	618 Kaufman		
the second state of the se	Address Date	1920		
	Current Use	Residence		Alterations/Modifications
RANKS CONTRACT	Property Type	Domestic: single-family	Ext. Materials	Exterior walls re-clad w/vinyl siding
States	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1		New porch added
W.	Structural System	Wood frame	Roof	
A second second second	Roof	Hipped	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Vinyl	Addition(s)	
	Address	620 Kaufman		
	Date	1940		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular	Doors	Original windows replaced
	Style	Colonial Revival; Minimal Traditional	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped	Addition(s)	
Priority 🔄 High 🔛 Medium 🖌 Low	Exterior Materials	Wood		
	• • • •			
	Address	101 Kelley		
	Date	1920		Alterations/Modifications
	Current Use	Residence/Commercial	Ext. Materials	
And the second s		Domestic: single-family	Windows	Original windows replaced w/ aluminum fra
	Plan Style	Bungalow	Doors	
	No. of Stories	1		Porch support replaced
	Structural System	Wood frame	Roof	
	Roof		Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	Front, rear and side wings added
· · · · · · · · · · · · · · · · · · ·				
	Address	201 Kirksey		
	Date	1930		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow	Windows Doors	
	Style	No Style		Original porch posts and flooring replaced
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Front gable	Addition(s)	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Asbestos	///////////////////////////////////////	

Categories and the second	Address	107 Kirven		
and the second second second	Date	1936		Alterations/Modifications
All Aller	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	Minimal Traditional	Porch	
SI Wat State 100	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Front gable	Addition(s)	
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Wood		
	A dalama a	000 1/1		
	Address Date	222 Kirven 1942		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular	Windows	Some replaced
Comparison of the second second	Style	Minimal Traditional	Doors	
151	No. of Stories	1	Porch	
and the second	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> High ✔ Medium Low	Exterior Materials	Wood	Addition(s)	
· · · · · · · · · · · · · · · · · · ·				
	Address	300 Kirven		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exterior walls re-clad w/brick
	Property Type	Domestic: single-family		Replaced with aluminum
Max Provide Alexandre	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority High Medium V Low	Exterior Materials	Brick		
	Address	523 Lake Park		
	Date	1940		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	
State of the second sec	Plan	Rectangular: massed		Original windows replaced
- Det The set	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof Roof	
	Roof	Front gable	Addition(s)	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address	112 LeatherWood		
	Date	1945		Alterations/Modifications
	Current Use	Commercial	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Bungalow	Doors	
	Style	No Style	Porch	
	No. of Stories	1 Wood frame	Roof	
The second se	Structural System	Wood frame Cross gable	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Roof Exterior Materials	Wood	Addition(s)	

	Address	923 Lone Elm Road		
	Date	1900		Alterations/Modifications
	Current Use	Residence	E (M (, i))	
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Rectangular: linear	Windows Doors	Windows replaced w/aluminum-frame units
	Style	National Folk	Doors Porch	
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority 🗌 High 🔽 Medium 🗌 Low	Exterior Materials	Asbestos	///////////////////////////////////////	
	Address	3030 Longbranch Road		
	Date	1925		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	Windows replaced, some openings changed
	Plan	Bungalow	Doors	
and the second second	Style	No Style	Porch	Porch added C. 1940
Alexandre and a second second	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
Priority High Medium 🗸 Low		Front gable	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Wood		
	Address	405 W. Madison		
	Date	1940		••• ·• · · · · ·
	Current Use	Commercial		Alterations/Modifications
	Property Type	Commercial	Ext. Materials	
	Plan	Irregular		
	Style	No Style	Doors	
	No. of Stories	2	Porch	
	Structural System	Load-bearing masonry	Roof	
	Roof	Front gable; Shed	Alterations	
<i>Priority</i> _ High _ Medium ✔ Low	Exterior Materials	Brick	Addition(s)	
· - ·			L	
	Address	400 E. Main		
	Date	1942		Alterations/Modifications
	Current Use	Commercial	Ext. Materials	
BACK PROCESS	Property Type	Commercial	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style		Original door replaced
	No. of Stories	1		-
	Structural System	Wood frame	Alterations	
	Roof	Side gable; Shed	Addition(s)	
Priority High 🖌 Medium Low	Exterior Materials	Wood		
	Address	510 rear E. Main		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family		
		Bungalow	Doors	
	Style	No Style	Porch	Porch posts replaced
	No. of Stories	1 Wood fromo	Roof	
A Contract Aller	Structural System	Wood frame	Alterations	
Priority High Madium		Side gable	Addition(s)	
Priority ☐ High ✔ Medium ☐ Low	Exterior Materials	Permastone		

	Address	570 E. Main		
V ³ EASTSINE BARA-GUE	Date	1940		Alterations/Modifications
972-923-090 500-MAN	Current Use	Commercial		
	Property Type	Domestic: single-family		Exterior walls re-clad w/masonite
Pre-Pau Cellular Nones	Plan	Rectangular: linear	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Front gable; Shed	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Masonite	Addition(s)	Small side and rear additions
	Address	613 E. Main		
	Date	1940		Alterations/Modifications
	Current Use	Vacant		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Front gable	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
· - ·				
	Address	710 E. Main		
Con Repaired in the	Date	1945		Alterations/Modifications
	Current Use	Residence	F (M ()) ()	
	Property Type	Domestic: single-family	Ext. Materials	
A CAR AND A	Plan	Irregular		All original windows replaced
and a second sec	Style	No Style	Doors	
Construction of the second	No. of Stories	1	Porch	
	Structural System	Wood frame; Load-bearing masonry		Roofline altered by addition
	Roof	Front gable; Hipped	Alterations	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Wood; Concrete block	Addition(s)	Concrete block wing added to front façade
	Address	801 E. Main		
A COMPANY OF A COM	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext Materials	Plywood panel added
	Property Type	Domestic: single-family	Windows	
	Plan	Bungalow	Doors	
	Style	No Style		Original porch posts replaced
and the second sec	No. of Stories	1	Roof	
the second se	Structural System	Wood frame	Alterations	
	Roof	Front gable	Addition(s)	
Priority High Medium 🗸 Low	Exterior Materials	Wood: Plywood Panel	, launon(o)	
	Address	907 E. Main		
and a second	Date	1935		Alterations/Modifications
	Current Use	Vacant	Ext. Materials	
	Property Type	Commercial	Windows	Windows boarded-up
and the second states and states	Plan	Rectangular: massed	Doors	Doorway boarded-up
	Style	No Style	Porch	·
	No. of Stories	1	Roof	
Statistics and a statistical statistics	Structural System	Load-bearing masonry	Alterations	
	Roof	Front gable w/ parapet	Addition(s)	
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Stucco; Concrete block		

and the second second	Address	1120 E. Main		
	Date	1920		Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exterior walls re-clad w/asbestos shingles
	Property Type	Domestic: single-family	- Windows	
	Plan	Bungalow	- Doors	
	Style	No Style		Original porch posts replaced
	No. of Stories	1	- Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable; Hipped	- Addition(s)	Small side façade wing added
Priority High Medium 🖌 Low	Exterior Materials	Wood; Asbestos	`	
	Address	1000 E. Main		
	Address	1200 E. Main		
A State of the second s	Date Current Use	1940 Residence		Alterations/Modifications
			Ext. Materials	
	Property Type Plan	Domestic: single-family Bungalow	— Windows	Original windows replaced
	Style	No Style	— Doors	
- A Contraction of the second	No. of Stories	1	- Porch	Original porch post replaced
	Structural System	Wood frame	— Roof	
1200	Roof	Front gable	— Alterations	
Priority High Medium 🖌 Low	Exterior Materials	Wood	— Addition(s)	
	Address	1202 E. Main		
	Date	1942		Alterations/Modifications
	Current Use	Residence	-	
	Property Type	Domestic: single-family		Exterior walls re-clad
	Plan	Rectangular: massed		Some window openings covered
	Style	No Style	— Doors — Porch	
	No. of Stories	1	— Porch — Roof	
	Structural System	Wood frame	Alterations	
and the second	Roof	Side gable	- Addition(s)	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Wood; Permastone	/iddition(0)	
	Address	1400 rear E. Main		
	Date	1935		Alterations/Modifications
1 Providence of the second sec	Current Use	Residence	Ext. Materials	
		Domestic: single-family	— Windows	Original windows replaced
	Plan Style	Bungalow No Style	— Doors	
	No. of Stories	1	- Porch	
	Structural System	Wood frame	— Roof	
	•	Front gable	Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	— Addition(s)	
· · · · · · · · · · · · · · · · · · ·				
an tel	Address	1503 E. Main		
	Date	1935		Alterations/Modifications
A CONTRACTOR OF THE PERSON OF	Current Use	Residence		Anterations/mounications
	Property Type	Domestic: single-family	— Ext. Materials	
	Plan	Bungalow		Original windows replaced
	Style	No Style	— Doors — Porch	
	No. of Stories	1	— Porch — Roof	
and the second s	Structural System	Wood frame	Alterations	
AT A CARL AND A REAL PARTY OF	Roof	Cross gable		Wing added to side façade
Priority 🗌 High 📄 Medium 🖌 Low	Exterior Materials	Wood	Addition(S)	

Date 19/2 Alterations/Modifications Priority Lign Contential Property Type Contential Priority Lign Madural Contential Property Type Contential Priority Lign Madural Contential Priority P		Address	401 W. Main		
Current Use Commencial Priority High Madum Low Property Low Priority High Maditics Low <		Date	1942		Alterations/Modifications
Property Type Commectal Windows Property Type Commectal Doors Priority I High V Madum Low Address 100 V. Main Roof Store Testime Block, Wood Address Address Priority I High V Madum Low Address 100 V. Main Roof Store Testime Block, Wood Address 100 V. Main Roof Store Testime Block, Wood Address 100 V. Main Roof Store Testime Block, Wood Address 100 V. Main Roof Store Testime Block, Wood Address 100 V. Main Roof Store Testime Block, Wood Browner, Block Address Priority I High V Madum Low Roof Address 10 main Roof Address 12 W. Main Browd Address Structural System Vood finame Roof Address Structural System Vood finame Address 10 main Roof Stores Testerior Matrials Wood Address Priority I High V Medium Low Address 10 mastic single-family Address Priority I High V Medium Low<		Current Use	Commercial		
Pian Imaginar Doors Pine Imaginar Doors Priority High Madum Priority High Mad		Property Type	Commercial		
Skyle No. of Skyle Pach Priority High Modum Low Priority High Modum Low Address 100 W, Main Date 1585 Corrente Elock Wood Address 100 W, Main Date 1585 Corrente Elock Wood Priority High		Plan	Irregular		
No. of Stories 1 Structural System Address 106 W. Main Priority High V Medum Low Address 1006 W. Main Address Priority High V Medum Low Address 1006 W. Main Address Priority High V Medum Low Address 1006 W. Main Address 1006 W. Main Priority High V Medum Low Address 1006 W. Main Address 1006 W. Main Priority High V Medum Low Residence Property Type Demastic: Intiliple family Priority High V Medum Low Structural System Mod trans Priority High V Medum Low Address 1007 W. Main Doors Priority High V Medum Low Address 1007 W. Main Address 1007 W. Main Priority High V Medum Low Address 1007 W. Main Address 1007 W. Main Priority High V Medum Low Address 1007 W. Main Address 1007 W. Main Priority High V Medum Low Residence Property Type Domastic: single-family Priority High V Medum Low Address 100 Midence Address 100 Midence Priority High Medum Low Address 108 Medun Address 100 Midence Str		Style	No Style		
Structural System Lodd-beating masory Alterations Priority High Medium Low Address 1005 W. Main Address Date 1383 Concrete Block. Wood Address 1005 W. Main Date Date 1383 Concrete Block. Wood Priority High Medium Concrete State Priority High No. of Stories Thereation Medifications Extender Meterials Wood Concrete State Porch P	and the second se	No. of Stories	1		
Priority High Medium Low Address Address Priority High Medium Low Address 1936 Address 1936 Concrete Block, Wood Alterations/Modifications Current Use Residence Property Type Concrete Block, Wood Priority High Medium Low Address 1005 W. Main Date 1936 Current Use Residence Property Type Priority High Medium Low No. of Stories Ext. Materials Structural System Mood frame Address 1207 W. Main Address 1207 W. Main Address 1207 W. Main Property Type Densetic: single-family Property Type Address Property Type Densetic: single-family Property Type Address Property Type Densetic: single-family Property Type Address Property Type Densetic: single-family		Structural System	Load-bearing masonry		
Priority High Maduum Low Extended Materials Lobolina Ellocy, Wood Image: Structural System Address 1005 W. Main Ext. Materials Ext. Materials Priority High Medium Low Address 1005 W. Main Priority High Medium Low Address 1006 W. Main Priority High Medium Low Style Bornalitic multiple-family Priority High Medium Low Exterior Materials Mood Priority High Medium Low Exterior Materials Mood Priority High Medium Low Address 1207 W. Main Defe 0 Densitic single-family Address 100 Medium Priority High Medium Low Exterior Materials Wood Priority High Medium Low Exterior Materials Mood Priority High Medium Low Exterior Materials Mood Priority High Medium Low Exterior Materials<	23				
Defe 1938 Alterations/Modifications Currant Use Reidence Protective Type Denset::::multiple-tamily Priority High ✓ Medum Low Structural System Wood Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High Medum Low Structural System No of Stories Priority High Medum Low Address 100 Priority High Medum Low Address 108 Maedon Priority High Medum Low Exterior Materials Mood Priority High Medum	<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Concrete Block; Wood	, automos	
Defe 1938 Alterations/Modifications Currant Use Reidence Protective Type Denset::::multiple-tamily Priority High ✓ Medum Low Structural System Wood Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High ✓ Medum Low Address 1207 W. Main Priority High Medum Low Structural System No of Stories Priority High Medum Low Address 100 Priority High Medum Low Address 108 Maedon Priority High Medum Low Exterior Materials Mood Priority High Medum					
Current Use Residence Property Type Domestic: multiple-family Har Buttonsmounchauturis Priority High Medium No. of Stories Stuctural Syst					
Property Type Domestic: multiple-family Ext. Materials Priority High Rectanguiar massed Doors Priority High No Siyle Roof Priority High Medium Low Address 1207 W. Main Address Browner Rood State Priority High Medium Low Address 1207 W. Main Address Browner Read Pointsci: single-family Priority High Medium Low Priority High Medium Cov Priority High Medium Low Pointsic: single-family Mindows Read Pointsic: single-family Mindows Read Pointsic: single-family Mood fame Read Rood State State <td></td> <th></th> <td></td> <td></td> <td>Alterations/Modifications</td>					Alterations/Modifications
Pirority High Medium Low Proving <				Ext. Materials	
Style No Style Parch New porch posts added Priority High Medium Low Barch New porch posts added Priority High Medium Low Exterior Materials Wood Wood Exterior Materials Wood Alterations Alterations Wood Exterior Materials Wood Alterations Alterations Windows Exterior Materials Wood Alterations Alterations Priority High Medium Low Alterations Ext. Materials Priority High Medium Low Residence Ext. Materials Windows replaced Priority High Medium Low Roof Cross gable Alterations Priority High Medium Low Exterior Materials Wood Alterations Priority High Medium Low Exterior Materials Wood Alterations Property Type Domestic: single-family Porch Rectangular: massed Bors Side apade Property Type Domestic: single-family Po					
No. of Stories 1 Protr. New poch posts added Priority High Mudum Low Structural System Wood frame Address Priority High Mudum Low Address 1207 W. Main Address Priority High Mudum Low Address 1207 W. Main Address Priority High Mudum Low Address 1207 W. Main Address Priority High Mudum Low Address 1207 W. Main Ext. Materials Priority High Mudum Low Address 1207 W. Main Ext. Materials Priority High Mudum Low Address 100 mestic: single-family Bain Priority High Medium Low Address 108 Maledon Address Priority High Medium Low Address 108 Maledon Address Priority High Medium Low Address 108 Maledon Ext. Faterials Priority High Medium Low Address 1211 Marta Doors Siding diast doors added to side facade Priority High Medium Low Address 1211 Marta Address Ext. Materials Mood farme Stories 1 No Stories Address				— Doors	
Structural System Wood frame Rod Priority High Medium Low Low Address Viority High Medium Low Address 1207 W. Main Viority High Medium No. of Stories Style Donestic: single-family Priority High Medium Low No. of Stories 1 Rod Structural System Wood frame Rod Cress gable Address Address Structural System Wood frame Rod Cress gable Address Address Viorotry High Medium Low Residence Ext. Materials Wood Property High Medium Low Residence Dows Ext. Materials Wood Current Use Residence Domstic: single-family Win		-		— Porch	New porch posts added
Roof Hipped Address Priority High Medium Low Exterior Materials Wood Address Address 120 W. Main Address Date 0 Atterations/Modifications Ext. Materials Wood Ext. Materials Priority High Nealum Low Priority High No. of Stories 1 Structural System Wood Toos gable Address 100 Maledon Address 100 Maledon Address 100 Maledon Priority High Medium Address 100 Maledon Bate 100 Maledon Address 100 Maledon Broity High Medium Property Type Domestic: single-family Plan Rectangular: massed Style No. Style Property Type Domestic: single-family Plan Rectangular: massed Style No. Style No. of Stories 1 Roof Atterations/Mo				— Roof	
Priority High Medium Low Exterior Materials Wood Addition(s) Addition(s) Address 1207 W. Main Address 1207 W. Main Alterations/Modifications Ext. Materials Property Type Domestic: single-family Plan Imegular Doors Priority High Medium Low Exterior Materials Wood Ext. Materials Priority High Medium Low Exterior Materials Wood Doors Priority High Medium Low Exterior Materials Wood Address Priority High Medium Low Address 108 Maledon Alterations/Modifications Ext. Materials Wood fame Fisher Mood fame Address 108 Maledon Property Type Domestic: single-family Property Type Domestic: single-family Mindows Some original Windows replaced Prority High Medium Low Exterior Materials Wood fame Prority High Medium Low Exterior Materials Mindows Some original Windows replaced		-		- Alterations	
Address 1207 W. Main Date 0 Current Use Residence Property Type Domestic: single-family Plan Irregular Style No. of Stories Address 100 Maledon Date 1940 Current Use Residence Property Type Domestic: single-family Plan Irregular No. of Stories 1 Address 108 Maledon Date 1940 Current Use Residence Property Type Domestic: single-family Plan Rectangular: massed Style No. of Stories Structural System Wood frame Roof Crass gable Exterior Materials Wood No. of Stories 1 Structural System Wood frame Roof Current Use Roof Stories 1				Addition(s)	
Date 0 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Priority High No. of Stories 1 Style No. of Stories 1 Style No Style Priority High Nedium Low Address 108 Maledon Address 108 Maledon Date 1940 Alterations/Modifications Current Use Residence Proch Roof Alterations/Modifications Current Use Residence Property Type Domestic: single-family Address 108 Maledon Date 1940 Current Use Residence Property Type Domestic: single-family Priority High Nedium Current Use Residence Property Type Property Type No. of Stories 1 Structural System Modef family Priority High Medium Low Style No. of Stories Property Type No. of Stories 1 Structural System Modef fame Roof Roof Roof Cross gable		Exterior materials			
Date 0 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Priority High No. of Stories 1 Style No. of Stories 1 Style No Style Priority High Nedium Low Address 108 Maledon Address 108 Maledon Date 1940 Alterations/Modifications Current Use Residence Proch Roof Alterations/Modifications Current Use Residence Property Type Domestic: single-family Address 108 Maledon Date 1940 Current Use Residence Property Type Domestic: single-family Priority High Nedium Current Use Residence Property Type Property Type No. of Stories 1 Structural System Modef family Priority High Medium Low Style No. of Stories Property Type No. of Stories 1 Structural System Modef fame Roof Roof Roof Cross gable		Addross	1207 W/ Main		
Current Use Residence Attractions/Modifications Property Type Domestic: single-family Midratons/modifications Bin Irregular Style No. 5tyle No. of Stories 1 Roof Structural System Wood frame Roof Address 108 Maledon Attractions/Modifications Address 108 Maledon Attractions/Modifications Address 108 Maledon Attractions/Modifications Current Use Residence Property Type Domestic: single-family Middition(s)					··· ·· ·· ·· ··
Property Type Domestic: single-family Ext. Materials Windows Mostlyle Doors Priority High Medium Low Priority High Medium Low Address 108 Maledon Address Darestic: single-family Mood frame Addition(s) Priority High Medium Low Address 108 Maledon Address Date 1940 Address Current Use Residence Proch Priority High Medium Current Use Rectangular: massed Sofie Doors Structural System Wood frame Atterations Structural System Wood frame Atterations Priority High Medium Low Address 1211 Martha Doors Structural System No. of Stories Atterations/Modifications Current Use Residence Proch Atterations/Modifications Property Type Doors Silding glass doors added to side facade Roof No. of Stories 1<	the second states				Alterations/Modifications
Plan Irregular No. Style No. Style No. of Stories 1 No. of Stories No. of Stories Structural System Wood frame Roof Address Roof Cross gable Modol Motions replaced Address Vindows Model to the state integration of the state integrate integrate integration of the state integration of				Ext. Materials	
Style No. style 1 Doors Priority High Medium Low Kadress 108 Maledon Address 108 Maledon Address 108 Maledon Address 108 Maledon Address 108 Maledon Address 108 Maledon Address 108 Maledon Address 108 Maledon Exterior Materials Kood Vindows Some original windows replaced Doors Ext. Materials Property Type Domestic: single-family Windows Some original windows replaced No. of Stories 1 Rectangular: massed Doors Sliding glass doors added to side façade Porch Original supports replaced No. of Stories Rood Rood Structural System Wood frame Cross gable Address Addition(s) Address 1211 Martha 1925 Exteriors/Modifications Ext. Materials Windows Structural System No. of Stories 1 Addition(s) Ext. Materials Windows Structural System No. of Stories 1 Structural System Noof <					Most original windows replaced
No. of Stories 1			-	— Doors	
Structural System Roof Wood frame Cross gable Roof Alterations Priority High Medium Low Low Address Date 108 Maledon Address 108 Maledon Address Date 1940 Alterations/Modifications Current Use Residence Ext. Materials Property Type Domestic: single-family Windows Style No Style No Style No. of Stories 1 Structural System Wood frame Rotof Cross gable Wood frame Address Style No. of Stories Structural System Wood frame Rotof Cross gable Wood Address 1211 Martha 1925 Current Use Residence Property Type Domestic: single-family Windows Style Property Type Domestic: single-family Roof Address Style Domestic: single-family Wood Bate 1925 Ext. Materials Current Use Residence		•		Porch	
Roof Cross gable Arterations Priority High Medium Low Address 108 Maledon Address Date 1940 Alterations/Modifications Viorent Use Residence Ext. Materials Priority High Addium Current Use Residence Priority High Medium Low Address 108 Maledon Briority High Medium Low Address 108 Maledon Priority High Medium Low Address 108 Maledon Briority High Medium Low Address 108 Maledon Priority High Medium Low Address 100 Mediance Address Priority High Medium Low Address 1211 Martha Exterior Materials Mood Priority High Medium Low Address 1211 Martha Ext. Materials Bargalow Style Cross gable Alterations/Modifications Ext. Materials Property Type Domestic: single-family					
Priority High Medium Low Exterior Materials Wood Address 108 Maledon Date 1940 Alterations/Modifications Date 1940 1940 Alterations/Modifications Current Use Residence Ext. Materials Windows Property Type Domestic: single-family Windows Some original windows replaced No. of Stories 1 Structural System Wood frame Roof Cross gable Alterations Alterations/Modifications Priority High Medium Low Address 1211 Martha Date 1925 Current Use Residence Ext. Materials Property Type Domestic: single-family Plan Burgalow Doors Structural System No. of Stories 1 Structural System Structural System No. of Stories 1 Structural System No. of Stories Ext. Materials No. of Stories 1 Structural System No. of Stories Ext. Materials Broperty Type Domestic: single-family Plan Burgalow Doors		-			
Address 108 Maledon Date 1940 Current Use Recidence Property Type Domestic: single-family Plan Rectangular: massed Style No. of Stories Priority High Medium ✓ Low Address Address 1211 Martha Date 1925 Current Use Residence Property Type Domestic: single-family Windows Some original windows replaced Doors Silding glass doors added to side façade Porch Original supports replaced Roof Cross gable Address 1211 Martha Date 1925 Current Use Residence Property Type Domestic: single-family Plan Bungalow Style Craftsman No. of Stories 1 Structural System Wood frame Roof Side gable	Priority High 🖌 Medium 🗌 Low			— Addition(s)	
Date 1940 Current Use Residence Property Type Domestic: single-family Plan Rectangular: massed Style No Style No. of Stories 1 Structural System Wood frame Roof Cross gable Address 1211 Martha Date 1925 Current Use Residence Property Type Domestic: single-family Windows Alterations Address 1211 Martha Date 1925 Current Use Residence Property Type Domestic: single-family Bungalow Style Style Craftsman No. of Stories 1 Structural System Wood frame No. of Stories 1 Property Type Domestic: single-family Bungalow Doors Style Craftsman No. of Stories 1 Structural System Wood frame Roof Side gable					
Current Use Residence Image: constraint of the image: const		Address	108 Maledon		
Current Use Residence Property Type Domestic: single-family No Style No Style No. of Stories 1 Structural System Wood frame Rectangular: massed No Style No. of Stories 1 Structural System Wood Roof Cross gable Address 1211 Martha 1925 Domestic: single-family Address 1211 Martha 1925 Ext. Materials Vindows Domestic: Single-family Windows Date 1925 Residence Property Type Domestic: single-family Windows Structural System No. of Stories 1 Bungalow Craftsman Structural System Wood frame No. of Stories 1 No. of Stories 1 Residence Proch Property Type Domestic: single-family Bungalow Doors Style Craftsman No. of Stories 1 Style <t< th=""><th>and the second second</th><th>Date</th><th>1940</th><th></th><th>Alterations/Modifications</th></t<>	and the second	Date	1940		Alterations/Modifications
Property Type Domestic: single-family Plan Rectangular: massed Style No Style No. of Stories 1 Structural System Wood frame Rectangular: massed Dors Stiding glass doors added to side façade Priority High High Medium Vood Cross gable Exterior Materials Wood Address 111 Martha 1925 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Bungalow Style No. of Stories 1 No. of Stories 1 Structural System Wood frame Roof Style Cartisman Porch No. of Stories 1 Structural System Wood frame Roof Side gable		Current Use	Residence		
Plan Rectangular: massed No. Style No. Style No. of Stories 1 Structural System Wood frame Roof Cross gable View Vood Priority High Medium Low Address 1211 Martha 1925 Addition(s) Current Use Residence Property Type Domestic: single-family Bungalow Doors Style 1 No. of Stories 1 Property Type Domestic: single-family Windows Doors Doors Alterations Alterations Alterations Alterations Doors Alterations Doors Alterations Doors Property Type Domestic: single-family Windows Doors Porch Roof Structural System Wood frame Roof Stide gable		Property Type	Domestic: single-family		
Style No Style No. of Stories 1 Structural System Wood frame Roof Cross gable Priority High Medium Low Address 1211 Martha 1925 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Bungalow Doors Style No. of Stories No. of Stories 1 Windows Doors Proch Original supports replaced Address 1211 Martha 1925 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Bungalow Doors Style Craftsman No. of Stories 1 No. of Stories 1 No of Stories 1 Style gable Alterations Alterations Alterations Alterations Alterations		Plan	Rectangular: massed		
No. of Stories 1 Structural System Wood frame Roof Cross gable Priority High Medium Low Exterior Materials Wood Address 1211 Martha Date 1925 Current Use Residence Property Type Domestic: single-family Bungalow Doors Style Craftsman No. of Stories 1 No. of Stories 1 Structural System Wood Bungalow Doors Pich 1 Structural System Wood frame Roof Alterations Alterations Alterations Active Alterations Bungalow Doors Alterations Alterations Active Alterations Alterations Alterations		Style	No Style		
Structural System Wood frame Roof Cross gable Priority High Medium Low Address 1211 Martha 1925 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Windows Doors Style Craftsman No. of Stories 1 Structural System Wood frame Roof Side gable					
Roof Cross gable Priority High Medium Low Exterior Materials Wood Address 1211 Martha Date 1925 Alterations/Modifications Current Use Residence Domestic: single-family Windows Dors Plan Bungalow Craftsman Doors Doors Style Craftsman Porch Roof Structural System Wood frame Side gable Alterations Addring Oors Alterations Bunding Autorial system Autorial system Structural System Wood frame Alterations Alterations Alterations		•			
Priority High Medium Low Exterior Materials Wood Address 1211 Martha 1925 Alterations/Modifications Date 1925 Residence Ext. Materials Property Type Domestic: single-family Windows Doors Plan Style Craftsman Doors Doors No. of Stories 1 Wood frame Noof Alterations Structural System Side gable Side gable Alterations			Cross gable		
Date 1925 Alterations/Modifications Current Use Residence Domestic: single-family Windows Plan Bungalow Doors Doors Style Craftsman Porch No. of Stories Structural System Wood frame No. of gable Alterations/Modifications	Priority High Medium 🖌 Low	Exterior Materials	Wood		
Date 1925 Alterations/Modifications Current Use Residence Domestic: single-family Windows Plan Bungalow Doors Doors Style Craftsman Porch No. of Stories Structural System Wood frame No. of gable Alterations/Modifications					
Current Use Residence Property Type Domestic: single-family Bungalow Doors Ctaftsman Porch No. of Stories 1 Structural System Wood frame Roof Alterations Addition(s)					
Property Type Domestic: single-family Plan Bungalow Style Craftsman No. of Stories 1 Structural System Wood frame Roof Side gable	A CARLES OF AND A CARLES			_	Alterations/Modifications
Property Type Domestic: single-family Bungalow Bungalow Style Craftsman No. of Stories 1 Structural System Wood frame Roof Side gable				Ext. Materials	
Plan Bungalow Style Craftsman No. of Stories 1 Structural System Wood frame Roof Side gable					
Style Craftsman Porch No. of Stories 1 Roof Structural System Wood frame Alterations Roof Side gable Addition(s)			-		
Structural System Wood frame Roof Side gable Alterations		-			
Roof Side gable Alterations Addition(s) Addition(s)					
Addition(s)		-		Alterations	
Priority High V Medium Low Exterior Materials Wood		Roof	Side gable		
		Frederican Martin 1.1	M/n nd	Addition(5)	

	Address	202 E. Marvin		
A A A A A A A A A A A A A A A A A A A	Date	1936		Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exterior walls re-clad w/asbestos shingles
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	Historic age side façade additions
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Asbestos; Wood		
	Address	413 E. Marvin		
	Date Current Use	1935 Residence		Alterations/Modifications
			Ext. Materials	
	Property Type Plan	Domestic: single-family Rectangular: massed	Windows	
	Style	No Style	Doors	
Standing of the standing of the set	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
Priority High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	907 E. Marvin		
	Date	1943		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family		Exterior walls re-clad
	Plan	Bungalow	Windows	
	Style	No Style	Doors	Death prote channel lettice added
And and a second second	No. of Stories	1	Roof	Porch posts changed, lattice added
be the strange of the	Structural System	Wood frame	Alterations	
and the second	Roof	Front gable	Addition(s)	
<i>Priority</i> High Medium	Exterior Materials	Asbestos	Addition(3)	
KULT AND AND A	Address	1204 E. Marvin	r	
	Date	1920		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family	Windows	
AND THE FULLY	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	Historic age porch enclosures
		1 Wood fromo	Roof	
and the second se	Structural System	Wood frame Complex (Side gable; Hipped; Shed)	Alterations	
Priority High ✔ Medium Low	Roor Exterior Materials	Wood	Addition(s)	
Priority High 🖌 Medium Low				
	Address	1311 E. Marvin		
	Date	1942		
A CONTRACTOR OF THE OWNER	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
And the second	-	Cross gable	Alterations	
<i>Priority</i>	Exterior Materials	Asbestos	Addition(s)	

Date 1915 Atterations/Modifications Current Use Residence Property Type Domestic single-family Property Type Domestic single-family Windows Doors Style Caffaman Porch Roof Style Side gable, Hipped Atterations Addition(s) Windows Exterior Materials Vinyl Addition(s) Style Colin Revival Roof Style Colin Revival No. of Stories 1 Style Colin Revival Roof Priority High Medium Low Address 606 W. Marvin Style Colin Revival Roof Crass gable Addition(s) Priority High Medium Low Address 606 W. Marvin Date 1944 Residence Porch Roof Style
Current Use Residence PriorityHigh Imeguar PriorityHigh Omestic: single-family Windows Doors Style Craftsman PriorityHigh Medium Low Address Structural System Wood frame Roof Stepable; Hipped Address Soft W. Marvin Date 1951 Address Software Priority High Priority High Priority High No. of Stories 1 Bate 1951 Current Use Religious Priority High No. of Stories 1 Style Gotnic Revival Porch Religious Priority High Priority High Priority High No. of Stories 1 Structural System Dade Bate 1944 Current Use Residence Propery
Property Type Domestic: single-family Windows Priority □ High Medium Low Priority □ High Medium Low Address 501 W. Marvin Address Bis 501 W. Marvin Address Current Use Religious Exterior Materials Priority □ High Medium Low Address 501 W. Marvin Address Date 1951 Atterations Current Use Religious Ext. Materials Priority □ High Medium Low Priority □ High Medium Low Priority □ High Medium Low Address 606 W. Marvin Borit Structural System Incelipous Address Brick Brick Exterior Materials Windows Exterior Materials Brick Mindows Education building added c. 1957 Address 606 W. Marvin Borits Date 1944 Education building added c. 1957 Mindows
Plan Irregular Doors Style Crafisman 2 Priority High Medium Low Address 501 W. Marvin Style Current Use Priority High Medium Address 501 W. Marvin Address 501 W. Marvin Address 501 W. Marvin Bate 1951 Current Use Religious Priority High Modum Low Address 501 W. Marvin Bate 1951 Current Use Religious Priority High No. of Stories 1 Style Gothic Revival No. of Stories 1 Structural System Cores gable Brick Brick Current Use Residence Property Type Residence Doors Exterior Materials Brick Irregular Current Use Residence Property Type Domestic: single-family Plan
Style Craftsman 2 No. of Stories 2 2 Priority High Medium Low Address 501 W. Marvin Address 501 W. Marvin Current Use Religious Priority High Medium Low Address 501 W. Marvin Date 1951 Current Use Religious Property Type Religious Piority High Medium Low Style Cotic Revival No. of Stories 1 Load-bearing masonry Roof Atterations Address Brick 506 W. Marvin Corss gable Address Address 606 W. Marvin Bate 1944 Current Use Residence Property Type Residence Property Type Irregular Style Colonial Revival; Ranch No. of Stories 1 Style Colonial Revival; Ranch No. of Stories
No. of Stories 2 Proren Structural System Wood frame Roof Roor Side gable; Hipped Address Priority High Medium Low Address 501 W. Marvin Date 1951 Current Use Religious Property Type Property Type Priority High Medium Low Address 501 W. Marvin Date 1951 Current Use Religious Property Type Religious Property Type Cothic Revival No. of Stories 1 Structural System Code-bearing masonry Cross gable Address Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows 1 Irregular Doors Doors Porch No. of Stories 1 No. of Stories 1 Styte Colonial Revival; Ranch
Structural System Wood frame Alterations Priority High Medium Low Side gable; Hipped Addition(s) Address S01 W. Marvin Address S01 W. Marvin Addition(s) Address S01 W. Marvin Address S01 W. Marvin Address S01 W. Marvin Adterations/Modifications Property Type Religious Ext. Materials Windows Property Type Coriss gable Address Soft Revival Profity ♥ High Medium Low Exterior Materials Exterior Materials Priority ♥ High Medium Low Address 606 W. Marvin Address 606 W. Marvin Exterior Materials Ext. Materials Ext. Materials Windows Date 1944 Extended Revival; Ranch Doors Poperty Type Demstic: single-family Pina Irregular Doors Poperty Type Domstic: single-family Pina Mitonows Doors Poperty Type Domstic: single-family Pina Materials Mitonows Doors
Roof Side gable; Hipped Addition(s) Priority High Medium Low Exterior Materials Vinyl Addition(s) Image: Structural System Address 501 W. Marvin Address Ext. Materials Atterations/Modifications Priority High Medium Low Religious Ext. Materials Windows Doors Property Type Religious Doors Doors Porch No. of Stories 1 Structural System Load-bearing masonry Roof Address Roof Cross gable Brick Brick Address Address Modelum Low Address 606 W. Marvin Address Address Bate 1944 Exterior Materials Brick Ext. Materials Windows Date 1944 Iregular Atterations/Modifications Ext. Materials Windows Date 1944 Iregular Structural System Structural System Doors Doors
Priority High Medium Low Exterior Materials Vinyl Address 501 W. Marvin 1951 Alterations/Modifications Date 1951 Alterations/Modifications Current Use Religious Ext. Materials Property Type Religious Bain Plan Irregular Doors Style Gothic Revival Porch No. of Stories 1 Roof Structural System Load-bearing masonry Alterations Addition(s) Education building added c. 1957 Address 606 W. Marvin Address Date 1944 Alterations/Modifications Address 606 W. Marvin Exterior Materials Date 1944 Exterior Materials Vindows Doors Ext. Materials Property Type Domestic: single-family Irregular No. of Stories 1 Structural System No. of Stories 1 No of Stories Structural System Structural System Doors No. of Stories 1 No of Stories<
Address 501 W. Marvin Date 1951 Current Use Religious Property Type Religious Bate 1951 Current Use Religious Property Type Religious Bate 1951 No. of Stories 1 Structural System Load-bearing masonry Rot Cross gable Structural System Load-bearing masonry Rot Cross gable Address 606 W. Marvin Date 1944 Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Plan Irregular Style Colnial Revival; Ranch No. of Stories 1 Style Colnial Revival; Ranch Porch Residence Property Type Colnial Revival; Ranch Roof Alterations Active Residence Porch Roof Roof Acture Roys main Roof
Date 1951 Current Use Religious Property Type Religious Plan Irregular Style Gothic Revival No. of Stories 1 Structural System Cross gable Brick Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows Ext. Materials Vindows Ext. Materials Brock Domestic: single-family Property Type Domestic: single-family Windows Doors Porch Roof Style Colonial Revival; Ranch Porch Roof Atterations Atterations Address 1
Current Use Religious Property Type Religious Plan Irregular Style Gothic Revival No. of Stories 1 Structural System Load-bearing masonry Roof Cross gable Priority ♥ High Medium Low Exterior Materials Brick Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows Doors Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows Doors Style Colonial Revival; Ranch No. of Stories 1 Style Colonial Revival; Ranch Roof Alterations Actor Roof Atterations Alterations Actor Alterations Actor Alterations Doors Alterations
Current Use Religious Property Type Religious Plan Irregular Gothic Revival Doors Porch 1 Structural System Load-bearing masonry Rof Cross gable Priority P High Medium Low Exterior Materials Brick Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows Irregular Object Object No. of Stories 1 Style Colonial Revival; Ranch Porch No. of Stories Style Colonial Revival; Ranch No. of Stories 1 Residence Porch Pian Irregular Colonial Revival; Ranch Roof Adterations Alterations Actor Roof Atterations Alterations Actor Roof Cross gable Alterations <t< td=""></t<>
Property Type Keligious Plan Irregular Style Gothic Revival No. of Stories 1 Structural System Load-bearing masonry Roof Cross gable Exterior Materials Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows
Plan Irregular Joors Style Gothic Revival Doors No. of Stories 1 Roof Structural System Load-bearing masonry Alterations Roof Cross gable Addition(s) Exterior Materials Brick Addition(s) Address 606 W. Marvin Education building added c. 1957 Address 606 W. Marvin Education building added c. 1957 Date 1944 Alterations/Modifications Current Use Residence Ext. Materials Property Type Domestic: single-family Windows Date 1944 Alterations/Modifications Style Colonial Revival; Ranch Doors No. of Stories 1 Roof Structural System Wood frame Roof Alterations Alterations Brick Cross gable Alterations
Style Gothic Revival 1 No. of Stories 1 Load-bearing masonry Priority ▶ High Medium Low Address Goth W. Marvin Brick Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Windows Doors Style Colonial Revival; Ranch No. of Stories 1 Style Colonial Revival; Ranch No. of Stories 1 Style Colonial Revival; Ranch Roof Alterations Alterations Alterations
No. of Stories 1
Structural System Roof Load-bearing masonry Cross gable Alterations Priority ☑ High Medium Low Exterior Materials Brick Addition(s) Education building added c. 1957 Image: Structural System Address 606 W. Marvin 1944 Alterations/Modifications Image: Structural System Date 1944 Exterior Materials Exterior Materials Image: Structural System Date 1944 Exterior Materials Ext. Materials Image: Style Colonial Revival; Ranch Doors Doors Doors Image: Structural System Wood frame No. of Stories 1 Roof Structural System Wood frame Alterations Alterations Alterations Alterations Alterations Alterations
Roof Cross gable Priority High Medium Low Exterior Materials Brick Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Irregular Doors Doors Doors Doors Porch No. of Stories 1 Structural System Wood frame Roof Cross gable
Priority High Medium Low Exterior Materials Brick Addition(s) Education building added c. 1957 Image: Structural System Address 606 W. Marvin 606 W. Marvin 1944 Alterations/Modifications Image: Structural System Does Structural System Doors for signed Doors for signed Ext. Materials Image: Structural System Wood frame 1 Moder frame Alterations Address Stable 1 Moder frame Alterations Address Moder frame Creater for signed Alterations Address Address Moder frame Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations Alterations
Address 606 W. Marvin Date 1944 Current Use Residence Property Type Domestic: single-family Irregular Doors Style Colonial Revival; Ranch No. of Stories 1 Structural System Wood frame Roof Alterations Alterations Alterations
Date 1944 Alterations/Modifications Current Use Residence Domestic: single-family Windows Plan Irregular Doors Doors Style Colonial Revival; Ranch 1 Porch No. of Stories 1 Wood frame Roof Structural System Wood frame Alterations/Modifications Roof Alterations/Modifications
Current Use Residence Property Type Domestic: single-family Plan Colonial Revival; Ranch Style Colonial Revival; Ranch No. of Stories 1 Structural System Wood frame Roof Alterations Alterations
Current Use Residence Property Type Domestic: single-family Plan Irregular Style Colonial Revival; Ranch No. of Stories 1 Structural System Wood frame Roof Alterations Addition(s) Addition(s)
Property Type Domestic: single-family Plan Irregular Style Colonial Revival; Ranch No. of Stories 1 Structural System Wood frame Roof Cross gable
Plan Irregular Doors Style Colonial Revival; Ranch Doors No. of Stories 1 Roof Structural System Wood frame Alterations Roof Cross gable Alterition(s)
Style Colonial Revival; Ranch No. of Stories 1 Structural System Wood frame Roof Alterations Addition(s)
No. of Stories 1 Structural System Wood frame Roof Alterations Addition(s)
Structural System Wood frame Alterations Roof Cross gable Addition(s)
Roof Cross gable Addition(s)
Priority 🖌 High 🗌 Medium 🗌 Low Exterior Materials Brick; Wood
Address 608 W. Marvin
Date 1942 Alterations/Modifications
Current Use Residence Ext. Materials Exterior walls re-clad w/vinyl siding
Property Type Domestic: single-family Windows Windows
Plan Rectangular: massed Doors
Style Colonial Revival Porch
No. of Stories 2 Roof
Structural System Wood frame
Roof Side gable
Priority High V Medium Low Exterior Materials Vinyl
Address 808 W. Marvin
Date 1942 Alterations/Modifications
Current Use Residence Ext. Materials
Property Type Domestic: single-family Windows
Plan Irregular Doors
Style Ranch: Minimal Traditional Porch
No. of Stories 1 Boof
Structural System Wood frame
Roof Cross gable Addition(s)
Priority High Medium Low Exterior Materials Brick; Wood

Aa	dress	175 McClain		
	Date	1905		Alterations/Modifications
Curre	ent Use	Residence		
Propert	у Туре	Domestic: single-family		Exterior walls re-clad
	Plan	Irregular		Original windows replaced
	Style	No Style	— Doors	
No. of S	Stories	1		Original porch replaced
Structural S	System	Wood frame	- Roof	
	Roof	Cross gable; Shed	— Alterations	
Priority 🗌 High 🗌 Medium 🖌 Low Exterior Ma	terials	Wood; Masonite	- Addition(s)	Has c. 1935 front addition
Aa	dress	409 N. Monroe		
	Date	1925		Alterations/Modifications
Curre	ent Use	Residence	First Masteriale	
Propert	у Туре	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		Original windows replaced
	Style	Craftsman	— Doors	
No. of S	Stories	1	- Porch	
Structural S	System	Wood frame	- Roof	
	Roof	Front gable	— Alterations	
Priority 🗌 High 🖌 Medium 🗌 Low Exterior Ma	terials	Wood	— Addition(s)	
Aa	dress	411 N. Monroe		
	Date	1925		Alterations/Modifications
Curre	ent Use	Residence	Ext. Materials	
Property	у Туре	Domestic: single-family	— Ext. Materiais — Windows	
	Plan	Bungalow	— Doors	
	Style	Craftsman	— Doors — Porch	
No. of S	Stories	1		
Structural S	System	Wood frame	— Roof — Alterations	
	Roof	Front gable		
Priority High V Medium Low Exterior Mai	terials	Wood	— Addition(s)	
			· · · · · · · · · · · · · · · · · · ·	
Aa	dress	426 N. Monroe		
	Date	1945		Alterations/Modifications
	ent Use	Residence	Ext Materials	Exterior walls re-clad w/vinyl siding
Propert	у Туре	Domestic: single-family	— Windows	
	Plan	Rectangular: massed	— Doors	
A CONTRACT OF A	Style	No Style		Original porch posts and flooring replaced
No. of S		1	- Roof	
Structural S	-	Wood frame	- Alterations	
	Roof	Hipped	- Addition(s)	
Priority High Medium V Low Exterior Ma	terials	Vinyl		
Aa	dress	112 Munchus		
	Date	1940		Alterations/Modifications
	ent Use	Residence	Ext. Materials	Exterior walls re-clad w/masonite
Property		Domestic: single-family	— Windows	
	Plan	Rectangular: massed	— Doors	
	Style	No Style		
No. of s		1		-
Structural S	-	Wood frame	- Alterations	
	Roof	Side gable; Shed		
Priority High Medium ✓ Low Exterior Ma	terials	Masonite		

	Address	114 Munchus		
	Date	1940		Alterations/Modifications
A State of the sta	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Bungalow	Doors	
	Style	No Style	Doors Porch	
	No. of Stories	1	Porch Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable		
Priority 🗌 High 📄 Medium ✔ Low	Exterior Materials	Wood	Addition(s)	Significant side addition
	Address	213 Murdock		
	Date	1905		Alterations/Modifications
	Current Use	Residence	Fut Matariala	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	L-Plan; Bungalow		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1		Original porch enclosed
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Wood	Addition(s)	L-plan w/ c. 1930 & 1955 additions
· - •			L	
and the second sec	Address	106 Odom		
	Date	1935		Alterations/Modifications
	Current Use	Residence	Fut Matariala	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		
	Style	Craftsman	Doors	
	No. of Stories	1.5	Porch	
	Structural System	Wood frame	Roof	
Ramo	Roof	Side gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	
beer the second	Address	202 Old Howard Road		
	Date	1915		Alterations/Modifications
	Current Use	Residence	Ext Motoriala	
The star with the star	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		
	Style	Mission Revival	Doors Porch	
Louis and Louis and the second	No. of Stories	1	Porch Roof	
	Structural System	Wood frame	Alterations	
the second s	Roof	Hipped	Alterations Addition(s)	
Priority 🖌 High 🗌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	327 Old Howard Road		
	Date	1915		Alterations/Modifications
	Current Use	Residence	Fyt Materials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family		Some original windows replaced
	Plan	Irregular	Doors	
	Style	No Style		Original porch posts and flooring replaced
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped	Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Vinyl	Addition(S)	

	Address	501 Oldham		
	Date	1935		Alterations/Modifications
	Current Use	Residence	E (M (, i))	
	Property Type	Domestic: single-family		Exterior walls partially re-clad w/masonite
	Plan	Bungalow	Windows Doors	
	Style	Craftsman	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
<i>Priority</i>	Exterior Materials	Wood; Masonite	Addition(6)	
	Address	113 Opal	[
Lordan Lordan	Date	1920		Alterations/Modifications
the second secon	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
and the second	No. of Stories	1	Roof	
and the second	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped; Shed	Addition(s)	Has a rear shed-roof addition
Priority High Medium 🖌 Low	Exterior Materials	Vinyl		
	Address	115 Opal		
	Date	115 Opal 1940		
A CONTRACTOR OF A CONTRACTOR O	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	Exterior walls re-clad w/asbestos shingles
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1		Original porch posts replaced
The second s	Structural System	Wood frame	Roof	
and the second se	Roof	Hipped	Alterations	
Priority ☐ High	Exterior Materials	Asbestos	Addition(s)	
	Address	205 Opal		
All and a second s	Date	1935		Alterations/Modifications
	Current Use	Vacant		
	Property Type	Domestic: single-family		Exterior walls re-clad w/ asphalt roll
	Plan	Rectangular: massed		Windows boarded-up w/plywood panels
	Style	No Style	Doors Porch	
	No. of Stories	1	Roof	
The second s	Structural System	Wood frame	Alterations	
	Roof	Hipped	Addition(s)	
<i>Priority</i> High Medium ✔ Low	Exterior Materials	Asphalt (composition) roll	Addition(3)	
and the second	Address	205 Overhill Drive		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	Classical Revival	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
		Side gable	Addition(s)	
Priority High V Medium Low	Exterior Materials	Brick		

	Address	508 E. Parks		
	Date	1935	_	Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exterior walls re-clad w/asbestos shingles
	Property Type	Domestic: single-family	- Windows	
	Plan	Irregular	— Doors	
	Style	No Style	- Porch	
	No. of Stories	1	- Roof	
	Structural System	Wood frame	Alterations	
	Roof	Complex - hipped	- Addition(s)	
Priority 🗌 High 🗌 Medium 🔽 Low	Exterior Materials	Asbestos		
	Address	505 -507 W. Parks		
	Date	1935		
Contract of the second of the	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: multiple-family		Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow	— Windows	
	Style	Craftsman	— Doors	
	No. of Stories	1	– Porch	
	Structural System	Wood frame	- Roof	
	Roof	Side gable	 Alterations 	
<i>Priority</i>	Exterior Materials	Asbestos	— Addition(s)	
· · · · · · · · · · · · · · · · · · ·			L	
	Address	? Parks School House Road		
	Date	1910		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Bungalow	— Doors	
	Style	Queen Anne	- Porch	
The second se	No. of Stories	1	- Roof	
The second second second second second	Structural System	Wood frame	- Alterations	
	Roof	Front gable	- Addition(s)	
Priority High V Medium Low	Exterior Materials	Wood		
	Address	207 Pasley		
	Date	1944		· · · · · · · · · · · · · · · · · · ·
	Current Use	Residence	_	Alterations/Modifications
		Domestic: single-family		Exterior walls re-clad w/masonite
	Plan	Bungalow		Original windows replaced
	Style	No Style	— Doors	
	No. of Stories	1		Original porch posts replaced
	Structural System	Wood frame	— Roof — Alterations	
and the second	Roof	Side gable	Alterations Addition(s)	
<i>Priority</i> ☐ High	Exterior Materials	Masonite	Addition(3)	
	Address	? Patrick Road		
	Date	1915	_	Alterations/Modifications
	Current Use	Vacant	Ext. Materials	
	Property Type	Domestic: single-family	— Windows	
And the second second second second second	Plan	Rectangular: massed	— Doors	
	Style No. of Stories	National Folk	- Porch	
and an	No. of Stories Structural System	Wood frame	- Roof	
		Hipped	— Alterations	
Priority High V Medium Low	Exterior Materials	Wood	— Addition(s)	
			L	

a state and	Address	? Patrick Road		
	Date	1915		Alterations/Modifications
	Current Use	Vacant	Ext Motoriala	Exterior walls re-clad
	Property Type	Domestic: single-family	– Ext. Materials – Windows	
THE REAL PROPERTY AND A DECIMAL OF THE REAL PROPERT	Plan	Rectangular: linear (2-room	– Doors	
	Style	Folk Victorian	- Porch	
and the second	No. of Stories	1	- Roof	
	Structural System	Wood frame	- Alterations	
	Roof	Cross gable	- Addition(s)	
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Asbestos; Metal		
		044 D		
	Address Date	214 Pecan 1940		
	Current Use	Residence	_	Alterations/Modifications
	Property Type	Domestic: single-family	— Ext. Materials	Exterior walls re-clad w/vinyl siding
	Plan	Irregular	— Windows	Window openings infilled/windows replaced
	Style	No Style	— Doors	
	No. of Stories	1	- Porch	New porch posts and flooring added
	Structural System	Wood frame	– Roof	
11	Roof	Hipped	 Alterations 	
Priority 🗌 High 🗌 Medium 🖌 Low	Exterior Materials	Vinyl	— Addition(s)	
			L	
	Address	304 Perry Street		
	Date	1941		Alterations/Modifications
	Current Use	Vacant		
	Property Type	Domestic: single-family	— Ext. Materials — Windows	Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow	— Willdows — Doors	
	Style	No Style	- Porch	
	No. of Stories	1	- Roof	
	Structural System	Wood frame	— Alterations	
	Roof	Front gable	- Addition(s)	Has a rear addition
Priority High Medium 🖌 Low	Exterior Materials	Asbestos	`	
	Address	206 Dorne Street		
	Date	306 Perry Street 1940	_	
The second second second	Current Use	Residence	_	Alterations/Modifications
		Domestic: single-family	— Ext. Materials	
	Plan	Bungalow	— Windows	
	Style	No Style	— Doors	
	No. of Stories	1	- Porch	
	Structural System	Wood frame	- Roof	
	Roof	Front gable	 Alterations Addition(s) 	
Priority High Medium 🖌 Low	Exterior Materials	Wood	- Addition(s)	
STATE CONTRACT	Address	302 Peters		
the second second	Date	1939		Alterations/Modifications
	Current Use	Vacant	Ext. Materials	Exterior walls re-clad w/asbestos shingle
	Property Type	Unknown	- Windows	
	Plan	Irregular	– Doors	
	Style	No Style	- Porch	
A REAL PROPERTY AND A REAL	No. of Stories	1 Wood frame	— Roof	
	Structural System	Wood frame	- Alterations	
Priority ☐ High	Roof Exterior Materials	Cross gable Asbestos	Addition(s)	Large addition

	Address	205 Picket		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Matorials	Exterior walls replaced w/aluminum siding
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority 🗌 High 🗌 Medium 🗹 Low	Exterior Materials	Aluminum		
	Address	209 Pickett		
	Date	1936		A 1/ // /B # 1/P //
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed		Some original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
<i>Priority</i>	Exterior Materials	Wood	Addition(s)	
There are a second s	Address	501 N. Rogers		
MARKEN CARACTER	Date	1925		Alterations/Modifications
and a second sec	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan	Bungalow	Doors	
	Style	Craftsman	Porch	·
Concession of the second second	No. of Stories	1	Roof	
Contraction of the second s	Structural System	Wood frame	Alterations	
Priority High 🖌 Medium 🗌 Low	Roof Exterior Materials	Cross gable	Addition(s)	
Priority High 🖌 Medium 🗌 Low		Wood		
11	Address	602 N. Rogers		
	Date	1935		Alterations/Modifications
	Current Use	Residence		
		Domestic: single-family		Exterior walls re-clad w/ vinyl
	Plan	Bungalow		Original windows replaced
	Style	Craftsman	— Doors Borch	
	No. of Stories	1	Porch	Porch supports replaced
	Structural System	Wood frame	Alterations	
Stational A	Roof	Front gable	Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Vinyl	, (0)	
The second s	Address	502 S. Rogers		
	Date	1940 Decidence		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Property Type Plan	Domestic: single-family	Windows	
	Plan Style	Bungalow No Style	Doors	
	No. of Stories	1	Porch	Original porch posts and flooring replaced
	Structural System	Wood frame	Roof	
Manual and the second	-	Side gable	Alterations	
Priority ☐ High Medium Low	Exterior Materials	Vinyl	Addition(s)	
, _ , _ ,				

	Address	602 S. Rogers		
A A A A A A A A A A A A A A A A A A A	Date	1942		Alterations/Modifications
	Current Use	Commercial		
HAH GROCERT	Property Type	Commercial	Ext. Materials	
	Plan	Rectangular: massed		Bars on windows
	Style	No Style	Doors	
	No. of Stories	1	Porch	
A street because the second	Structural System	Wood frame	Roof	
Contraction of the second s	Roof	Side gable w/ shed addition at back	Alterations	
Priority 🗌 High 🗹 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	708 S. Rogers		
	Date	1920		Alterations/Modifications
	Current Use	Residence		Alterations/modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	Window openings altered, original windows
	Style	National Folk	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
And sugar	-		Alterations	
	Roof	Hipped	Addition(s)	
Priority High 🖌 Medium Low	Exterior Materials	Wood		
	A dalama a	1010 C. Damas		
	Address	1010 S. Rogers		
	Date	<u>1935</u>		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Bungalow	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority High 🖌 Medium 🗌 Low	Exterior Materials	Wood	()	
	Address	1017 S. Rogers		
	Date	1942		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	No Style		Porch posts and roof replaced
		1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Hipped		Carport Added
<i>Priority</i>	Exterior Materials	Stucco	Addition(6)	
C. S.	Address	1023 S. Rogers		
A CHAM "	Date	1925		Alterations/Modifications
	Current Use	Residence	Ext Matorials	Exterior walls re-clad w/vinyl
	Property Type	Domestic: single-family	Windows	/
	Plan	Bungalow	Doors	
	Style	Craftsman	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame		
	Roof	Side gable	Alterations	
<i>Priority</i>	Exterior Materials	Vinyl	Addition(s)	

	Address	1025 S. Rogers		
	Date	1925		Alterations/Modifications
Server the first state	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Bungalow	Doors	
	Style	No Style		
	No. of Stories	1		Original porch posts and hand rails replaced
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	1111 S. Rogers		
A CALL AND A	Date	1935		Alterations/Modifications
	Current Use	Residence	Ext. Materials	· · · · · · · · · · · · · · · · · · ·
	Property Type	Domestic: single-family	Windows	
	Plan	Gable-Front-and Wing	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(3)	
	Address	1200 S. Rogers		
the second strends	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family		All original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	No Style		Porch posts replaced
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Vinyl		
	Address	214 E. Ross		
	Date	1935		
	Current Use	Residence		Alterations/Modifications
		Domestic: single-family	Ext. Materials	Exterior walls re-clad w/asbestos
		- · ·	Windows	
	Plan Style	Bungalow No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Asbestos	Addition(s)	
	Address	312 E. Ross		
	Date	1942		Alterations/Modifications
A CONTRACT OF	Current Use	Residence		
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed		
and the second s	Style	No Style	Doors	
	No. of Stories	1	Porch	
Care and the second	Structural System	Wood frame	Root	
	-	Side gable	Alterations	
<i>Priority</i>	Exterior Materials	Wood	Addition(s)	

Date 1944 Atterations/Modifications Priority Extended Biogram Extended		Address	505 E. Ross		
Currant Use Readons Property Property Printly High Property Readence Proper	CAR A A CONTRACTOR	Date	1944		Alterations/Modifications
Property Type Domestic single family Windows Priority I High Madum V Low No Style No Style Proch Perch Parth pasts and not replaced Priority I High Madum V Low Mood fame Rood Address Sole pasts Priority I High Madum V Low Address Sole pasts Address Address Priority I High Madum V Low Address Sole pasts Address Address Priority I High Madum V Low Address Sole pasts Address Address Priority I High Madum V Low Address Sole pasts Address Address Priority I High Madum V Low Address Sole pasts Address Address Priority I High Madum I Low Address Sole family Materations/Modifications Etail High Property Type Address Address </th <th></th> <th>Current Use</th> <th>Residence</th> <th></th> <th></th>		Current Use	Residence		
Plan Bungdow Doors Priority High Madum Low Structural System Wood farms Roof Structural System Maxmila Address SdS gible Priority High Madum Low Address SdS E Ross Address SdS E Ross Address SdS E Ross Priority High Madum Low Address SdS E Ross Priority High Madum Low Address SdS E Ross Priority High Madum Low Address SdS E Ross Priority High Modum Low Address SdS E Ross Structural System Wood farm Rod Address SdS E Ross Priority High Modum Low Address SdS E Ross Priority High Modum Low Address SdS E Ross Priority High Modum Low Address SdS E Ross Priority High Modum Exterior Materials Mood farms Struc		Property Type	Domestic: single-family		
Syle No Syle Park		Plan	Bungalow		
No. 07 Stories 1 Structural System Address		Style	No Style		
Priority High Medium Image: Constructure System Address Address <t< th=""><th></th><th>No. of Stories</th><th>1</th><th></th><th></th></t<>		No. of Stories	1		
Priority High Medium I.cv Exterior Meanish Machine Address Massile Address Sould Address Sould Sould Address Address Address Sould Sould Address Address Address Sould Sould Address Address Structural System Rectangular massed Windows One oniginal window changed Doors Priority High Medium Low Exterior Meaning Address One Signal window changed Priority High Medium Low Exterior Meaning Mode fame Address One Signal window changed Address One Signal window changed Doors Address One Signal window changed Address One Signal window	A CONTRACTOR OF A CONTRACTOR OFTA CONTRACTOR O	Structural System	Wood frame		
Priority		Roof	Side gable		
Date 1944 Atterations/Modifications Current Use Readence Property Type Demestic: single-family Priority High Medium Low Koof Storkes 1 Readence Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Structural System Modified from Residence Property Type Denestic: single-family Priority High Medium Low Address 603 E. Ross Atterations/Modifications Priority High Medium Low Address 603 E. Ross Atterations/Modifications Priority High Medium Low Address 603 E. Ross Atterations/Modifications Priority High High Medium Low Address 603 E. Ross Atterations/Modifications Priority High High High High Low Address 603 E. Ross </th <th><i>Priority</i> ☐ High</th> <th>Exterior Materials</th> <th>Masonite</th> <th>Addition(3)</th> <th></th>	<i>Priority</i> ☐ High	Exterior Materials	Masonite	Addition(3)	
Date 1944 Atterations/Modifications Current Use Readence Property Type Demestic: single-family Priority High Medium Low Koof Storkes 1 Readence Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Priority High Medium Low Address 601 E. Ross Atterations/Modifications Structural System Modified from Residence Property Type Denestic: single-family Priority High Medium Low Address 603 E. Ross Atterations/Modifications Priority High Medium Low Address 603 E. Ross Atterations/Modifications Priority High Medium Low Address 603 E. Ross Atterations/Modifications Priority High High Medium Low Address 603 E. Ross Atterations/Modifications Priority High High High High Low Address 603 E. Ross </th <th></th> <th></th> <th></th> <th></th> <th></th>					
Current Use Residence Priority Type Domastic: single-family Priority Type No Style Priority Thigh Medium I tow Priority Thigh Residence Priority Thigh Medium I tow Priority Thigh <th></th> <th>Address</th> <th></th> <th> _</th> <th></th>		Address		_	
Property Type Demestic: single-family Ext. Materials Windows Oce original window changed Style No Style Priority High Madium Priority High Madium View Steg gabe: Shed Address Sub gabe: Shed Property Type Demestic: single-family Pinty High Madium Priority High No Shy Property Type Demestic: single-family Mindows Chiginal windows replaced Doors Style No of Stories Structural System No Shyle No of Stories Property Type Demestic: single-family Mindows Porint <td< th=""><th></th><th></th><th></th><th></th><th>Alterations/Modifications</th></td<>					Alterations/Modifications
Property Type Densett:::strige-family Windows One sciginal window changed Plan: Retaingular: massed Doors Porch Style No. of Strikes 1 Structural System Mood fame Addition(s) Priority High Medium Low Exterior Materials Wood Address 60 f Steg gabe; Shed Addition(s) Addition(s) Address 60 f Residence Porch Addition(s) Priority High Medium No Address OD Energite: Stringe-family Priority High Medium No Structural System Wood Address Priority High Medium Low Exterior Materials Wood Doors Priority High Medium Low Address Stog Engle-family Doors Priority High Medium Low Exterior Materials Wood Doors Priority High Medium Low Exterior Materials Wood Doors Priority High Medium Low				Ext. Materials	
Prior Prior <td< th=""><th></th><th></th><th></th><th></th><th></th></td<>					
Syle No. Style Parch Rod Structural System Wood frame Rod Briority High Medium Low Address 601 E. Ross Address 601 E. Ross Date 1944 Alterations Address 601 E. Ross Date 1944 Alterations Address 601 E. Ross Date 1944 Alterations/Modifications Priority High Medium Low Address 601 E. Ross Bate 1944 Domestic: single-family Windows replaced Dors Priority High No. of Stories Torth Roof Roof Style No. of Stories Stuctural System Wood frame Alterations/Modifications Priority High Medium Low Address 603 E. Ross Address Bate Date 1944 Exterior Materials Mood frame Address Priority High Medium Low Address 603 E. Ross Address Bate Damestic: single-family Bungalow No Style <th></th> <th></th> <th></th> <th></th> <th>-</th>					-
No. of Stories 1 Briority High Medium Low Priority High Medium Low Address 601 E. Ross Address Date 1944 Alterations/Modifications Current Use Besidence Property Type Date 1944 Alterations/Modifications Priority High Medum Current Use No. of Stories 1 Structural System Wood frame No. of Stories 1 Structural System Wood frame No. of Stories 1 Structural System Wood frame Roof Font gable Alterations/Modifications Zureuru Use Roof Font gable Alterations/Modifications Priority High Medum Low 603 E. Ross Alterations/Modifications Bard 1944 Exterior Materials Wood Alterations/Modifications Priority High Medum No No Style No Property Type Domestic: single-family Bungalow Doors Porch Roof<	and the second s	-	No Style		
Structural System Wood frame Alterations Addition(s) Priority High Medium Low Exterior Materials Wood Address 601 E. Ross Date 1944 Alterations/Modifications Priority High Medium Low Style No. of Structural System Current Use Priority High Medium Low Style No. of Structural System Wood frame Priority High Medium Low Exterior Materials Wood Exterior Materials Priority High Medium Low Address 603 E. Ross Exterior Materials Address Priority High Medium Low Address 603 E. Ross Ext. Materials Ext. Materials Ext. Materials Mindows Priority High Medium Low Address 603 E. Ross Ext. Materials Ext. Materials Ext. Materials Ext. Materials Ext. Materials Mindows Doors Doors Doors Proch Proch Address 607 E. Address 607 E. Mindows	A CONTRACTOR OF A CONTRACTOR O				
Roof Side gable; Shed Addition(s) Priority High Medium Low Exterior Materials Wood Address 601 E. Ross Date 1944 Atterations/Modifications Priority High Current Use Residence Ext. Materials Windows Priority High Medium Low Style No Style Porch Priority High Medium Low Exterior Materials Wood Ext. Materials Priority High Medium Low Exterior Materials Wood Ext. Materials Priority High Medium Low Exterior Materials Wood farme Roof Front gable Address 603 E. Ross Ext. Materials Date 1944 Exterior Materials Exterior walls re-clad Windows Style No Style Doors Ext. Materials Properity Tigable No Style No Style Doors Priority High Medium Low Exterior Materials Mood farme Roof Front gable Kof Strones Style No Style No of Stories Style No Style No Style Ext. Materia		Structural System			
Priority High Medium Low Address 601 E. Ross Date 1944 Date Atterations/Modifications Current Use Residence Froeprity Type Donestic: single-family Priority High Medium Low Atterations/Modifications Priority High Medium Low Exterior Materials Mindows Priority High Medium Low Atterations/Modifications		Roof	Side gable; Shed		
Date 1944 Atterations/Modifications Current Use Residence Property Type Domestic single-family Priority High Ext. Materials Windows replaced Priority High No of Stories 1 Roof Roof Front gable Exterior Materials Wood Address 603 E. Ross Address Address Date 1944 Current Use Residence Priority High Medium Low Address Model 603 E. Ross Address Address Date 1944 Current Use Residence Priority High Medium Low Prine Burgalow Address Style No Style No Style Prine Burgalow Doors Priority High Medium Low Prine Burgalow Doors Style No Style No Style Prine Burgalow Doors Style No of Stories 1 Roof Address Briority High Medium Current Use Residence <th><i>Priority</i> High Medium ✔ Low</th> <th>Exterior Materials</th> <th>Wood</th> <th>, idunion(o)</th> <th></th>	<i>Priority</i> High Medium ✔ Low	Exterior Materials	Wood	, idunion(o)	
Date 1944 Atterations/Modifications Current Use Residence Property Type Domestic single-family Priority High Ext. Materials Windows replaced Priority High No of Stories 1 Roof Roof Front gable Exterior Materials Wood Address 603 E. Ross Address Address Date 1944 Current Use Residence Priority High Medium Low Address Model 603 E. Ross Address Address Date 1944 Current Use Residence Priority High Medium Low Prine Burgalow Address Style No Style No Style Prine Burgalow Doors Priority High Medium Low Prine Burgalow Doors Style No Style No Style Prine Burgalow Doors Style No of Stories 1 Roof Address Briority High Medium Current Use Residence <th></th> <th></th> <th></th> <th></th> <th></th>					
Current Use Residence Property Type Domestic: single-family Priority High Medium Current Use Residence Priority High Medium Low Style Priority High Medium Low Style Priority High Medium Low Address Materations Modifications Address Address 603 E. Ross Address Darestic: single-family Modi Address Priority High Medium Low Address 603 E. Ross Extention Materations Darestic: single-family Modifications Ext. Materations/Modifications Current Use Residence Properly Type Domestic: single-family No. of Stories 1 Priority High Medium Current Use Priority High Medium Current					
Property Type Domestic: single-family Ext. Materials Bungalow Style No Style Style No Style Porch Roof Front gable Address Briority High Medium Low Address 603 E. Ross Address Date Exterior Materials Wood Address 603 E. Ross Addition(s) Darrestic: single-family Pilan Bungalow Structural System Style No dof frame Roof Front gable Address Date 1944 Exterior Materials Current Use Residence Property Type Property Type Domestic: single-family Doors Plan Bungalow Doors Style No of Stories 1 Structural System Wood frame Address Property High Medium Low Address 607 E. Ross Address Date 1935 Ext. Materials Vindows Original windows replaced Doors					Alterations/Modifications
Plan Bungalow Bungalow Doors Style No. of Stories 1 Prortig No. of Stories Prortigable Priority High Medium Low Exterior Materials Wood frame Addition(s) Address 603 E. Ross Date 1944 Alterations Addition(s) Address 603 E. Ross Date 1944 Alterations/Modifications Current Use Residence Prorth Bungalow Doors Bungalow Style No. of Stories 1 Style Porch Roof Address 603 E. Ross Date Ext. Materials Exterior walls re-clad Windows Doors Doors Bungalow Doors Style No. of Stories 1 Structural System Wood frame Roof Front gable Alterations Addition(s) Addition(s) Windows Low Exterior Materials Vinyl; Corrugated fiberglass Addition(s) Address 607 E. Ross 1935 Alterations/Modifications Ext. Materials Property Type				Ext. Materials	
Plan Bungalow No. Style No. Style Priority High Medium Low Exterior Materials Wood Front gable Address 603 E. Ross Date Structural System Wood Front gable Address 603 E. Ross Date Structural System Vint Current Use Property Type Doors Doors Alterations/Modifications Ext. Materials Exterior walls re-clad Windows Doors Doors Ext. Materials Style No. Style Porch Porch No. of Stories 1 Structural System Wood frame Front gable Vint; Corrugated fiberglass Vint; Corrugated fiberglass Alterations/Modifications Ext. Materials Modition(s) Prorth High No. of Stories 1 No. of Stories 1 No. of Stories 1 Style No. of Stories Style <th></th> <th></th> <th></th> <th>Windows</th> <th>Original windows replaced</th>				Windows	Original windows replaced
No. of Stories 1 Roof Roof Roof Alterations Priority High Medium Low Address 603 E. Ross Addition(s) Addition(s) Image: Structural System Wood Wood Image: Structural System Model Address Addition(s) Image: Structural System Model Address 603 E. Ross Exterior Materials Address Exterior Materials Address Structural System Address Structural System Address Structural System Model Ext. Materials Ext. Materials Ext. Materials Mindows Diate Property Type Diate Structural System No. of Stories Structural System Mode frame Roof Address Address GOT E. Ross Address GOT E. Ross Address GOT E. Ross Exterior Materials Modelines Ext. Materials Modelines Ext. Materials Modelifications Ext. Materials Modelifications Ext. Materials Address GOT E. Ross Address GOT E. Ross Ext. Materials Modelifications Ext. Materials Modelifications Ext. Materials Modifications Ext. Ma					
Structural System Wood frame Roof Priority High Medium Low Exterior Materials Wood Address 603 E. Ross Date 1944 Atterations/Modifications Current Use Residence Ext. Materials Exterior walls re-clad Windows Property Type Domestic: single-family Wood frame Roof No. of Stories 1 Structural System Wood frame Roof Address 607 E. Ross Address Orrerity High Medium Low Address 607 E. Ross Address 607 E. Ross Date 1935 Atterations/Modifications Current Use Residence Domestic: single-family Address 607 E. Ross Date 1935 Current Use Residence Ext. Materials Windows orglaced Property Type Domestic: single-family Windows Orginal door replaced Doors Orginal door replaced Property Type Domestic: single-family Windows Orginal door replaced Porch Roof Address 607 E. Ross Style <th></th> <th>•</th> <th>· · · · · · · · · · · · · · · · · · ·</th> <th>Porch</th> <th></th>		•	· · · · · · · · · · · · · · · · · · ·	Porch	
Priority High Medium Low Low Address 603 E. Ross Address Bate 1944 Alterations/Modifications Current Use Residence Ext. Materials Exterior walls re-clad Priority High Medium Low No. 61 Stories 1 Structural System No. of Stories 1 Structural System Porch Priority High Medium Low Address 607 E. Ross Address 607 E. Ross 1935 Alterations/Modifications Priority High Medium Low Address 607 E. Ross Bargalow Style No. of Stories 1 Alterations/Modifications Priority High Medium Low Exterior Materials Vinyl: Corrugated fiberglass Address 607 E. Ross 1935 Ext. Materials Mindows replaced Property Type Domestic: single-family Windows Original windows replaced Dors No. of Stories 1 Structural System No. of Stories 1 Nof No. of Stories </th <th></th> <th></th> <th></th> <th> Roof</th> <th></th>				Roof	
Priority High Medium Low Exterior Materials Wood Addition(s) Address 603 E. Ross Date 1944 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Ext. Materials Exterior walls re-clad Priority High Medium No. of Stories 1 Ext. Structural System No. of Stories 1 Structural System Wood frame Alterations Alterations Priority High Medium Low Exterior Materials Viny; Corrugated fiberglass Alterations/Modifications Materials Vinglow Structural System Wood frame Alterations Addition(s) Address 607 E. Ross 1935 Exterior Materials Mindows replaced Bit Mindows replaced Property Type Domestic: single-family Plan Burgalow Structural System Structural System Koof No. of Stories 1 Structural System No. of Stories 1 Structural System Ext. Materials Ext. Materials Property Type Domestic: single-family	The second secon	-		Alterations	
Address 603 E. Ross Date 1944 Current Use Residence Property Type Domestic: single-family Plan Bungalow Style No. of Stories Structural System Wood frame Roof Fronty Compatibility Priority High Medium Low Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Windows				Addition(s)	
Date 1944 Current Use Residence Property Type Domestic: single-family Bungalow Style No. of Stories 1 Structural System Wood frame Roof Front gable Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Windows Mood frame Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Bungalow No. of Stories Style No. of Stories Style No. of Stories Date 1935 Current Use Residence Property Type Domestic: single-family Windows Original windows replaced Porch No. of Stories Style No. of Stories Property Type Domestic: single-family Windows Original door replaced Porch Roof Sty	Priority High V Medium Low	Exterior Materials	Wood		
Date 1944 Current Use Residence Property Type Domestic: single-family Bungalow Style No. of Stories 1 Structural System Wood frame Roof Front gable Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Windows Mood frame Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Bungalow No. of Stories Style No. of Stories Style No. of Stories Date 1935 Current Use Residence Property Type Domestic: single-family Windows Original windows replaced Porch No. of Stories Style No. of Stories Property Type Domestic: single-family Windows Original door replaced Porch Roof Sty		Address	603 E Poss		
Current Use Residence International modulications Property Type Domestic: single-family Ext. Materials Exterior walls re-clad Windows No Style No Style Doors Priority High Medium Low Keterior Materials Exterior Materials Vinyl: Current Use Residence Plan Bungalow Doors Priority High Medium Low Keterior Materials Vinyl: Corrugated fiberglass Vinyl: Current Use Residence Porch Porch enclosed Address 607 E. Ross 1 Addition(s) Addition(s) Vinyl: Current Use Residence Domestic: single-family Adterials Windows Original windows replaced Doors Original windows replaced Property Type Domestic: single-family Windows Original windows replaced Porch No. of Stories 1 Roof Roof Style No. of Stories 1 Roof Adterials Windows Original windows replaced Porch Roof Adterations					
Property Type Domestic: single-family Ext. Materials Exterior walls re-clad Windows No Style No Style Doors Priority High Medium No Style No Style Priority High Medium Low Exterior Materials Vinyl; Corrugated fiberglass Address 607 E. Ross Date 1935 Alterations/Modifications Current Use Residence Property Type Domestic: single-family Windows Plan Bungalow Style No Style Address Dores Current Use Residence Ext. Materials Windows Original windows replaced Doors Original door replaced No. of Stories 1 Structural System Wood frame Roof Structural System Wood frame Address Address 1 Stide gable Address Address					Alterations/Modifications
Plan Bungalow Doors Style No Style Doors Priority High Medium I Priority High Medium I Address 607 E. Ross Date 1935 Current Use Residence Property Type Doors Park Medium No. of Stories 1 Structural System Vinyl; Corrugated fiberglass Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Windows Original windows replaced Doors Original windows replaced No. of Stories 1 Style No Style No. of Stories 1 Structural System Wood frame Roof Site gable				Ext. Materials	Exterior walls re-clad
Style No Style Doors Priority High Medium No. of Stories 1 Priority High Medium Low Koof Front gable Vinyl; Corrugated fiberglass Vood frame Addition(s) Addition(s) Vinyl; Corrugated fiberglass 607 E. Ross 1 Date 1935 Alterations/Modifications Current Use Residence Exterior Materials Property Type Domestic: single-family Windows Plan Bungalow Doors Style No. Style Porch No. of Stories 1 No. Style No. of Stories 1 Roof Structural System Wood frame Porch Roof 1 Stories Structural System Wood frame Alterations Roof Stie gable Addition(s)				Windows	
No. of Stories 1 Porch Porch enclosed Structural System Wood frame Roof Priority High Medium Low Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Windows Original windows replaced No. of Stories 1 No. of Stories 1 Style No. Style No. of Stories 1 Windows Original windows replaced Doors Original door replaced Porch Roof Alterations Alterations Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Windows Original windows replaced Doors Original door replaced Porch Roof Structural System Wood frame Side gable Addition(s)					
Structural System Wood frame Alterations Priority High Medium Low Exterior Materials Vinyl; Corrugated fiberglass Addition(s) Address 607 E. Ross Date 1935 Alterations/Modifications Current Use Residence Exterior Sigle-family Windows Original windows replaced Plan Bungalow No. of Stories 1 Structural System Orod frame No. of Stories 1 Structural System Wood frame Alterations/Modifications Structural System Wood frame Style No. of Stories Alterations Address 607 E. Ross Date Ext. Materials Ext. Materials Vindows Original windows replaced Doors Original door replaced No. of Stories 1 Structural System Wood frame Roof Side gable Alterations Alterations		•			
Roof Front gable Alterations Priority High Medium Low Exterior Materials Vinyl; Corrugated fiberglass Addition(s) Address 607 E. Ross Jate 1935 Alterations/Modifications Date 1935 Date 1935 Alterations/Modifications Property Type Domestic: single-family Windows Original windows replaced Plan Bungalow No. of Stories 1 Roof Structural System Wood frame No difference Alterations Side gable Side gable Addition(s) Alterations	and the Allingham and the Alli				
Priority High Medium Low Exterior Materials Vinyl; Corrugated fiberglass Addition(s) Address 607 E. Ross 1935 1935 Alterations/Modifications Date 1935 Residence Ext. Materials Original windows replaced Property Type Domestic: single-family Windows Original windows replaced No. of Stories 1 No Style Original door replaced No. of Stories 1 No of frame Alterations Structural System Wood frame Side gable Alterations Addition(s) Image: Structural System No of frame Alterations		-			
Address 607 E. Ross Date 1935 Current Use Residence Property Type Domestic: single-family Bungalow Original windows replaced No. of Stories 1 Style No Style No. of Stories 1 Structural System Wood frame Roof Side gable	Priority High Medium ✓ Low		-	Addition(s)	
Date 1935 Alterations/Modifications Current Use Residence Domestic: single-family Windows Original windows replaced Plan Bungalow No Style Original door replaced Original door replaced No. of Stories 1 Wood frame No of gable Alterations/Modifications Structural System No of gable Alterations/Modifications Doess Alterations/Modifications Original windows replaced Doess Original door replaced Buod frame Stide gable Alterations Alterations	• • •			L	
Current Use Residence Property Type Domestic: single-family Bungalow Original windows replaced Style No. of Stories 1 Wood frame Wood frame Roof Stile gable		Address	607 E. Ross		
Property Type Domestic: single-family Undextication Plan Bungalow Original windows replaced Style No. style Original door replaced No. of Stories 1 Roof Structural System Wood frame Alterations Roof Side gable Alterations		Date	1935		Alterations/Modifications
Property Type Domestic: single-family Bungalow Bungalow Style No Style No. of Stories 1 Structural System Wood frame Roof Side gable		Current Use	Residence	Ext Matariala	
Plan Bungalow Style No Style No. of Stories 1 Structural System Wood frame Roof Alterations Addition(s)		Property Type	Domestic: single-family		
Style No. Style No. of Stories 1 Structural System Wood frame Roof Alterations Side gable Addition(s)		Plan			
No. of Stories 1 Structural System Wood frame Roof Alterations Addition(s)		Style	No Style		
Structural System Wood frame Alterations Roof Side gable Addition(s)			1		
Roof Side gable Addition(s)		-			
Priority High Medium Low Exterior Materials Wood					
	Priority 🔄 High 🖌 Medium 📋 Low	Exterior Materials	Wood		

Date 1940 Alterations/Modifications	
Allefations/wiounications	
Current Use Residence Ext. Materials Exterior walls reclad w/brick & as	hestos
Property Type Domestic: single-tamily Windows	
Plan Bungalow Doors	
Style No Style Parch	
No. of Stories 1 Roof	
Structural System Wood frame Alterations	
Roof Cross gable Addition(s)	
Priority High Medium V Low Exterior Materials Brick; Asbestos	
Address 1505 W. Ross	
Dut. 1005	
Date 1935 Alterations/Modifications Current Use Residence Texture tite	
Property Type Domestic: single-family Ext. Materials	
Plan Bungalow Windows	
Style No Style Doors	
No. of Stories 1	
Structural System Wood frame Root	
Roof Side gable Alterations	
Priority □ High ✔ Medium □ Low Exterior Materials Wood Addition(s)	
Address 201 Rousseau	
Date 1935 Alterations/Modifications	
Current Use Residence Ext. Materials Asbestos & plywood added to extended to exte	terior
Property Type Domestic: single-family Windows	
Plan Bungalow Doors	
Style No Style Parch par	
No. of Stories	
Structural System Wood frame Alterations	
Roof Front gable Addition(s)	
Priority High Medium V Low Exterior Materials Asbestos; Plywood Panels	
Address 202 Rousseau	
Dut. 1000	
Date 1920 Alterations/Modifications Current Use Residence Extended	
Property Type Domestic: single-family Ext. Materials	
Plan Rectangular: massed Windows	
Style No Style	
No of Stories 1	
Structural System Wood frame Roof	
Roof Front gable Alterations	
Priority High Medium Low Exterior Materials Wood Addition(s)	
Address 412 Royal	
Date 1925 Alterations/Modifications	
Current Use Residence Ext. Materials	
Property Type Domestic: single-family Windows	
Plan Bungalow Doors	
Style Craftsman Parch	
No. of Stories 1 Structural System Workform	
Structural System Wood frame Alterations	
Roof Front gable Priority High Medium Low Exterior Materials Wood	
Priority High V Medium Low Exterior Materials Wood	

No. 10	Address	505 Royal		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> ☐ High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	202 Stephens		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority ☐ High	Exterior Materials	Wood	Addition(s)	
	Address	? E. Sterrett Road		
	Date	1935		Alterations/Modifications
	Current Use	Commercial		
	Property Type	Commercial	Ext. Materials	
	Plan	Irregular	Windows	
	Style	No Style	Doors	
	No. of Stories	1.5	Porch	
	Structural System	Metal frame	Root	
	Roof	Front gable	Alterations	
Priority ☐ High	Exterior Materials	Metal panel	Addition(s)	
	Address	201 -206 Sterrett Road		
	Date	1945		Alterations/Modifications
	Current Use	Residence		
		Domestic: single-family		Exterior walls re-clad w/ asbestos shingle
	Plan	Rectangular: linear	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	-	Side gable	Alterations	
<i>Priority</i> ☐ High Medium Low	Exterior Materials	Asbestos	Addition(s)	
	Address	131 E. Sterrett Road		
and the second se	Date	1905		Alternatione /Mandificatione
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
		L-Plan	Windows	Windows replaced w/aluminum frame units
	Style	No Style	Doors	
	No. of Stories	1	Porch	New porch added
	Structural System	Wood frame	Root	
	-	Cross gable	Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	

	Address	140 E. Sterrett Road		
	Date	1890		Alterations/Modifications
	Current Use	Vacant		
A CONTRACT OF A	Property Type	Domestic: single-family	Ext. Materials	
THE PARTY OF THE PARTY	Plan	Irregular		
The second s	Style	Queen Anne	Doors	
	No. of Stories	2	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority 🗹 High 🗌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	409 Sycamore		
	Date	1939		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
and the second s	Plan	Gable-Front-and Wing	Windows Doors	
	Style	No Style		
We I	No. of Stories	1	Porch	
-	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> High ✓ Medium Low	Exterior Materials	Wood	Addition(s)	
A CALL AND A	Address	411 Sycamore		
	Date	1942		Alterations/Modifications
	Current Use	Residence	Ext Materials	
	Property Type	Domestic: single-family		Exterior walls re-clad w/vinyl
	Plan	Irregular		Original windows replaced
And the second s	Style	Colonial Revival	Doors	
	No. of Stories	2	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable		
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Vinyl	Addition(s)	
and the second sec	Address	500 Sycamore	·	
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl
	Property Type	Domestic: single-family		
	Plan	Irregular	Doors	
	Style	Colonial Revival	Porch	
	No. of Stories	2	Roof	
—	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
<i>Priority</i> High ✔ Medium Low	Exterior Materials	Vinyl		
	Address	510 Sycamore		
	Date	1940		Alterations/Modifications
	Date Current Use	1940 Residence	Ext. Materials	
	Date Current Use Property Type	1940 Residence Domestic: single-family	Ext. Materials	
	Date Current Use Property Type Plan	1940 Residence Domestic: single-family Irregular		
	Date Current Use Property Type Plan Style	1940 Residence Domestic: single-family Irregular Colonial Revival		
	Date Current Use Property Type Plan Style No. of Stories	1940 Residence Domestic: single-family Irregular Colonial Revival 2	Windows Doors	
	Date Current Use Property Type Plan Style No. of Stories Structural System	1940 Residence Domestic: single-family Irregular Colonial Revival 2 Wood frame	Windows Doors Porch	
	Date Current Use Property Type Plan Style No. of Stories Structural System Roof	1940 Residence Domestic: single-family Irregular Colonial Revival 2 Wood frame Side gable	Windows Uoors Porch Roof Alterations	
Priority High ✓ Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System	1940 Residence Domestic: single-family Irregular Colonial Revival 2 Wood frame	Windows Uoors Porch Roof	

	Address	607 Sycamore		
	Date	1930		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan	Irregular	Doors	
	Style	Tudor Revival		
	No. of Stories	2		
	Structural System	Wood frame	Alterations	
	Roof	Complex	Addition(s)	
Priority 🗹 High 🗌 Medium 🗌 Low	Exterior Materials	Brick; Wood		
	A dalama a	C10 Current		
	Address	610 Sycamore		
	Date	1940		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type Plan	Domestic: single-family	Windows	
	Style	Irregular Minimal Traditional	Doors	
THE REAL PROPERTY OF THE PARTY	No. of Stories	2	Porch	
	Structural System	2 Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> ☐ High ✔ Medium ☐ Low	Exterior Materials	Brick	Addition(s)	
	Address	700 Sycamore		
	Date	1940		Alterations/Modifications
	Current Use	Residence		
100	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular		Original windows replaced
	Style	Minimal Traditional		Original front door replaced
	No. of Stories	2	Porch	
	Structural System	Wood frame	Roof Alterations	
	Roof	Cross gable	Addition(s)	
Priority 🗌 High 📄 Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address	1411 Sycamore		
	Date	1942		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family	Windows	
	Plan	Irregular	Doors	
	Style	No Style	Porch	Porch supports replaced
	No. of Stories	1 Wood from a	Roof	
and the second se	Structural System	Wood frame	Alterations	
Priority High Medium V Low	Roof Exterior Materials	Cross gable	Addition(s)	
Priority High Medium V Low		<u>viiiyi</u>		
	Address	? Tyler Drive (Highway 77)		
	Date	1935		
	Current Use	Vacant		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
The second second	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
		Side gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(s)	

	Address	? Tyler Road (Cardinal)		
	Date	1910		Alterations/Modifications
and the second s	Current Use	Vacant	Ext. Materials	
ALL SE	Property Type	Domestic: single-family		
	Plan	Rectangular: linear	Doors	
	Style	National Folk		
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority 🗌 High 🔲 Medium ✔ Low	Exterior Materials	Wood		
A PARTY A PARTY AND A PARTY	Address	426 E. University		
	Date Current Use	1920 Residence		Alterations/Modifications
			Ext. Materials	
	Property Type Plan	Domestic: single-family Irregular	Windows	
	Style	Craftsman	Doors	
	No. of Stories	1	Porch	
A DESCRIPTION OF THE OWNER	Structural System	Wood frame	Roof	
	•	Complex	Alterations	
Priority ☐ High ✔ Medium ☐ Low	Exterior Materials	Wood	Addition(s)	
	Address	203 W. University		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular		Some original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i>	Exterior Materials	Wood	Addition(3)	
and the second second	Address	319 W. University		
	Date	1925		Alterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
		Domestic: single-family		Original windows replaced
		Bungalow	Doors	
	Style	Craftsman	Porch	Porch supports replaced
	No. of Stories Structural System	1 Wood fromo	Roof	
	-	Wood frame Front gable	Alterations	
Priority ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood	Addition(s)	Lattice (wood) on porch; shutters
	Address	324 W. University		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
the second se	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
		Bungalow		
	Style	No Style	Doors	
	No. of Stories	1		Porch supports replaced
	Structural System	Wood frame	Roof	
	-	Front gable	Alterations	
<i>Priority</i>	Exterior Materials	Asbestos	Addition(s)	
· · · · · · · · · · · · · · · · · · ·				

Constant States	Address	22 US Highway 77		
CONTRACTOR TO A	Date	1905		Alterations/Modifications
	Current Use	Religious	Fort Matariala	
	Property Type	Domestic: single-family		Original exterior materials replaced Original windows replaced
	Plan	L-Plan		Original doors replaced
	Style	No Style		Porch posts replaced
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Wood		
	Address	1317 Waller		
	Date Current Use	1905 Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Property Type Plan	L-Plan	Windows	Windows replaced w/aluminum frame units
	Style	No Style	Doors	
	No. of Stories	1	Porch	Rear porch enclosed
and the second sec	Structural System	Wood frame	Roof	
	Roof	Cross gable w/shed-roof rear wing	Alterations	
Priority High Medium 🖌 Low	Exterior Materials	Vinvl	Addition(s)	
	Address	400 Water		
	Date	1942		Alterations/Modifications
	Current Use	Commercial		
THE SHOP	Property Type	Commercial	Ext. Materials	
	Plan	Irregular		Original windows replaced
	Style	No Style	Doors	
a manufacture of the last of the	No. of Stories	1	Porch Roof	
the second s	Structural System	Load-bearing masonry	Alterations	
and the second second second second	Roof	Flat	Addition(s)	
<i>Priority</i> ☐ High	Exterior Materials	Concrete Block	Addition(3)	
	Address	1020 Water		
	Date	1930		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family	Windows	Original windows replaced
	Plan	Bungalow	Doors	
	Style	No Style	Porch	Original porch supports replaced
	No. of Stories Structural System	1 Wood frame	Roof	
1	Roof	Hipped	Alterations	
Priority High ✔ Medium Low	Exterior Materials	Wood	Addition(s)	
	Address	1022 Water		
	Date	1942		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations Addition(s)	
Priority 🗌 High 🗌 Medium 🖌 Low	Exterior Materials	Wood	Audition(S)	

Open 1900 1900 Alterations/Modifications Priority International Modifications Ext. Materials Ectator will so clud Priority International Modifications Ext. Materials Ectator will so clud Priority International Modifications Ext. Materials Ectator will so clud Priority International Modifications Ext. Materials actual Priority International Modifications Ext. Materials actual Priority International Modifications Ext. Materials Materials Priority International Modifications Ext. Materials	and the second	Address	1024 Water		
Current Use Residence Property Type Densets: cangle-family Priority I High Modium I Low Address 22 Villams Address 22 Villams Priority I High Modium I Low Priority I High Modium I Low Address 22 Villams Address 20 Villams Address 20 Villams Address 10 of 32 kines Structural System Vood fame Address 19 Vipit Addre		Date	1930		Alterations/Modifications
Property Type Comments:::rigit=family Windows Priority Construction Style Style Doors Priority Construction Model Style Mode Style Doors Priority Construction Model Style Model Style Proch Restandantial Mesonic Construction Address 80/2 Ministrict Priority Construction Address 80/2 Ministrict Address Priority Construction Address 80/2 Ministrict Address Priority Construction Model Style Ministrict Ministrict Ministrict Priority Construction Ministrict Ministrict Ministrict Ministrict <td>A CONTRACTOR OF A CONTRACTOR OF</td> <td>Current Use</td> <td>Residence</td> <td></td> <td></td>	A CONTRACTOR OF	Current Use	Residence		
Plan Rectangular massed Doors No. of Stories 1 Perch Priorty High Modum Low Priorty High Modum Low Address 822 Williams Moort fame Priorty High Modum Low Address 822 Williams Moort fame Priorty High Modum Low Address 822 Williams Exterior Materials Macronic Use Residence Priorty Priorty High Modum Low Priorty		Property Type	Domestic: single-family		
Style No Style Parch No. of Stories 1 Structural System Wood frame Priority High Medium Widdim Loar Address 802 Williams Date 1840 Structural System 1 Date 1832 Current Use 1832 Current Use 1832 Current Use 1832 Current Use 1000 Structural System 102 Wait Date 1647 Date 1647 Date 1647 Date		Plan	Rectangular: massed		
No. 05 Stores Structures System No. 05 Stores Atterations Priority High Medium Low Atterations Atterations Priority High Medium Low Stores 1 Stores Atterations Priority High Medium Low Stores 1 Stores 1 Priority High Medium Low Exterior Materials Wood Atterations 2 Priority High Medium Low Atterations 2 2 Atterations Priority High Medium Low Atterations 2 2 2 <td< th=""><th></th><th>Style</th><th>No Style</th><th></th><th></th></td<>		Style	No Style		
Briority High Medium Noco frame Alterations Addition(s) Priority High Medium No. Status Address 802 Williams Date 1940 Dates 1940 Alterations Address Priority High Medium Dates 1940 Alterations Address Priority High Medium Constructions Statistics Alterations Address 1940 Priority High Medium Constructions Address 1940 Alterations Modifications Priority High Medium Constructions Address 1940 Alterations Modifications Priority High Medium Constructions Address 1940 Alterations Address 1940 Priority High Medium Constructions Address 1940 Alterations Address Address 1940 Alterations Address Address 1000 Porch Address 1000 Porch Address 1000 Porch Address 10		No. of Stories	1		
Priority High Medium Low Address Sola 2 Wilams Address Sola 2 Wilams Address Sola 2 Wilams Address Sola 2 Wilams Address Sola 2 Wilams Current Use Date 1940 Atterations/Modifications Current Use Residence Promise: single family Promise: single family Priority High No. 61 Stories 1 Sola 2 Wilams Priority High Medium Low Sola 2 Wilams Address Priority High Medium Core Sola 2 Wilams Address Structural System Lod Sola 2 Wight Ext. Materations Addi		Structural System	Wood frame		
Priority High Medium Media Medium Medium		Roof	Cross/hipped		
Date 1940 Alterations/Modifications Eventual System Rectangler massed Boors Priority High Medium Low Address 19 Wyatt Address 19 Wyatt Alterations/Modifications Ext. Materials Mood Address 19 Wyatt Address 19 Wyatt Address 19 Wyatt Address 19 Wyatt Doors Ext. Materials Priority High Medium Low Address Priority High Medium Low Address Address 19 Wyatt Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Commercial Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Commercial Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Commercial Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Domestic single-family Mindows	<i>Priority</i>	Exterior Materials	Masonite	Addition(b)	
Date 1940 Alterations/Modifications Eventual System Rectangler massed Boors Priority High Medium Low Address 19 Wyatt Address 19 Wyatt Alterations/Modifications Ext. Materials Mood Address 19 Wyatt Address 19 Wyatt Address 19 Wyatt Address 19 Wyatt Doors Ext. Materials Priority High Medium Low Address Priority High Medium Low Address Address 19 Wyatt Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Commercial Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Commercial Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Commercial Bar Rectangler massed Doors Stole distinitied wiphywood Property Type Domestic single-family Mindows					
Current Use Residence Property Type Domestic: single-tamily Plan Rectangular: massed Style No. of Style No. of Style No. of Style Priority High Medium Priority High Medium Addressions Stegable Addressions Addressions Priority High Medium Priority High Medium Addressions Stegable Addressions Stegable Addressions Stegable Addressions Stegable Current Use Vacant Property Type Connercial Pala Rectangular: massed Style No. of Style No. of Style Style No. of Style <					
Property Type Demestic: single-family Ext. Materials Priority High No. of Stories 1 Priority High Modium Low Priority					Alterations/Modifications
Property Type Dornestic: single-terminy Windows Plane Rectangular: massed Dors Style No. of Storie 1 Roof Priority High Medium Low Exterior Materials Wood frame Alterations Addition(e) Alterations Addition(e) Priority High Medium Low Exterior Materials Wood Address 19 Wyatt Date Date Address Priority High Medium Low Exterior Materials Wood Address 19 Wyatt Date Date Date Date Property Type Commercial massed Date Date Date Date Property Type Commercial massed Date				Ext. Materials	
Style No. of Stories 1 Dors Parch Priority High Medium Low Side gable Aldressions Addressions Priority High Medium Low Addressi 19 Wyatt Addressions Priority High Medium Low Addressions 19 Wyatt Addressions Priority High Medium Low Addressions 19 Wyatt Addressions Priority High Medium Low Addressions 19 Wyatt Addressions Priority High Medium Low No Style Porch Rod Priority High Medium Low State 10 Wyatt Addression Priority High Medium Low State 1942 Addression Priority High Medium Low State 1942 Addression Current Use Rectangular massed State 1942 Addression Addression Property Type Doestic: single-family Mediation(s) Doors Por					
No. of Stories 1 Prich Structural System Wood frame Roof Roof Atterstions Address Priority High Medium Low Address 19 Wydatt Address Date 1335 Atterations/Modifications Priority High Medium Low Address 19 Wydatt Atterations/Modifications Priority High No Style No Style Property Type Commercial Property Type Structural System No Style No Style No. of Stories 1 Roof Structural System Load-beering masonry Atterations/Modifications Priority High Medium Low Address 102 Wydatt Atterations/Modifications Roof Structural System No Style No. of Stories 1 Atterations/Modifications Property Type Commercial Roof Stories Structural System No Style No Style No. of Stories 1 Stories <t< td=""><td></td><td></td><td></td><td> Doors</td><td></td></t<>				Doors	
Structural System Wood frame Roof Atterations Priority High Medium Low Atterations Addition(s) Addition(s) Address 19 Wyatt Address Address Address Image: Structural System No of Structural System Address Address Address Image: Structural System Address 19 Wyatt Ext. Materials Mindows Priority High Nedium Low Vacant Ext. Materials Windows Priority High Medium Low Structural System No Style Dores Steleight infilied wiplywood Prointy High Nedium Low Exterior Materials Stucco Address Mindows Exterior Materials Stucco Address 1942 Address Address Priority High Medium Low Exterior Materials Windows Ext. Materials Mindows Priority High Medium Low Exterior Materials Wood Ext. Materials Mindows Priority High </td <td></td> <td>-</td> <td></td> <td> Porch</td> <td></td>		-		Porch	
Roof Side gable Address Priority High Medium Low Address 19 Wyatt Address Jate 1935 Atterations/Modifications Current Use Vacant Property Type Commercial Priority High Medium Low Rectangular: massed Doors Style No Style No Style Porch Roof Priority High Medium Low Address 102 Wyatt Windows Exterior Materials Stuccural System Commercial Windows Priority High Medium Low Address 102 Wyatt Address 102 Wyatt Exterior Materials Exterior Materials Modifications Priority High Medium Low Residence Property Type Current Use Prostry Type Dones Style No Style Porch Rectangular: massed Doors Structural System Stockers 1 Stockers 1 Stockers 1 Rectangular: massed Doors Structural System Kod				Roof	
Priority High Medium Low Exterior Materials Wood Addition(s) Addition(s) Address 19 Wyett Date 1935 Alterations/Modifications Friority High Medium Low Rectangular. massed Dors Style Priority High Medium Low Exterior Materials Windows Dors Style Priority High Medium Low Exterior Materials Style Dors Style Materials Microard Alterations/Modifications Exterions Alterations Alterations Alterations Microard Dors Style No Style	DUC	-		Alterations	
Priority High Medium Cow Exterior Materials Wood Address 19 Wyatt Date 1935 Alterations/Modifications Exterior Materials Date 1935 Alterations/Modifications Exterior Materials Style No. of Stories Style No. of Stories Priority High Medium Low Exterior Materials Style No. of Stories Priority High Medium Low Exterior Materials Stuce Address Priority High Medium Low Exterior Materials Stuce Address Priority High Medium Low Exterior Materials Stuce Exterior Materials Priority High Medium Low Address 102 Wyatt Ext. Materials Date 1942 Current Use Residence Ext. Materials Windows Date 1942 Style No Style No Style No Style Property Type Domestic: single-family Phene Rectangular: massed Doors Ext. Materials M				Addition(s)	
Date 1935 Current Use Vacant Property Type Commercial Primercial Primercial Primercial No. of Stories Style No. Style Priority High Medium Low Address 102 Wyatt Date 1942 Current Use Vacant Residence Priority High Medium Viatural System Vacant Materials Structural System Vacant Materials Mindows Address 102 Wyatt Date Date 1942 Current Use Residence Property Type Doors Style No. Style Property Type Doors Structural System Wood frame Roof Side gable Exterior Materials Wood Vacant Vacant Property Type Religious Priority High Mediums Low Style No. of Stories	Priority High Medium Low	Exterior Materials	Wood		
Date 1935 Current Use Vacant Property Type Commercial Primercial Primercial Primercial No. of Stories Style No. Style Priority High Medium Low Address 102 Wyatt Date 1942 Current Use Vacant Residence Priority High Medium Viatural System Vacant Materials Structural System Vacant Materials Mindows Address 102 Wyatt Date Date 1942 Current Use Residence Property Type Doors Style No. Style Property Type Doors Structural System Wood frame Roof Side gable Exterior Materials Wood Vacant Vacant Property Type Religious Priority High Mediums Low Style No. of Stories		Addroop	10 Whight		
Current Use Vacant Property Type Commercial Printy High Rectangular.massed Doors Style No. Style No. of Stories 1 Structural System Load-bearing masonny Roof Flat Structural System Load-bearing masonny Address 102 Wyatt Based 1942 Current Use Residence Priority High Medium Low Address 102 Wyatt Bate 1942 Current Use Residence Property Type Onnestic: single-family Windows Doors Style No of Stories Structural System Wood frame Style No of Stories Priority High Windows Address Style No of Stories Priority High Middition(s) Mood Style No of Stories Priority High Mediums Low <td></td> <td></td> <td></td> <td></td> <td></td>					
Property Type Commercial Plan Rectangular: massed Style No Style No. of Stories 1 Structural System Load-bearing masonry Friority High Medium Low Address 102 Wyatt Bare 1942 Current Use Residence Prority High No. of Stories 1 Style No. of Stories Structural System Modeframe Style No. of Stories Priority High Medium Low Address 102 Wyatt Bare Dates Bare Style No. of Stories 1 Style No. of Stories Structural System Wood frame Address 201 Wyatt Bate 1944 Current Use Religious Prorch Religious Prorch Religious Property Type Religious Property Type Religious					Alterations/Modifications
Plan Rectangular: massed No Style No. of Stories 1 No of Stories 1 Priority High Medium Low Exterior Materials Stucco Address 102 Wyatt Style Address 102 Wyatt Address 102 Wyatt Dores Exterions/Modifications Current Use Residence Dores Ext. Materials Style No Style Dores Ext. Materials Property Type Dores Structural System Low Address Style No Style Dores Ext. Materials Property Type Dores Style No Style No of Stories 1 Residence Dores Style No Style No Style Porch No of Stories 1 Roof Atterations Style No of Stories 1 Roof Atterations Address 201 Wyatt Address Date 1944 Exterior Materials Mood Current Use Religious Ext. Materials Modifications <tr< td=""><td></td><td></td><td></td><td>Ext. Materials</td><td>1</td></tr<>				Ext. Materials	1
Style No Style Doors Stabelights intilled w/plywood Priority High Medium Low Low Filat Roof Address Stucco Stucco Address Address Address Address Priority High Medium Low Address 102 Wyatt Atterations Address 102 Wyatt Estenior Materials Stucco Stucco Atterations/Modifications Priority High Medium Low Address 102 Wyatt Est. Materials Minows Priority High Medium Low Address 102 Wyatt Est. Materials Mows Priority High Medium Low Residence Porch Roof Address Doors Style No Style Porch Roof Address Mindows Doors Porch Roof Roof Address Modor Porch Roof Address Address Modo Address Address Address Porch Roof Roof Roof Address Porch Roof				Windows	
No. of Stories 1 Roof Roof Alterations Priority High Medium Low Exterior Materials Stucco Addition(s) Priority High Medium Low Address 102 Wyatt Address Address Address 102 Wyatt Date 1942 Alterations/Modifications Exteriors/Modifications Priority High Medium No. of Stories 1 Rectangular: massed Doors Ext. Materials Windows Priority High Medium Low Exterior Materials Wood frame Alterations/Modifications Priority High Medium Low Exterior Materials Wood Addition(s) Priority High Medium Low Exterior Materials Wood Addition(s) Address 201 Wyatt Date 1944 Ext. Materials Modifications Property Type Religious Property Type Religious Ext. Materials Windows Doors No. of Stories 1 Inregular Doors North entry doors added				Doors	Sidelights infilled w/plywood
Priority High Medium Low Low Address 102 Wyatt Address 102 Wyatt 1942 Atterations/Modifications Address 102 Wyatt 1942 Atterations/Modifications Current Use Residence Ext. Materials Windows Priority High Medium Low Property Type Domestic: single-family Plan Rectangular: massed Doors Porch Roof Style No. of Stories 1 Structural System Address No. of Stories 1 Structural System Address Porch Roof Side gable Exterior Materials Mood Addition(s) Address 201 Wyatt Exterior Materials Addition(s) Addition(s) Address 201 Wyatt Date 1944 Atterations/Modifications Current Use Religious Property Type Religious Ext. Materials Property Type Religious Property Type Religious Date Proch No. of Stories 1 Style No. Style No </td <td></td> <td>-</td> <td></td> <td>Porch</td> <td></td>		-		Porch	
Roof Flat Alterations Priority High Medium Low Exterior Materials Stucco Address 102 Wyatt Address 102 Wyatt Date 1942 Alterations/Modifications Current Use Residence Ext. Materials Windows Property Type Domestic: single-family No. of Stories 1 Structural System No. of Stories 1 Structural System Wood frame Aldition(s) Priority High Medium Low Address 201 Wyatt Address 201 Wyatt Structural System Vood Alterations Address 201 Wyatt Alterations Addition(s) Modelium Low Address 201 Wyatt Alterations/Modifications Modelium Low Address 201 Wyatt Alterations/Modifications File No. of Stories 1 Structural System Date Ext. Materials Modelium Low Address 201 Wyatt Ext. Materials Modifications File No. Style No. St	and the second second			Root	
Priority High Medium Iow Exterior Materials Stucco Addition(s) Address 102 Wyatt 1942 Alterations/Modifications Current Use Residence Ext. Materials Windows Property Type Domestic: single-family Windows Doors Priority High Medium Cover No. of Stories Structural System Wood frame Alditerations Aldition(s) Priority High Medium Low Exterior Materials Wood Address 201 Wyatt 1944 Alterations Aldition(s) Address 201 Wyatt 1944 Alterations Aldition(s) Property Type Religious Irregular No Style No style Property Type Religious Irregular No Style No style Property Type No of Style No Style No Style No Style Property Type Religious Irregular Alterations Doors No of Stories 1 Load-bearing masonry Roof Alterations M	and the second			Alterations	
Address 102 Wyatt Date 1942 Current Use Residence Property Type Domestic: single-family Plan Rectangular: massed Style No. of Stories Structural System Wood frame Roof Side gable Address 201 Wyatt Date 1944 Alterations/Modifications Bate Style No. of Stories 1 Structural System Wood Religious Alterations/Modifications Property Type Demestic: single-family Windows Doors Porch Rectangular: massed Style No. of Stories Date 1944 Current Use Religious Property Type Religious Property Type Religious Pin Irregular No. of Stories 1 Style No Style No. of Stories 1 Load-bearing masonry Alterations	Priority High Medium V Low			Addition(s)	
Date 1942 Current Use Residence Property Type Domestic: single-family No. Style No. Style No. of Stories 1 Structural System Wood frame Roof Side gable Exterior Materials Wood Vood 1 Alterations/Modifications Ext. Priority High Medium Low Address 201 Wyatt Date Property Type Religious Religious Property Type Religious Irregular Doors No. of Stories 1 No. of Stories 1 No. of Stories 1 Date Property Type Religious Property Type No. Style No. Style Porch No. Style No. of					
Date 1942 Current Use Residence Property Type Domestic: single-family No. Style No. Style No. of Stories 1 Structural System Wood frame Roof Side gable Exterior Materials Wood Vood 1 Alterations/Modifications Ext. Priority High Medium Low Address 201 Wyatt Date Property Type Religious Religious Property Type Religious Irregular Doors No. of Stories 1 No. of Stories 1 No. of Stories 1 Date Property Type Religious Property Type No. Style No. Style Porch No. Style No. of		Address	102 Wyatt		
Current Use Residence Property Type Domestic: single-family Bin Rectangular: massed Style No Style No. of Stories 1 Structural System Wood frame Roof Side gable Exterior Materials Wood Address 201 Wyatt Date 1944 Current Use Religious Property Type Religious Property Type Religious Property Type Religious Bate 1944 Current Use Religious Property Type Religious Plan Irregular Style No Style Doors New front entry doors added Porch Roof Style No Style No. of Stories 1 Style No Style No. of Stories 1 Structural System Load-bearing masonry		Date			Alterations/Modifications
Property Type Domestic: single-family Windows Plan Rectangular: massed Doors Style No. Style Porch No. of Stories 1 Roof Structural System Wood frame Alterations Roof Structural System Wood Wood Exterior Materials Wood Vood Structural System No. of Stories Address 201 Wyatt Address Date 1944 Religious Property Type Religious Ext. Materials Property Type Religious Windows Property Type Religious Ext. Materials Property Type Religious Doors No. of Stories 1 No. Style No. of Stories 1 Load-bearing masonry Alterations Alderestics New front entry doors added Porch No. of Stories 1 Load-bearing masonry Alterations		Current Use	Residence	F (M) () ()	
Plan Rectangular: massed Style No Style No. of Stories 1 Structural System Wood frame Roof Side gable Wood Side gable Address 201 Wyatt 1944 Alterations/Modifications Current Use Religious Priority □ High No. of Stories Structural System No. of Stories Structural System 201 Wyatt Bate 1944 Current Use Religious Property Type Religious Plan Irregular No. of Stories 1 Style No. of Stories Structural System Load-bearing masonry Load-bearing masonry Alterations		Property Type	Domestic: single-family		
Style No Style No. of Stories 1 Structural System Wood frame Roof Side gable Priority High Medium Low Address 201 Wyatt Date 1944 Current Use Religious Property Type Religious Plan Irregular Style No Style No. of Stories 1 Style No Style Porch Religious Plan Irregular Style No Style No. of Stories 1 Style No Style No. of Stories 1 Structural System Load-bearing masonry Alterations Alterations		Plan	Rectangular: massed		
No. of Stories 1 Structural System Wood frame Roof Side gable Priority High Medium Low Address 201 Wyatt Date 1944 Current Use Religious Property Type Religious Property Type Religious Plan Irregular Style No. of Stories Style No. of Stories Style 1 No. of Stories 1 Structural System Load-bearing masonry		Style	No Style		
Structural System Wood frame Roof Side gable Alterations Priority High Medium Low Address Address Date 1944 Alterations/Modifications Current Use Religious Extender Mindows Property Type Religious Ext. Materials Windows Doors No Style Doors New front entry doors added No. of Stories 1 Load-bearing masonry Roof Alterations/Modifications Alterations/Modifications		No. of Stories	1		
Roof Side gable Addition(s) Priority High Medium Low Exterior Materials Wood Address 201 Wyatt Date 1944 Alterations/Modifications Date 1944 Eligious Ext. Materials Modifications Property Type Religious Religious Ext. Materials Windows Date No. of Stories 1 Doors New front entry doors added No. of Stories 1 Load-bearing masonry Alterations		Structural System	Wood frame		
Priority High Medium Low Exterior Materials Wood Address 201 Wyatt 1944 Alterations/Modifications Date 1944 Eligious Ext. Materials Property Type Religious Irregular Doors New front entry doors added No. of Stories 1 Load-bearing masonry Alterations		Roof	Side gable		
Date 1944 Alterations/Modifications Current Use Religious Ext. Materials Property Type Religious Windows Plan Irregular Doors New front entry doors added No. of Stories 1 Rod-bearing masonry Reof Alterations/Modifications Ext. Materials Windows Vo. of Stories 1 Redigious New front entry doors added Structural System Load-bearing masonry Alterations/Modifications	Priority High Medium ↓ Low	Exterior Materials	Wood	Addition(3)	
Date 1944 Alterations/Modifications Current Use Religious Ext. Materials Property Type Religious Windows Plan Irregular Doors New front entry doors added No. of Stories 1 Rod-bearing masonry Reof Alterations/Modifications Ext. Materials Windows Vo. of Stories 1 Redigious New front entry doors added Structural System Load-bearing masonry Alterations/Modifications					
Current Use Religious Property Type Religious Plan Irregular Style No Style No. of Stories 1 Structural System Load-bearing masonry					
Property Type Religious Plan Irregular Style No. of Stories Structural System 1 Load-bearing masonry Alterations	+				Alterations/Modifications
Property Type Religious Windows Plan Irregular Doors New front entry doors added No. of Stories 1 1 Roof Structural System Load-bearing masonry Alterations	and the second			Ext. Materials	1
Plan Irregular Style No Style No. of Stories 1 Structural System Load-bearing masonry					
Style No. Style No. of Stories 1 Structural System Load-bearing masonry					
No. of Stories 1 Structural System Load-bearing masonry					
Structural System Load-bearing masonry	and the second sec				
	Service in the service of the servic	-			
Roof Cross gable Addition(s)					
Priority High V Medium Low Exterior Materials Stone; Wood	riority 🔄 High 🗹 Medium 📋 Low	Exterior Materials	Stone; Wood		

	Address	604 Wyatt		
	Date	1944		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Irregular	Doors	
	Style	No Style	Porch	
- Part - 2 part - a p	No. of Stories	1		
and the second	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped	Addition(s)	
Priority 🗌 High 🗌 Medium 🔽 Low	Exterior Materials	Wood		
		005 144 - 14		
	Address	905 Wyatt		
	Date	1944 Desidence		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type Plan	Domestic: single-family	Windows	
	Style	Irregular No Style	Doors	
and the second s	No. of Stories	1	Porch	
and the second	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
			L	
	Address	1102 Wyatt		
and the second second	Date	1944		Alterations/Modifications
1	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Gable-Front-and Wing		One window has been replaced
	Style	No Style	Doors	
A second s	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof Roof	
and a second	Roof	Cross gable	Addition(s)	
<i>Priority</i> ☐ High	Exterior Materials	Wood	Addition(3)	
	Address	1200 Wyatt		
and the second and the second second	Date	1944		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
A CONTRACTOR OF A CONTRACTOR O		Domestic: single-family		
	Plan	Irregular	Doors	
and and an and the second of the second of	Style	No Style	Porch	
and the stand of the stand	No. of Stories Structural System	1 Wood frame	Roof	
	-	Cross gable	Alterations	
<i>Priority</i> High ✔ Medium Low	Roor Exterior Materials	Wood	Addition(s)	
	Address	1407 Wyatt (Cleaver)		
	Date	1940		
	Current Use	Vacant		Alterations/Modifications
	Property Type	Domestic: single-family		Exterior walls re-clad w/brick
	Plan	Rectangular: massed		Original window replaced w/ aluminum sash
	Style	No Style	Doors	
THE REAL PROPERTY AND ADDRESS	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
		Side gable	Alterations	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Brick	Addition(s)	

		Address	201 Young		
		Date	1940		Alterations/Modifications
STR-	N	Current Use	Residence	Ext Motoriala	Exterior walls re-clad w/masonite
		Property Type	Domestic: single-family		
		Plan	Bungalow	– Villdows – Doors	Original windows replaced
		Style	No Style	– Doors – Porch	
	And and and a state of the second	No. of Stories	1	- Porch Roof	
		Structural System	Wood frame	– Alterations	
		Roof	Front gable		
<i>Priority</i> 🗌 High	🗌 Medium 🗹 Low	Exterior Materials	Masonite	Addition(s)	
and a state of the		Address	202 Young		
A CAR	A A A A A A A A A A A A A A A A A A A	Date	1940		Alterations/Modifications
		Current Use	Residence	Ext. Materials	
		Property Type	Domestic: single-family		Aluminum sash windows added
		Plan	Bungalow	 Doors 	
C. C		Style	No Style		Original porch supports replaced
		No. of Stories	1	- Roof	
		Structural System	Wood frame	- Alterations	
		Roof	Front gable	- Addition(s)	
Priority 🗌 High	Medium 🖌 Low	Exterior Materials	Vinyl	Addition(3)	
. Alberta	BARREL AND	Address	205 Young		
		Date	1935	_	Alterations/Modifications
		Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl
		Property Type	Domestic: single-family	- Windows	
		Plan	Bungalow	- Doors	
		Style	No Style	- Porch	
	Justice of the strends	No. of Stories	1	- Roof	
		Structural System	Wood frame	- Alterations	
		Roof	Front gable	- Addition(s)	
Priority 🗌 High	Medium 🖌 Low	Exterior Materials	Vinyl		
A.	a state and	Address	207 Young		
A CARE NOV	And the second second	Date	1935	_	Alterations/Modifications
		Current Use	Residence	Ext. Materials	
			Domestic: single-family		Front aluminum & new frame
		Plan	Irregular	— Doors	
		Style	Craftsman; Minimal Traditional	- Porch	
	and the second second	No. of Stories	1	- Roof	
Carrier Data	Bit-EL	Structural System	Wood frame	- Alterations	
.		Roof		- Addition(s)	
Priority 🗌 High	Medium 🖌 Low	Exterior Materials	Wood		

Appendix B

Inventory of Post-World War II Neighborhoods

Almond Street Neighborhood

Located within the 100-200 blocks of Almond Street is a grouping of wood-frame, single-family houses that were erected c.1946-1950. These resources are typically rectangular in plan and have either side-gabled or hipped roofs. All but two of the houses in this neighborhood are one-story in height. Original exterior wall materials include wood, brick, and stucco. All of the houses are utilitarian in appearance, displaying no distinctive stylistic elements. There are many alterations within the neighborhood, the most common include the recladding of original exterior materials with vinyl siding, asbestos shingles, or plywood paneling and the replacement of original windows.

	Address	100 Almond	
A A A A A A A A A A A A A A A A A A A	Date	1950	Alterations/Modifications
	Current Use	Residence	
	Property Type	Domestic: single-family	Ext. Materials
	Plan	Rectangular: massed	Windows Original windows replaced
		No Style	Doors
and the second	No. of Stories	1	Porch
and the second	Structural System	Wood frame	Roof
Sile	-	Side gable	Alterations
<i>Priority</i> ☐ High	Exterior Materials	Brick	Addition(s)
a la atrik	Address Date Current Use	101 Almond 1950 Residence	Alterations/Modifications
me descriptions	Current Use	Residence	Ext Materials
	Dranauto Turna	Demonsting single family	Ext. materials
		Domestic: single-family	Windows
	Plan	Rectangular: massed	
	Plan Style	Rectangular: massed No Style	Windows
	Plan Style No. of Stories	Rectangular: massed No Style 1	Windows Doors
	Plan Style No. of Stories Structural System	Rectangular: massed No Style 1 Load-bearing masonry	Windows Doors Porch
	Plan Style No. of Stories Structural System Roof	Rectangular: massed No Style 1 Load-bearing masonry Hipped	Windows Doors Porch Roof
Priority High Medium ✓ Low	Plan Style No. of Stories Structural System	Rectangular: massed No Style 1 Load-bearing masonry	Windows Doors Porch Roof Alterations
Priority High Medium ✓ Low	Plan Style No. of Stories Structural System Roof	Rectangular: massed No Style 1 Load-bearing masonry Hipped Stucco 106 Almond	Windows Doors Porch Roof Alterations
Priority High Medium ✓ Low 	Plan Style No. of Stories Structural System Roof Exterior Materials	Rectangular: massed No Style 1 Load-bearing masonry Hipped Stucco	Windows Doors Porch Roof Alterations

	Date 1946 nt Use Residence / Type Domestic: single-family Plan Rectangular: massed Style No Style		Alterations/Modifications Exterior walls re-clad w/vinyl
	Type Domestic: single-family Plan Rectangular: massed	Windows	,
Property	Plan Rectangular: massed	Windows	,
	Plan Rectangular: massed		
		Doors	
	SIVIE IND SIVIE		
No. of S		Porch	
	ystem Wood frame		
Siruciurars	-	Alterations	
	Roof Cross/hipped	Addition(s)	
Priority 🗌 High 🗌 Medium 🖌 Low 🛛 Exterior Mat	erials Vinyl	///////////////////////////////////////	

and the second second	Address	209 Almond		
and the second	Date	1946		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	No Style	Doors	
	No. of Stories	1		
and the second	Structural System	Wood frame	Alterations	
and the second s	Roof	Side gable	Addition(s)	
Priority High Medium V Low	Exterior Materials	Wood	Addition(s)	

Barger Drive Neighborhood

Barger Drive, located in central Waxahachie is a short, U-shaped street off Brown Avenue. According to records held at the Ellis County Courthouse, the neighborhood was platted in 1946. The resources in this neighborhood are wood-frame, one-story, single-or multiple-family houses that date from 1946-1955. Roofs are hipped or side-gabled. Original exterior materials include brick veneer and wood siding. All of the houses are utilitarian in appearance, displaying no distinctive stylistic elements. Almost all of the neighborhood's resources have had alterations to their original exterior wall material and/or original windows.

	Address	99 Barger		
	Date	1955		Iterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: multiple-family	Ext. materials Windows	
	Plan	Rectangular: massed		
	Style	Ranch	Doors	
CONTRACTOR OF THE OWNER	No. of Stories	1	Porch Roof	
	Structural System	Wood frame		
	Roof	Hipped	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Brick	Addition(s)	
		-	L	
N 15 58 1				
and a section	Address	107 Barger		
	Date	1950	A	Iterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Irregular	Doors	
	Style	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
<i>Priority</i> ☐ High	Exterior Materials	Wood		
	Adduses	100 D		
	Address Date	122 Barger 1946		
			/	Iterations/Modifications
	Current Use	Residence	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Property Type	Domestic: single-family	Windows	
	Plan	Irregular	Doors	
	Style	No Style	Porch	
and the second s	No. of Stories	1	Roof	
A CONTRACT OF A	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Vinyl		

Bellevue Addition

Priority

The 100 block of Monticello Drive, Pensacola Avenue, Charlotte Avenue, and Wilmington Avenue, in addition to the 100-200 blocks of Richmond Drive form one distinct neighborhood in the central portion of Waxahachie. Also associated with this neighborhood is a small, well-landscaped pocket park, situated along Richmond Drive. These streets are composed primarily of a mix of single- and multiple-family, late 1940s utilitarian homes and 1950s Ranches with some later, post-1960 development on Wilmington Street. The resources in this neighborhood are wood-frame and are one-story in height. Roofs are hipped, gable-on-hip, cross-gabled, and side- gabled. Alterations to exterior materials and original windows appear throughout the neighborhood.

Priority High Medium Low	Plan Style No. of Stories Structural System	Domestic: single-family Irregular No Style 1 Wood frame Cross/hipped	Alterations/Modifications Ext. Materials Windows Doors Porch Roof Alterations Addition(s)	
	Address Date Current Use Property Type	101 Charlotte 1950 Residence Domestic: single-family	Alterations/Modifications Ext. Materials Windows	

	Date	1330	Alterations	Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
A PROVIDENCE OF	Plan	Irregular	Windows	
	Style	Ranch	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Gable-on-Hip	Alterations	
High 🗌 Medium ✔ Low	Exterior Materials	Brick; Wood	Addition(s)	
			L	

	Address	103 Charlotte		
	Date	1950		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	Ranch	Doors	
	No. of Stories	1		
Contraction of the second second	Structural System	Wood frame	Alterations	
	Roof	Gable-on-Hip	Addition(s)	
Priority High Medium 🖌 Low	Exterior Materials	Brick; Wood	Addition(s)	



Priority High V Medium Low



Priority High V Medium Low



Priority High V Medium Low

Address	113 Monticello	
Date	1955	
Current Use	Residence	
Property Type	Domestic: single-family	
Plan	Irregular	
Style	No Style	
No. of Stories	1	
Structural System	Wood frame	
Roof	Cross/hipped	
Exterior Materials	Brick; Wood	

Alterations/Modifications			
Ext. Materials			
Windows	Original windows replaced		
Doors			
Porch			
Roof			
Alterations			
Addition(s)			

Address	114 Monticello	
Date	1955	
Current Use	Residence	
Property Type	Domestic: single-family	
Plan	Rectangular: massed	
Style	Ranch	
No. of Stories	1	
Structural System	Wood frame	
Roof	Cross/hipped	
Exterior Materials	Brick	

	Alterations/Modifications
Ext. Materials	
Windows	Original windows replaced
Doors	
Porch	
Roof	
Alterations	
Addition(s)	

Address	101 Pensacola Avenue		
Date	1955	Alterations/Modifications	
Current Use	Residence	Ext. Materials	
Property Type	Domestic: single-family	Windows	
Plan	Irregular	Doors	
Style	Ranch	Porch	
No. of Stories	1	Roof	
Structural System	Wood frame	Alterations	
Roof	Cross gable/ hipped	Addition(s)	
Exterior Materials	Brick	Audition(s)	



Address	102 Pensacola Avenue	
Date	1950	Alterations/Modifications
Current Use	Residence	Ext. Materials Exterior walls partially re-clad
Property Type	Domestic: single-family	Windows
Plan	Irregular	Doors
Style	No Style	Porch
No. of Stories	1	Roof
Structural System	Wood frame	Alterations
Roof	Cross/hipped	Addition(s)
Exterior Materials	Asbestos; Brick: Wood	Addiuon(s)

Address 104 Pensacola Avenue



Priority High Medium V Low



Priority High V Medium Low



Priority ☐ High ✔ Medium ☐ Low

Date	1955
Current Use	Residence
Property Type	Domestic: single-family
Plan	Rectangular: massed
Style	No Style
No. of Stories	1
Structural System	Load-bearing masonry
Roof	Side gable
Exterior Materials	Vinyl

Alterations/Modifications			
Ext. Materials	Exterior walls re-clad w/vinyl		
Windows			
Doors			
Porch			
Roof			
Alterations			
Addition(s)	Enclosed carport added		
-			

. .

Alterations/Modifications			
Ext. Materials	Vinyl siding added to gable ends		
Windows			
Doors			
Porch			
Roof			
Alterations			
Addition(s)			

Address	110 Richmond Drive	
Date	1946	Alterations/Modifications
Current Use	Residence	Ext. Materials
Property Type	Domestic: single-family	Windows
Plan	Gable-Front-and Wing	Doors
Style	No Style	Porch
No. of Stories	1	Roof
Structural System	Wood frame	Alterations
Roof	Cross gable	Addition(s)
Exterior Materials	Wood	Aution(9)

A CONTRACTOR	Address	101 Richmond Lane		
	Date	1955		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
the second second second	Property Type	Domestic: multiple-family	Windows	
	Plan	Irregular	Doors	
	Style	Ranch	Doors Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped; Gabled	Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Brick; Plywood panel	Addition(s)	



✓ Medium □ Low Priority 🗌 High



Priority 🗌 High ✓ Medium 🗌 Low



1 Barristan	14		
oritv	Hiah	Medium	Low

Address	201 Richmond Lane	
Date	1946	
Current Use	Residence	
Property Type	Domestic: single-family	
Plan	Irregular	
Style	Ranch	
No. of Stories	1	
Structural System	Wood frame	
Roof	Cross/hipped	
Exterior Materials	Wood	

Alterations/Modifications			
Ext. Materials			
Windows			
Doors			
Porch			
Roof			
Alterations			
Addition(s)			

Address	101 Wilmington Avenue	
Date	1950	
Current Use	Residence	
Property Type	Domestic: single-family	
Plan	Rectangular: massed	
Style	Ranch	
No. of Stories	1	
Structural System	Wood frame	
Roof	Cross/hipped	
Exterior Materials	Wood	

Alterations/Modifications			
Ext. Materials			
Windows			
Doors			
Porch			
Roof			
Alterations			
Addition(s)			

Date 1955 Alterations/Modifications Current Use Residence Ext. Materials Property Type Domestic: multiple-family Windows Plan Rectangular: massed Doors Style Ranch Doors	Address	106 Wilmington Avenue	
Property Type Domestic: multiple-family Ext. Materials Plan Rectangular: massed Windows Style Ranch Doors	Date	955 Alterations/Modifications	
Property Type Domestic: multiple-family Windows Plan Rectangular: massed Doors Style Ranch Doors	Current Use	Residence	Ext Matariala
Plan Rectangular: massed Style Ranch	Property Type	Domestic: multiple-family	
Style Ranch	Plan	Rectangular: massed	
Porch	Style	Ranch	Porch
No. of Stories 1 Roof	No. of Stories	1	
Structural System Wood frame Alterations	Structural System	Wood frame	
Roof Cross/hipped Addition(s)	Roof	Cross/hipped	
Exterior Materials Wood	Exterior Materials	Wood	

Boze Street Neighborhood

Situated in central Waxahachie directly south of Barger Street is Boze Street, which contains a collection of single-family, wood-frame dwellings. Most of the neighborhood's resources were erected early in the post-World War II era, c. 1946-1950. The street is narrow and lots are small allowing for small front and rear yards. Roofs are side-gabled or side-gabled with a projecting front-gabled wing. Some roofs also have exposed rafter ends. The majority of the neighborhood's homes have been altered with the addition of vinyl siding, asbestos shingles, or masonite to exterior walls and the replacement of original windows.

	Address	104 Boze		
	Date	1946	Alterations/Modifications	
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials Exterior walls re-clad w/ asbestos shingles	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
Priority 🗌 High 🗌 Medium ✔ Low	Exterior Materials	Asbestos	Addition(s)	
	Address	113 Boze		
	Date	1946	Alterations/Modifications	
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
		Rectangular: massed	Windows Original windows replaced	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Side gable	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address	207 Boze		
	Date	1946		
	Current Use		Alterations/Modifications	
A CARLENDER OF THE CARL		Domestic: single-family	Ext. Materials	
	Plan	Irregular	Windows Orig. windows replaces w/ aluminum sash u	I
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority High Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
		wood		-

	Address	210 Boze	
	Date	1940	Alterations/Modifications
	Current Use	Residence	Ext. Materials
	Property Type	Domestic: single-family	Windows
	Plan	Rectangular: massed	Doors
	Style	No Style	Porch
	No. of Stories	1	Roof
and a second second of the second second	Structural System	Wood frame	Alterations
and the second	Roof	Complex	
Priority High Medium 🖌 Low	Exterior Materials	Vinyl; Stucco	Addition(s)
		-	

Bryson Street Neighborhood

The 400-900 blocks of Bryson Street, centrally located within Waxahachie, contain a grouping of c. 1940-1955, single-family homes with generous, well-landscaped front and rear yards. Also located within this neighborhood are two houses that were erected before 1935 and one c. 1960 house. These resources are primarily one-story and have side-gabled, hipped, or front-gabled roofs. Exterior materials include asbestos shingles, wood siding, and brick veneer. A small number have had alterations to original exterior materials, but, for the most part, the neighborhood retains its historic integrity to a good degree.

T. States	Address	404 Bryson		
	Date	1946	Alterations/Modifications	
	Current Use	Residence	Ext. Materials Exterior walls re-clad w/asbestos	
	Property Type	Domestic: multiple-family	Windows Front facade window replaced	
	Plan	Irregular	Doors	
	Style	No Style		
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	-	Hipped	Alterations	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Asbestos	Addition(s)	
	Address Date	600 Bryson 1945	A 14 a web a no 100 a difici a si a no	
	Address Date Current Use	1945	Alterations/Modifications	
	Date Current Use	1945 Residence	Ext. Materials	
	Date Current Use Property Type	1945 Residence Domestic: single-family		
	Date Current Use Property Type Plan	1945 Residence Domestic: single-family Rectangular: massed	Ext. Materials	
	Date Current Use Property Type Plan Style	1945 Residence Domestic: single-family Rectangular: massed No Style	Ext. Materials Windows	
	Date Current Use Property Type Plan Style No. of Stories	1945 Residence Domestic: single-family Rectangular: massed No Style 1	Ext. Materials Windows Doors	
	Date Current Use Property Type Plan Style No. of Stories Structural System	1945 Residence Domestic: single-family Rectangular: massed No Style 1 Wood frame	Ext. Materials Uindows Doors Porch	
Priority ☐ High ☐ Medium ✔ Low	Date Current Use Property Type Plan Style No. of Stories Structural System	1945 Residence Domestic: single-family Rectangular: massed No Style 1	Ext. Materials Windows Doors Porch Roof	

	Date	606 Bryson 1946		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials Windows	Exterior walls re-clad w/ asbestos shingle
	Plan	Rectangular: massed	Doors	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable; Hipped	Addition(s)	
<i>iority</i> 🗌 High 🔄 Medium ✔ Low	Exterior Materials	Asbestos	Addition(s)	


10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	Address	700 Bryson		
and the second second second	Date	1946		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	-	
and the second second second second second	Roof	Side gable	Alterations	
Priority 🗌 High 🔄 Medium ✔ Low	Exterior Materials	Wood	Addition(s)	
	Address Date	901 Bryson 1955		Alterations/Modifications
	Current Use		Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
		No Style	Porch	
	No. of Stories			
	Structural System		Alterations	
	Roof	Hipped		2nd story is likely an addition
<i>Priority</i> ☐ High	Exterior Materials	Brick; Masonite	Aution(3)	

Ferris Avenue Neighborhood

The 1400-1500 blocks of North Ferris Avenue contain primarily single-family irregular- or rectangular-plan dwellings. The majority of the neighborhood's houses were erected in the late 1940s while a smaller number were erected in the early 1950s. Resources are one-story in height and all utilize wood-frame construction. Side-gabled roofs are prevalent although the neighborhood has some hipped-roof and front-gabled dwellings. Front and rear yards are generous and well landscaped. A majority of the neighborhood's resources have exterior material alterations. In addition, some of the neighborhood's dwellings have had their original windows replaced with aluminum sash, single-hung units. Within the 1400 block there is one c. 1980 commercial building, one c. 1960 church, and one c. 1985 dwelling.

	Address	1414 N. Ferris Avenue		
	Date	1946		Alterations/Modifications
States	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Gable-Front-and Wing	Doors	
	Style	Ranch		
	No. of Stories	1	Porch Roof	
A CONTRACTOR OF THE OWNER OWNE	Structural System	Wood frame	Alterations	
	Roof	Cross gable		
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Vinyl	Addition(s)	

	Address	1415 N. Ferris Avenue		
	Date	1946	Alterations/Modifications	
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
and a second P	Plan	Bungalow	Doors	
CONTRACTOR OF	Style	No Style	Porch	
	No. of Stories	1	Roof	
A REAL PROPERTY OF	Structural System	Wood frame	Alterations	
1.178 (2)	Roof	Hipped		
Medium Low	Exterior Materials	Wood	Addition(s)	



Priority High

Address	1500 N. Ferris Avenue	
Date	1946	Alterations/Modifications
Current Use	Residence	Ext. Materials
Property Type	Domestic: single-family	Windows
Plan	Rectangular: massed	Doors
Style	No Style	Porch
No. of Stories	1	Roof
Structural System	Wood frame	Alterations
Roof	Side gable	Addition(s)
Exterior Materials	Asbestos	Auuuuuiisi

Floyd Street Neighborhood

The 500-600 blocks of Floyd Street are dominated by a small grouping of c. 1955, almost identical Ranch houses. These resources are one-story in height and are built of wood-frame construction. Each house was originally built with an attached garage although two of the houses have had their garages infilled. Additional alterations include the addition of vinyl siding or asbestos shingles to the exterior and the replacement of original windows with aluminum-sash, single-hung units. The rectangular-plan dwellings have shallow side-gabled roofs with deep overhanging eaves.

	Address	200 Floyd		
	Date	1944		Alterations/Modifications
	Current Use	Residence; Shed	Ext Matariala	Exterior walls re-clad
	Property Type	Domestic: single-family	Ext. Wateriars Windows	
	Plan	Irregular	Doors	
	Style	Tudor Revival	Porch	
	No. of Stories	1	Roof	
the second se	Structural System	Wood frame	Alterations	
	Roof	Cross gable		
<i>Priority</i> ☐ High 🖌 Medium 🗌 Low	Exterior Materials	Asbestos Shingles; Plywood Panel	Addition(s)	
	Address Date Current Use	204 Floyd 1935 Residence	Ext. Materials	Alterations/Modifications
and the second in the	Property Type	Domestic: single-family		
	Plan	Bungalow	Windows	
	Style	No Style	Doors Porch	
	No. of Stories	1	Roof	
the second s	Structural System	Wood frame	Alterations	
and the second sec	Roof	Side gable	Alterations Addition(s)	
<i>Priority</i> ☐ High ☐ Medium ✔ Low	Exterior Materials	Wood	Addition(S)	
	Address Date Current Use	208 Floyd 1942 Residence		Alterations/Modifications
	Property Type	Domestic: single-family	Ext. Materials	Exterior walls re-clad w/vinyl siding
	Plan	Irregular	Windows	
A CONTRACTOR OF A CONTRACTOR	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	·
208	Roof	Side gable	Alterations	
Priority High Medium 🗸 Low	Exterior Materials	Vinyl	Addition(s)	Side wings added
, , ,			L	



Priority High Medium 🖌 Low



Priority High Medium V Low

Priority High Medium V Low

Address	408 Floyd
Date	1935
Current Use	Residence
Property Type	Domestic: single-family
Plan	Bungalow
Style	Craftsman
No. of Stories	1
Structural System	Wood frame
Roof	Front gable
Exterior Materials	Asbestos Shingles

Alterations/Modifications		
Ext. Materials	Exterior wall re-clad w/asbestos shingles	
Windows	most original windows replaced	
Doors		
Porch	Porch posts replaced	
Roof		
Alterations		
Addition(s)	Rear carport addition	
-		

Address	506 Floyd
Date	1955
Current Use	Residence
Property Type	Domestic: single-family
Plan	Irregular
Style	No Style
No. of Stories	1
Structural System	Wood frame
Roof	Cross/hipped
Exterior Materials	Wood: Brick

Alterations/Modifications				
Ext. Materials				
Windows				
Doors				
Porch				
Roof				
Alterations				
Addition(s)				

Address	602 Floyd	
Date	1955	Alterations/Modifications
Current Use	Residence	Ext. Materials Exterior walls re-clad
Property Type	Domestic: single-family	Windows
Plan	Rectangular: massed	Doors
Style	Ranch	Porch
No. of Stories	1	Roof
Structural System	Wood frame	Alterations
Roof	Side gable	Addition(s)
Exterior Materials	Asbestos	

Kirksey Street Neighborhood

The 100-300 blocks of Kirksey Street are composed of primarily 1946-1955, single-family dwellings. The resources, which are one-story in height, were built of wood-frame construction. Roof types include hipped, side-gabled and front-gabled. The majority of the neighborhood's resources have had their exterior wall reclad with vinyl siding, asbestos shingles, or plywood panels. In addition a number of the neighborhood's homes have had their original windows replaced with aluminum-frame, single hung units. The neighborhood has a number of non-historic intrusions, the majority of which are confined to the 300 block.

	Address	201 Kirksey		
	Date	1930		
	Current Use	Residence		Alterations/Modifications
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos shingles
	Plan	Bungalow		
	Style	No Style	Doors	
	No. of Stories	1		Original porch posts and flooring replaced
	Structural System	Wood frame	Roof	
	•	Front gable	Alterations	
Priority ☐ High	Exterior Materials	Asbestos	Addition(s)	
		1000000		
and the second second second	Address	209 Kirksey		
	Date	1946		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family		
		Irregular	Doors	
	-	No Style	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Asbestos; Plywood panel		
	Address Date	215 Kirksey 1946	[
and the second				Alterations/Modifications
	Current Use	Residence	Ext. Materials	
		Domestic: single-family	Windows	Original windows replaced
	Plan	Irregular	Doors	
	Style No. of Stories	No Style	Porch	
		-	Roof	
and the second	-	Wood frame	Alterations	
	ROOT	Cross gable	Addition	

Exterior Materials Wood; Asbestos

Appendix B: Page 15	

Addition(s)

Lewis Street Neighborhood

Single-story, wood-frame dwellings dominate the 100-200 blocks of Lewis Street. The resources in this neighborhood, which date from between 1946-1950, are dedicated to both single-family and multiple-family residential uses. They are typically rectangular in plan and have side-gable roofs. The majority of the neighborhood's houses have either attached or detached single-car garages. Original exterior materials include wood siding and brick veneer. Typical alterations within the neighborhood include the replacement of original windows and exterior materials.

	Address	102 Lewis		
	Date	1946		Alterations/Modifications
Cu	rrent Use	Residence		
	erty Type	Domestic: multiple-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	No Style	Doors	
No	of Stories	1	Porch	
	al System	Wood frame	Roof	
	Roof	Side gable	Alterations	
Priority High Medium V Low Exterior	Materials	Wood	Addition(s)	
	materialo	1000		
	Address	103 Lewis		
and the second second	Date	1955		Alterations/Modifications
	ırrent Use	Residence	Ext. Materials	
Prop	erty Type	Domestic: multiple-family		Original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
No.	of Stories	1	Roof	
Structure	al System	Wood frame	Alterations	
	Roof	Cross/hipped	Addition(s)	
Priority ☐ High ☐ Medium ✔ Low Exterior	Materials	Brick	Addition(s)	
	Address	104 Lewis		
A CONTRACT OF THE OWNER OWNER OF THE OWNER	Date	1950		Alterations/Modifications
	ırrent Use	Residence	Ext. Materials	Original exterior materials replaced
Prop	erty Type	Domestic: single-family	Windows	
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	of Stories	1	Roof	
Structure	al System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority ☐ High ☐ Medium ✔ Low Exterior	Materials	Vinyl	Auguro (3)	



Priority ☐ High ☐ Medium ✔ Low

Address	108 Lewis	
Date	1946	
Current Use	Residence	- Ex
Property Type	Domestic: single-family	
Plan	Rectangular: massed	_
Style	No Style	_
No. of Stories	1	_
Structural System	Wood frame	_
Roof	Side gable	_
Exterior Materials	Vinyl	_

Alterations/Modifications					
Ext. Materials					
Windows	Original windows replaced				
Doors					
Porch					
Roof					
Alterations					
Addition(s)					
-					



Priority ☐ High ☐ Medium ✔ Low

Address	207 Lewis	
Date	1946	Alterations/Modifications
Current Use	Residence	Ext. Materials
Property Type	Domestic: single-family	Windows
Plan	Rectangular: massed	· · · · · · · · · · · · · · · · · · ·
Style	No Style	Doors
No. of Stories	1	Porch
Structural System	Wood frame	Roof
Roof	Side gable	Alterations
Exterior Materials	Wood	Addition(s)

Olive Street Neighborhood

Priority ☐ High ☐ Medium ✔ Low

The targeted post-World War II grouping includes the 100-300 blocks of Olive Street. This neighborhood contains an assemblage of single- and multiple-family houses that were erected between 1946 and 1955. The 100 block is dominated by c. 1946-1950 homes while the 200 block is composed primarily of c. 1955 Ranch houses. All resources within this neighborhood are small wood-frame houses with small front and back yards. Roofs are side-gabled or cross-hipped. Original exterior materials include wood and brick veneer. The bulk of this neighborhood's resources have had their exterior walls reclad with vinyl siding.

	Address	105 Olive		
	Date	1950		Alterations/Modifications
	Current Use	Residence		Alterations, mounications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof		Alterations	
Priority ☐ High ☐ Medium ✔ Low	Exterior Materials	Masonite	Addition(s)	
			L	
	Address Date	203 Olive 1950		Alterations/Modifications
and the second sec	Current Use		Ext. Materials	
		Domestic: single-family		Original windows replaced
	Plan	Irregular	Doors	
The state of the s	Style	No Style		
the second second second second second second		1	Roof	
	Structural System	Wood frame	Alterations	
		Cross gable	Addition(s)	
Priority 🗌 High 📄 Medium 🖌 Low	Exterior Materials	Brick; Wood		
	Address Date	206 Olive		
		Commercial		Alterations/Modifications
		Domestic: single-family	Ext. Materials	
	Plan	Rectangular: massed	Windows	
	Style	Ranch	Doors	
	No. of Stories	1	Porch	
		Wood frame	Roof	
Care - State -	•	Side gable	Alterations	
Data atta	Rutarian Matariala		Addition(s)	

Exterior Materials Brick

Overhill Drive Neighborhood

Overhill Drive is a wide, two-block street in the northern portion of Waxahachie. The neighborhood contains a collection of primarily one-story, single-family Ranch dwellings with one early c. 1925 Classical Revival dwelling, one c. 1955 Contemporary style home, and one c. 1946 Neoclassical Revival home. The 100 block is dominated by c. 1956 Ranch homes while within the 200 block are c. 1950 Ranch homes. Exteriors are typically brick veneer and roofs are hipped and gabled. Each house has a generous front and rear lawn. The neighborhood has undergone few alterations and contains only one post-1960 intrusion.

A DECEMBER OF	Address	111 Overhill Drive		
	Date	1955		Alterations/Modifications
the same of the same of the same	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed	Doors	•
	Style	Ranch	Porch	
Automation and A	No. of Stories	1	Porch	
	Structural System	Wood frame	Alterations	
	Roof	Cross/hipped	Addition(s)	
Priority High V Medium Low	Exterior Materials	Brick	Addition(s)	
	Address Date	203 Overhill Drive		Alterations/Modifications
and the first state of the second state of the	Current Use	Residence		
A CARLES AND AND A CARLES		Domestic: single-family	Ext. Materials	
	Plan	Irregular		
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Complex	Alterations	
Priority High V Medium Low	Exterior Materials	Brick	Addition(s)	
	Address Date	205 Overhill Drive		Alterations/Modifications
	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials	
A CONTRACTOR OF	Plan	Rectangular: massed	Windows	
	Style	Classical Revival	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	-
and the second	Roof		Alterations	
Priority 🗌 High 🖌 Medium 🗌 Low	Exterior Materials	Brick	Addition(s)	
· _ ·				

	Address	208 Overhill Drive		
	Date	1955		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
P	Property Type	Domestic: single-family		
	Plan	Irregular		
	Style	Ranch	Doors	
	No. of Stories	1	Porch	
Struc	ctural System	Wood frame	Roof	
		Cross/hipped	Alterations	
	ior Materials	Brick	Addition(s)	
Priority High V Medium Low Exter				
Priority High Mealum Low Extern	Address	218 Overhill Drive		
Priority High V Mealum Low Extern	Date	1955		Alterations/Modifications
	Date Current Use	1955 Residence	Ext. Materials	
	Date Current Use Property Type	1955 Residence Domestic: single-family		
	Date Current Use Property Type	1955 Residence		
	Date Current Use Property Type	1955 Residence Domestic: single-family	Windows Doors	
Ρ	Date Current Use Property Type Plan	1955 Residence Domestic: single-family Irregular	Windows Doors Porch	
P C	Date Current Use Property Type Plan Style No. of Stories ctural System	1955 Residence Domestic: single-family Irregular Contemporary 1 Wood frame	Windows Uoors Porch Roof	
P	Date Current Use Property Type Plan Style No. of Stories ctural System	1955 Residence Domestic: single-family Irregular Contemporary 1	Windows Doors Porch	

Perry Street Neighborhood

The Perry Street neighborhood is an historically African-American neighborhood in the southeast portion of Waxahachie, off Getzendaner Street. The majority of Perry Street's homes date from 1945-1955, although there are a number of post-1960 and pre-1935 buildings within the neighborhood. The street is narrow and the lots are small, allowing for only small front-lawns without sidewalks. The houses in the neighborhood are wood-frame single-family dwellings and roofs are side-gabled, front-gabled or hipped. Exterior wall cladding includes wood siding, asbestos shingles, vinyl siding, and plywood paneling. Common alterations include the replacement of original exteriors and windows. Also, a number of the neighborhood's homes have had wings added to front and/or rear facades.

	Address	301 Perry Street		
THE A BOOM	Date	1946		Alterations/Modifications
	Current Use	Residence	Ext Matarials	Exterior walls re-clad w/aluminum siding
	Property Type	Domestic: single-family		Original windows replaced
	Plan	Rectangular: massed	Doors	
	Style	No Style	Porch	
	No. of Stories	1		
	Structural System	Wood frame	Alterations	
the second se	Roof	Side gable; Shed	Addition(s)	
Priority High Medium V Low	Exterior Materials	Aluminum	Addition(3)	

A REAL MARKET	Address	303 Perry Street		
	Date	1946		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family		
	Plan	Gable-Front-and Wing		Original windows replaced
	Style	No Style	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
Priority 🔄 High 🖌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	-			

	Address	304 Perry Street		
	Date	1941	Alterations/Modifications	
	Current Use	Vacant	Ext. Materials Exterior walls re-clad w/asbestos st Windows Doors Porch	
	Property Type	Domestic: single-family		Exterior walls re-clad w/asbestos sningles
	Plan	Bungalow		
	Style	No Style		
	No. of Stories	1		
	Structural System	Wood frame	Roof	
	Roof	Front gable	Alterations	
<i>Priority</i> ☐ High	Exterior Materials	Asbestos	Addition(s)	Has a rear addition



Priority High Medium V Low

306 Perry Street	
1940	
Residence	
Domestic: single-family	
Bungalow	-
No Style	-
1	-
Wood frame	-
Front gable	-
Wood	-
	1940 Residence Domestic: single-family Bungalow No Style 1 Wood frame Front gable

.....

Alterations/Modifications			
Ext. Materials			
Windows			
Doors			
Porch			
Roof			
Alterations			
Addition(s)			



Priority High V Medium Low

Address	308 ? Perry Street	
Date	1956	
Current Use	Religious	
Property Type	Religious	
Plan	Rectangular: massed	
Style	No Style	
No. of Stories	1	
Structural System	Wood frame	
Roof	Cross gable	
Exterior Materials	Wood	

Alterations/Modifications			
Ext. Materials			
Windows	Orig. windows replaced w/ metal sash units		
Doors			
Porch			
Roof			
Alterations			
Addition(s)			
-			

Village Drive Neighborhood

The Village Drive neighborhood is composed of a collection of nearly identical single-family concrete-block dwellings that were erected c. 1946. These rectangular-plan, front-gabled resources are situated within a cul-de-sac in the northern portion of Waxahachie. Exterior wall materials present include concrete block, asbestos shingles, and plywood panels. Each dwelling has a small fenced front and rear yard. The majority of these dwellings have had their exterior walls reclad and their original windows replaced. The neighborhood has only one modern intrusion located at 210 Village Drive. Due to the homogeneous nature of the neighborhood, it is likely the homes are former rental units.

	Address	202 Village Drive Circle		
	Date	1946		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	- Ext. materials - Windows	
	Plan	Bungalow		
	Style	No Style	- Doors	
	No. of Stories	1		Porch roof changed
	Structural System		- Roof	
	-	Front gable	- Alterations	
Priority High Medium 🖌 Low	Exterior Materials	Brick; Asbestos; Concrete block	- Addition(s)	
	Address Date	211 Village Drive Circle	-	
	Date	1946	-	Alterations/Modifications
Con States	Date Current Use	1946 Residence	- Ext. Materials	Alterations/Modifications
	Date Current Use Property Type	1946 Residence Domestic: single-family		Alterations/Modifications Original windows replaced
	Date Current Use Property Type Plan	1946 Residence Domestic: single-family Rectangular: massed		
	Date Current Use Property Type Plan Style	1946 Residence Domestic: single-family Rectangular: massed No Style	Windows	
	Date Current Use Property Type Plan Style No. of Stories	1946 Residence Domestic: single-family Rectangular: massed No Style 1	- Windows - Doors	
	Date Current Use Property Type Plan Style No. of Stories Structural System	1946 Residence Domestic: single-family Rectangular: massed No Style 1 Load-bearing masonry	- Windows - Doors - Porch	
Priority High Medium Low	Date Current Use Property Type Plan Style No. of Stories Structural System	1946 Residence Domestic: single-family Rectangular: massed No Style 1	- Windows - Doors - Porch - Roof	Original windows replaced

Appendix C

Supplemental Inventory of HIGH Priority Properties

Appendix C

Waxahachie Survey Update of 2003 - Supplemental Inventory of HIGH Priority Properties (Built Prior to 1946)

	Address	209 S. Hawkins		
	Date	1890		Alterations/Modifications
A CONTRACT OF A	Current Use	Residence		
	Property Type	Domestic: single-family	Ext. Materials Windows	
	Plan	Rectangular: linear (horizon	Doors	
	Style	Folk Victorian	Porch	
	No. of Stories	1	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Side gable	Addition(s)	
Priority 🖌 High 🗌 Medium 🗌 Low	Exterior Materials	Wood		
	Address	? Hawkins Street	-	
	Date Current Use	1900		Alterations/Modifications
		Landscape (Hawkins Spring)	Ext. Materials	
Market and Andrews	Property Type Plan	Landscape: Spring N/A	Windows	
	Style	N/A N/A	Doors	
	No. of Stories	0	Porch	
	Structural System	0 N/A	Roof	
	Roof	N/A	Alterations	
Priority ✓ High Medium Low	Exterior Materials	Concrete	Addition(s)	
	Address	3209 Highway 77		
	Date	1905		Alterations/Modifications
	Current Use	Residence	F (M () ()	Alterations/modifications
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Modified L-Plan	Windows	
	Style	Queen Anne; Folk Victorian	Doors Porch	
	No. of Stories	2	Roof	
	Structural System	Wood frame	Alterations	
	Roof	Cross gable	Addition(s)	
<i>Priority</i> ✔ High	Exterior Materials	Wood	, idultion(o)	
	Address	0 ? Howard Road		
A STATE OF THE S	Date	1900		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
a A A A A A A A A A A A A A A A A A A A	Property Type	Domestic: single-family	Windows	
	Plan Style	Rectangular: linear Folk Victorian	Doors	
	Siyle		1	
	•		Porch	
	No. of Stories	1	Roof	
	No. of Stories Structural System	1 Wood frame	Roof Alterations	
Priority V High Medium Low	No. of Stories Structural System Roof	1 Wood frame Side gable	Roof	
Priority ✓ High Medium Low	No. of Stories Structural System	1 Wood frame	Roof Alterations	
Priority ♥ High Medium Low	No. of Stories Structural System Roof	1 Wood frame Side gable	Roof Alterations	
Priority ♥ High Medium Low	No. of Stories Structural System Roof Exterior Materials	1 Wood frame Side gable Wood	Roof Alterations Addition(s)	Alterations/Modifications
Priority ✓ High Medium Low	No. of Stories Structural System Roof Exterior Materials Address	1 Wood frame Side gable Wood ? E. Jefferson	Roof Alterations Addition(s)	Alterations/Modifications
Priority ✓ High Medium Low	No. of Stories Structural System Roof Exterior Materials Address Date	1 Wood frame Side gable Wood ? E. Jefferson 1920	Roof Alterations Addition(s) Ext. Materials	Alterations/Modifications
Priority ✓ High Medium	No. of Stories Structural System Roof Exterior Materials Address Date Current Use	1 Wood frame Side gable Wood ? E. Jefferson 1920 Funerary (Freedman's Cemetery)	Roof Alterations Addition(s) Ext. Materials Windows	Alterations/Modifications
Priority ♥ High Medium Low	No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type	1 Wood frame Side gable Wood ? E. Jefferson 1920 Funerary (Freedman's Cemetery) Funerary	Roof Alterations Addition(s) Ext. Materials Windows Doors	Alterations/Modifications
Priority ♥ High Medium Low	No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories	1 Wood frame Side gable Wood ? E. Jefferson 1920 Funerary (Freedman's Cemetery) Funerary Not applicable	Roof Alterations Addition(s) Ext. Materials Windows Doors Porch	Alterations/Modifications
Priority High Medium Low	No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style	1 Wood frame Side gable Wood ? E. Jefferson 1920 Funerary (Freedman's Cemetery) Funerary Not applicable 0 Not applicable	Roof Alterations Addition(s) Ext. Materials Windows Doors Porch Roof	Alterations/Modifications
	No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories	1 Wood frame Side gable Wood ? E. Jefferson 1920 Funerary (Freedman's Cemetery) Funerary Not applicable Not applicable 0 Not applicable Not applicable Not applicable	Ext. Materials Windows Doors Porch Alterations	Alterations/Modifications
Priority ♥ High Medium Low	No. of Stories Structural System Roof Exterior Materials Address Date Current Use Property Type Plan Style No. of Stories Structural System	1 Wood frame Side gable Wood ? E. Jefferson 1920 Funerary (Freedman's Cemetery) Funerary Not applicable 0 Not applicable	Roof Alterations Addition(s) Ext. Materials Windows Doors Porch Roof	Alterations/Modifications

Appendix C: Page 1

Waxahachie Survey Update of 2003 - Supplemental Inventory of HIGH Priority Properties (Built Prior to 1946)

	Address	501 W. Marvin		
	Date	1951		Alterations/Modifications
	Current Use	Religious		
	Property Type	Religious	Ext. Materials	
The second se	Plan	Irregular		
	Style	Gothic Revival	Doors	
	No. of Stories	1	Porch	
	Structural System	Load-bearing masonry	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> ✔ High 🗌 Medium 🗌 Low	Exterior Materials	Brick	Addition(s)	Education building added c. 1957
	Address	606 W. Marvin		
	Date	1944		Alterations/Modifications
	Current Use	Residence	5 (M () ()	
	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Irregular	Windows	
	Style	Colonial Revival; Ranch	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> ✔ High 🗌 Medium 🗌 Low	Exterior Materials	Brick; Wood	Addition(s)	
· - ·				
han the	Address	202 Old Howard Road		
	Date	1915		Alterations/Modifications
	Current Use	Residence		
the standard the same	Property Type	Domestic: single-family	Ext. Materials	
	Plan	Bungalow		
	Style	Mission Revival	Doors	
	No. of Stories	1	Porch	
	Structural System	Wood frame	Roof	
Constant of the second s	Roof	Hipped	— Alterations	
<i>Priority</i> ✔ High 🗌 Medium 🗌 Low	Exterior Materials	Wood	Addition(s)	
	Address	140 E. Sterrett Road		
Second AL CONTRACT	Date	1890		Alterations/Modifications
	Current Use	Vacant	Fort Materials	
A CONTRACT OF THE OWNER	Property Type	Domestic: single-family	Ext. Materials	
A CALLER AND A CALL	Plan	Irregular		
THE REAL PROPERTY AND A DESCRIPTION OF THE REAL PROPERTY.	Style	Queen Anne	Doors	
	No. of Stories	2	Porch	
	Structural System	Wood frame	Roof	
	Roof	Cross gable	Alterations	
<i>Priority</i> ✔ High Medium Low	Exterior Materials	Wood	Addition(s)	
	Address	607 Sycamore		
	Date	1930		Alterations/Modifications
	Current Use	Residence	Ext. Materials	
	Property Type	Domestic: single-family	Windows	
	Plan	Irregular		
	Style	Tudor Revival	— Doors — Porch	
	Style			
	No. of Stories	2		
	-	2 Wood frame	Roof	
	No. of Stories Structural System		Roof Roof	
Priority ✓ High Medium Low	No. of Stories Structural System	Wood frame	Roof	

Appendix D

Maps of Waxahachie Historic Resource Survey Update

